

Submit 1 Copy To Appropriate District Office  
District I - (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II - (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV - (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised August 1, 2011

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO.
30-025-07290
5. Indicate Type of Lease STATE FEE XX
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Rose Eaves
8. Well Number 001
9. OGRID Number
10. Pool name or Wildcat Knowles Devonian

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	
2. Name of Operator State of New Mexico formerly Platinum Exploration, Inc	
3. Address of Operator 1625 N. French Drive Hobbs NM, 88240	
4. Well Location Unit Letter <u>N</u> : <u>660</u> feet from the <u>South</u> line and <u>1980</u> feet from the <u>West</u> line Section <u>35</u> Township <u>16S</u> Range <u>38E</u> NMPM County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A XX  
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

See Attached

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

Type or print name \_\_\_\_\_ E-mail address: \_\_\_\_\_ PHONE: \_\_\_\_\_

For State Use Only

APPROVED BY: Mary Brown TITLE: Dist. Supervisor DATE: 3/16/2015  
Conditions of Approval (if any):

MAR 17 2015

## **Plugging Report**

### **Rose Eaves #1**

3/9/2015        Moved in equipment and rig up. RIH with wireline and sat down at 1540'. Tried to work down. Could not. RIH with workstring with perforated sub/bull plug. Worked passed bad spot at 422'. Sat down at 1763'. Could not work past. Rigged up plugging equipment and shut down.

3/10/2015        Stacked out at 1763'. Took 5 bbls to catch circulation. Pumped 30 bbls. Could not wash down. Tubing still stacking out at 1763'. Circulated hole with MLF and spotted 50 sx Class C cement with CaCl. WOC and tagged @ 1614'. POOH to 472' and spotted 50 sx class c cement. SION

3/11/2015        RIH and tagged cement at 382'. POOH and perforated at 60'. Established circulation. Pumped cement down 10 ¾" casing to perfs at 60' and up 10 ¾" X 16" annulus to surface. Took 60 sx to get good cement to surface. Cut off wellhead. Cement was to surface on both sides. Installed marker and cut off anchors.