

Submit 3 Copies To Appropriate District Office  
District I  
1625 N. French Dr., Hobbs, NM 87240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
June 19, 2008

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

|   |
|---|
| WELL API NO.<br>30-025-36247  |
| 5. Indicate Type of Lease<br>STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> |
| 6. State Oil & Gas Lease No.  |
| 7. Lease Name or Unit Agreement Name:<br>North Hobbs G/SA Unit                                      |
| 8. Well Number<br>527   |
| 9. OGRID Number<br>157984   |
| 10. Pool name or Wildcat<br>Hobbs; Grayburg-San Andres  |

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
Oil Well ☒ Gas Well ☐ Other **HOBBS OCD**

2. Name of Operator  
Occidental Permian Ltd. **MAR 20 2015**

3. Address of Operator  
P.O. Box 4294, Houston, TX 77210-4294 **RECEIVED**

4. Well Location  
Unit Letter N : 627 feet from the South line and 1782 feet from the West line  
Section 30 Township 18-S Range 38-E NMPM County Lea  
11. Elevation (Show whether DR, RKB, RT, GR, etc.)  
3649' GR

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
WELL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

MI x RU pulling unit. ND WH x NU BOP. RU spooler x POOH w/ESP equipment x tubing. Inspect ESP equipment and found pump was covered with asphaltines. RIH w/4-3/4" bit on 139 jts. 2-7/8" workstring x tag at 4380'. Pull up above perms. Kill well w/110 bbls 10# BW. POOH w/ bit x WS. RU spooler x RIH with REDA 400 ESP equipment on 124 jts. 2-7/8" production tubing (SN @ 4008'). ND BOP x NU WH. RD pulling unit x clean location.

Spud Date: RU - 3/3/15 Rig Release Date: RD - 3/11/15

hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mark Stephens TITLE Regulatory Compliance Analyst DATE 3/19/15  
Type or print name Mark Stephens E-mail address: Mark\_Stephens@oxy.com PHONE (713) 366-5158

For State Use Only  
APPROVED BY Mary Brown TITLE Dist. Supervisor DATE 3/23/2015  
Conditions of Approval (if any):

**MAR 26 2015**