Office	State of New Mexico	Form C-103
Office <u>District I</u> – (575) 393-6161  1625 N. French Dr., Hobbs, NM 88240 OBBS  District II – (575) 748-1283	y, Minerals and Natural Resources	Revised July 18, 2013 WELL API NO.
1625 N. French Dr., Hobbs, NM 8824010 District II – (575) 748-1283		30-025-42173
811 S. First St., Artesia, NM 88210	CONSERVATION DIVISION	5. Indicate Type of Lease
District III - (505) 334-6178 APR U 9 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. I funcis Di.	STATE S FEE
District IV = (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		VO-6987
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		7. Lease Name or Unit Agreement Name RAPTOR WEST 3 STATE
PROPOSALS.)   1. Type of Well: Oil Well   ⊠ Gas Well   □ Other		8. Well Number 4H
2. Name of Operator		9. OGRID Number
NADEL AND GUSSMAN PERMIAN, L.L.C.		155615
3. Address of Operator		10. Pool name or Wildcat
601 N. MARIENFELD, SUITE 508, MIDLAND, TX 79701		SCHARB; BONE SPRING
4. Well Location		
	feet from the <u>SOUTH</u> line and	
Section 3 Township 19S Range 34E NMPM LEA County		
11. Elevat	tion (Show whether DR, RKB, RT, GR, etc.	c.)
	3988' GL	
12 Check Appropriate	e Box to Indicate Nature of Notice	Report or Other Data
12. Check Appropriate	e Box to indicate ivalure of ivolice	, report of other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK  PLUG AND ABANDON  REMEDIAL WORK		_
TEMPORARILY ABANDON CHANGE	_	RILLING OPNS. P AND A
PULL OR ALTER CASING MULTIPLE	E COMPL CASING/CEME	NI JOB []
DOWNHOLE COMMINGLE ☐ CLOSED-LOOP SYSTEM ☐		
CLOSED-LOOP SYSTEM  OTHER:	OTHER: COMP	LETION
		and give pertinent dates, including estimated date
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of		
proposed completion or recompletion.		
1/8/2015 – TEST CASING TO 4500 PSI FOR 30 MINS. HELD OK. INCREASE PRESSURE TO 5500 PSI TO OPEN RSI		
TOOL @ 14,994'. PRESSURE AFTER OPENING TOOL 4000 PSI.		
100L & 11,771. Haddora in Tax of Linited 100B 1000 Id.		
1/23/2015 TO 1/31/2015 – FRAC WELL AND CLEAN OUT W/ COIL TUBING TO 14, 546'		
2/1/2015 – COMMENCED FLOWBACK. WELL ON PRODUCTION.		
2/1/2015 – COMMENCED FLOWBACK, WELL ON PRODUCTION.		
		·
Spud Date: 10/20/2014	Rig Release Date:	11/15/2014
I hereby certify that the information above is true	e and complete to the best of my knowled	lge and belief.
0 0		
SIGNATURE CAMIL DAG	TITLE REGULATORY AN	ALYST DATE 4.6.2015
SIGNATURE XVIII SUSSE	HILL REGULATORI AN	ALISI DAIL 7.0.2013
Type or print name <u>SARAH PRESLEY</u>	E-mail address: <u>spreslsey@na</u>	guss.com PHONE: (432) 682-4429
For State Use Only		- <u>*</u>
MIL.	TITLE Petroleum Engi	neer DATE 24/20/18
APPROVED BY:	TITLE Petroleum Engi	· · · · · · · · · · · · · · · · · · ·
Conditions of Approval (if any):		A CONTRACTOR OF THE CONTRACTOR