Submit 1 Copy To Appropriate District Office	State of New Mexico		Form C-103	
District I – (575) 393-6161	Energy, Minerals and Natural Resources			ed August 1, 2011
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.	,
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION		30-025-28339	
<u>District III</u> – (505) 334-6178	1220 South St. Francis Dr.		5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505			EE 🗌
District IV – (505) 476-3460	Santa 1 C, INVI 67303		6. State Oil & Gas Lease N	0.
1220 S. St. Francis Dr., Santa Fe, NM 87505				
	ICES AND REPORTS ON WELL	LS	7. Lease Name or Unit Agr	reement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			South Hobbs (G/SA) Unit	
DIFFERENT RESERVOIR. USE "APPLIC PROPOSALS.)	CATION FOR PERMIT" (FORM C-101)	FOR SUCH		/
1. Type of Well: Oil Well	Gas Well Other Temporarily Abandoned		8. Well Number 136	
2. Name of Operator	Gus Wen Grand Temperari	HOBBSOCD	9. OGRID Number: 15798	4
Occidental Permian Ltd.		9 00000	7. OGRED Humber: 13770	T
3. Address of Operator		A50 5 6 2015	10. Pool name or Wildcat	Hobbs (G/SA)
2611 State Hwy 214 Denver	City, TX 79323	APR 1 6 2015		
4. Well Location			J	
	400 foot from the North	line on Call 257	foot from the West 1:	
Unit Letter F: 2490 feet from the North line and 2504 feet from the West line				
Section 4	Township 19S		NMPM Lea	County
	11. Elevation (Show whether D 3621' KB	OK, KKB, KI, GK, etc.,	, , , , , , , , , , , , , , , , , , , ,	
			,	·
12 Charle	A	NI-4	D Od D	
12. Check A	Appropriate Box to Indicate	Nature of Notice,	Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK ☑ PLUG AND ABANDON ☐ REMEDIAL WORK ☐				JO . NG CASING □
TEMPORARILY ABANDON	CHANGE PLANS ☐ COMMENCE DRILLING OPNS.☐ P AND A ☐			
PULL OR ALTER CASING	드			
DOWNHOLE COMMINGLE				
DOVINIOLE COMMINICALE				
OTHER:		OTHER:		
13. Describe proposed or comp	leted operations. (Clearly state a	ll pertinent details, and	d give pertinent dates, includi	ng estimated date
	ork). SEE RULE 19.15.7.14 NM.	AC. For Multiple Cor	mpletions: Attach wellbore d	iagram of
proposed completion or recompletion.				
		•		
1. POOH w/ prod equipment		•		
2. Clean out well to PBTD @4290' and drill out cmt to TD @4322'				
3. Perforate 4105'-08', 4142'-49', 4205'-15', 4218'-23', 4228-36', 4243'-52', 4258'-67', 4272'-4315' (4 spf)				
4. Acid treat per prog During this procedure we plan to use				
5. Scale squeeze the closed-loop system with a steel				
6. RIH w/ prod equipment tank and haul contents to the required				
			disposal per ODC Rule :	19.15.17
Spud Date:	Rig Release	Date:		
I hereby certify that the information	above is true and complete to the	best of my knowledg	e and belief.	
•	,	,		
14	' . ()			
SIGNATURE Sleve	TITLE_Lift	t SpecialistDAT	ΓΕ <u>4/10/2015</u>	<u></u>
	_			
Type or print name Steve Sne	ead E-mail addres	s steve_snead@ox	y.com PHONE:_ 806-592-	-6312
For State Use Only		–	——————————————————————————————————————	—
			1	W. Janle
APPROVED BY:	TITLE Pe	troleum Engineer	DATE O	120112
Conditions of Approval (if any):			•	ŕ