Pistrict 1 1635 N. French Dr., Phone: (575) 393-61: <u>District 11</u> 811 S. First St., Arte Phone: (575) 748-12 <u>Pistrict 111</u> 1000 Rio Brazos Ro: Phone: (305) 333-61 <u>District IV</u> 1220 S. K. Francis F. Phone: (505) 476-34 APPLLIC	61 Fax: (575) sia, NM 88210 83 Fax: (575) 64 Aziec, NM 78 Fax: (505) 96, Santa Fe, N 60 Fax: (505)	393-0720 748-9720 87410 334-6170 1M 87505 476-3462 N FOR I	PERMIT TO Operator Name an COG Operatin 2208 West Mai	Energy Miner Oil Co 1220 So San DRILL, RE-E d Address	e of New Mexico als and Natural nservation Divis outh St. Francis ta Fe, NM 8750 NTER, DEEPI	Resources sion Dr. for yt		Imper
<u>.</u>			Artesia, NM	88210		30-0	A ATRA AL	
* Propert	y Code	17	<u></u>	Property Corazon 4 St	Name nte SWD		1	"Well No
	27 00			^{7.} Surface L	أعافك الكري والمراجع والمتحاف الماقا المالية			
UL-Loi	Section	Township	Range	Lot Idn Feet		Feet From	E/W Line	County
Bu	4	215	33E	10 350	10' Nonh	2500'	East	Lea
UL - Lot	Section	Townshin	Range	Lot Idn Feet		Feet From	E/W Line	County
		,						coonty
··			<u></u>	". Pool Info	rmation			
SWD: Devonian				Pool Name		5WD-1	628	Pool Code 96101
SWD, Devoluan			<u></u>	Additional Well	Information	70001	100	<u>} 90101</u>
¹¹ Work New V ¹⁶ Mut	/ell		¹² Well Type SWD	¹³ Cable		¹⁴ Lease Type State ¹⁹ Contractor	15	Ground Level Elevation 3817.5* ³⁰ Spuid Date
N	4		16,500'		onian	CURIFURN		5/1/2015
Depth to Ground	l water		Distanc	e from nearest fresh wate	r well	Distance	e to nearest sur	face water
	·		^{21.} P	roposed Casing an	l Cement Program	n		
Туре	Hole	Size	Casing Size	Casing Weight/ft	Setting Dept	h Sacks of	Coment	Estimated TOC
Surface	26		20	133	1,725'	200	000	0'
Introd	17.	5	13.375	68	5,600'	200	ю	0'
Production	12.2	5	9.625	43.5	11,700'	150	ю	0,
Liner	8.7	5	7	29	15,400'	40	0	11.400'
	+		ОН				· · · · · · · · · · · · · · · · · · ·	11,400
Disposal	6.12	۵		Cement Program:	I6,500'	<u> </u>		
hole to app hole to app hole to app	proximat proximat proximat	ely 5600 ely 11,7 ely 15,4	' with brine '00' with cut .00' with WBM, water, and]		68#, L80 and c -5/8", 43.5#, L 110 liner and c e for salt wate	ement to surface •80 csg and ceme ement back to T(r disposal purpo	e in 2 sta ent to sur DL. Drill	ges. Drill 12-1/4 face. Drill 8-3/4
	Турс			rking Pressure		Pressure		Manufacturer
Do	uble Ran	n		5000		5000		Cameron
est of my know further certif 19.15.14.9 (B)	vledge and y that I ha	belief. ve complie	d with 19.15.14.9 (and complete to the	C Approved By:	DIL CONSERVA	TION DIV	ISION
Signature: V	<u> </u>	<u>ap</u>	leg			Zac	the	
Printed name:	Mayte Rey	ycs	· · · · · · · · · · · · · · · · · · ·		Title:	Foleum Engin	eer	0.11
Title: Regulat	ory Analys	<u>I</u>			Approved Date:	25/01/15	Expiration Date	- 09folf5
E-mail Address	mreyes I @	concho.com	<u>n</u>					
Date: 4/23/201	5		Phone: 575-748-	6945	Conditions of Appr		Contraction of the local division of the loc	
					Pm C	See Al conditions		

MAY 0 5 2015

CONDITIONS OF APPROVAL

API #	Operator	Well name & Number
30-025-425279	COG Operating LLC	CORAZON 4 State # 2
Applicable conditions of approval marked with XXXXXX		<i>q</i> 000

Administrative Orders Required

SWD-1528	Will require administrative order for injection or disposal prior to injection or disposal
Other wells	

Other wells

Drilling

XXXXXXX	Once the well is spud, to prevent ground water contamination through whole or partial conduits from the surface, the operator shall drill without interruption through the fresh water zone or zones and shall immediately set in cement the water protection string			
Pits				

PITS

XXXXXXX	If using a pit for drilling and completions, must have an approved pit form prior to spudding the well

Completion & Production

XXXXXXX	Must notify Hobbs OCD office prior to conducting MIT (575) 393-6161 ext. 114		
XXXXXXX	Must conduct & pass MIT prior to any injection		

Potash Area

XXXXXXX	POTASH AREA - Four String Casing Program – In accordance with R-111-P surface string, salt protection string and production string shall be cemented to surface. Liner string must tie back into the production string
XXXXXXX	POTASH AREA - Salt Protection String - If the cement fails to reach the surface or the bottom of the cellar, where required, the top of the cement shall be located by a temperature or other survey and additional cementing shall be done until the cement is brought to the surface.

Casing

XXXXXXX	If cement does not circulate to surface, must run temperature survey or other log to determine top of
	cement
XXXXXXX	Surface casing must be set 25' below top of Rustler Anhydrite in order to seal off protectable water