Submit 3 Copies To Appropriate District Office	State of New Mexico			Form C-103					
District I	Energy, Minerals and Natural Resources			Revised March 25, 1999					
1625 N. French Dr., Hobbs, NM 88240 <u>Dístrict II</u>			WELL API NO.						
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION				30-025-27486 5. Indicate Type of Lease					
District III	1220 South	n St. Fran	ncis Dr.	STATE \boxtimes - FEE					
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505			6. State Oil & Gas Lease No.					
1220 S. St. Francis Dr., Santa Fe, NM		,		o. outeon te	Gub Deube 110.				
87505									
SUNDRY NOTIO (DO NOT USE THIS FORM FOR PROPOS	CES AND REPORTS ON		IC PACK TO A	7. Lease Name of	or Unit Agreement Na	ame:			
DIFFERENT RESERVOIR. USE "APPLIC									
PROPOSALS.)		· · · •		8011	_				
1. Type of Well:				State 2, 8006					
Oil Well Gas Well Other SWD									
2. Name of Operator BTA Oil Producers LLC				8. Well No.					
3. Address of Operator	9. Pool name or	Wildcat							
104 S. Pecos, Midland, TX 79	SWD;Delaware								
4. Well Location									
	660				~				
Unit Letter N : 556 feet from the south line and 1980 feet from the west line									
Section 2			Range 34E	NMPM I	Eddy County				
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3376' GR									
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data									
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:									
PERFORM REMEDIAL WORK 🗌	PLUG AND ABANDON		REMEDIAL WORI	к 🗆	ALTERING CASIN	G 🗌			
_		_				_			
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRI		PLUG AND ABANDONMENT				
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST AN CEMENT JOB	ND 🗌					
OTHER:			OTHER:	MIT Test		\boxtimes			

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

07/30 thru 09/24/14 Dig out cellar. Install WH on 9-5/8" csg. Plate back 20" and 13-3/8" csg to 9-5/8" csg. Install 5M csg head and press test 9-5/8" WH to 1500 psi. Install 2" risers with ball valves at surface. Wrap csg stubs in polyken tape. Backfill cellar. MIRU PU. NU BOP. Drill out cmt plug at surf. Tag CICR @ 960'. Drill out CICR and sqz cmt below. Did not tag plug @ 1465' - circ clean @ 1600'. Drill out plugs 3400' and 4800'. Tag cmt plug @ 8200'. Circ clean. Test csg to 600 psi. Good test, Test csg to 500 psi for 30 min on chart recorder. MIRU WL unit. RIH w/CIBP. Correlate to SLB open hole log dated 11/28/81. Set CIBP @ 7300'. Perf 7120-5508' w/3-1/8" guns, 2 SPF. Dump bail 40' cmt on CIBP @ 7300'. RIH w/pkr & tbg. Set pkr @ 5379'. ND BOP, NU tbg head. NU BOP. Get off pkr & circ around pkr fluid. Press test backside to 700 psi for 35 min on chart recorder.. ND BOP. NU WH. Perform injection test pumping in 2.5 BPM @ 1000 psi. RDMO. MIRU Acid Specialists. Pump 8000 gal 10% HCl w/200 bio balls. Perform MIT and injection rate test. This well was successfully tested. NMOCD field representative (Mr. George Bower) witnessed the test.

my knowledge and belief.	SWD-1492
tory Administrator	DATE 01/11/15

MAY 1 2 2015

I hereby certify that the information above is true and complete to the best of my knowledge and belief.							
SIGNATURE	m Juskep	TITLE Regulatory	AdministratorDATE01/11/15				
Type or print name	Pam Inskeep	pinskeep@btaoil.com	Telephone No. 432-682-3753				
(This space for State un APPPROVED BY Conditions of approval	Valey 2500	wn TITLE Dist	. Supervision DATE 5/11/2015				