Submit 1 Copy To Appropriate District	State of Nev	v Mexico	Form C-103
Office <u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Resources		Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88240	25 N. French Dr., Hobbs, NM 88240		WELL API NO.
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION		30-025-28983
<u>District III</u> - (505) 334-6178	1220 South St. Francis Dr.		5. Indicate Type of Lease STATE ☐ FEE ☒
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460	NM 87410 Sonto Eq. NIM 87505		6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	,		o. State on a Gas Zease 110.
SUNDRY NOT	ICES AND REPORTS ON W	FIIS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			South Hobbs (G/SA) Unit
PROPOSALS.) 1. Type of Well: Oil Well	Gas Well Other: Injecto		8. Well Number 191
2. Name of Operator			9. OGRID Number: 157984
Occidental Permian Ltd.		JUN 3 0 2015	
3. Address of Operator			10. Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX 79) 323	RECEIVED	
4. Well Location			
Unit Letter L: 1585 feet from the South line and 395 feet from the West line			
Section 4	A	19S Range 38E	NMPM Lea County
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3620.1 (KB)			
•			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING			
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PAND A			
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB			
DOWNHOLE COMMINGLE			
OTHER:	Г	OTHER:	П
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of			
proposed completion or recompletion.			
1 DOOH/ destinei			
1. POOH w/ production equipment 2. Clean out well to original PRTD	@4310' (Cement)	During this	procedure we plan to use
2. Clean out well to original PBTD @4310' (Cement) 3. Clean out well to new PBTD: 4320' the closed-			loop system with a steel
4. Perforate 4278'-4315', 4270'-4253', 4233'-4244', 4214'-4230' tank and ha			aul contents to the required
			er ODC Rule 19.15.17
6. RIH w/ injection equipment (CTI)			
7. Put well on injection			
Spud Date:	Rig Relea	ase Date:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURETITLE_Injection Well AnalystDATE6-26-15			
Type or print name _Robbie Underhill E-mail address _Robert _Underhill@oxy.com PHONE: _806-592-6287			
For State Use Only			
APPROVED BY: TITLE Petroleum Engineer DATE 07/17/15			
Conditions of Approval (if any).			