Submit 3 Copies To A	Appropriate District		State of New Mexico Energy, Minerals and Natural Resources			Form C-103
District I 1625 N. French Dr., F	Johns NM 87240	Energy, winicials a	na Naturai Resou	irces	WELL API NO.	June 19, 2008
District II		OIL CONSERV	'ATION DIVIS	ION	30-025-28	3343
1301 W. Grand Ave., District III	UI W. Grand Ave., Ariesia, NW 88210				5. Indicate Type of L	ease
1000 Rio Brazos Rd.,	Aztec, NM 87410		e, NM 87505		STATE	FEE X
<u>District IV</u> 1220 S. St. Francis Di 87505	r., Santa Fe, NM				6. State Oil & Gas Le	ease No.
SUNDRY NOTICES AND REPORTS ON WELLS DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)					7. Lease Name or Un  South Hobbs G/	
I. Type of Well:					8. Well Number	SA UTITE
Oil Well Gas Well Other WIW AIIG 1 9 2015					140	
2. Name of Opera				10	9. OGRID Number	
	Permian Ltd.				157984	
3. Address of Operator RECEIVED					10. Pool name or Wildcat	
P.O. Box 4294, Houston, TX 77210-4294 1. Well Location					Hobbs: Graybur	g-San Andres
Unit Letter _	1 .	1485 feet from the	SouthIi	ing and	1245 feet from t	he West line
Offit Letter _	·			ine and	<u> 12 10</u> leet from t	nenne
Section	4	Township		38-E		County Lea
36		11. Elevation (Show	whether DR, RKB, 3605' GR	RT, GR, etc	:)	
	· · · · · · · · · · · · · · · · · · ·				<u>-</u>	<u> </u>
	12. Check A	ppropriate Box to In	dicate Nature of	f Notice, R	Report, or Other Da	ta
NO	TICE OF INTI	ENTION TO:	<b>\</b>	SUBS	SEQUENT REPO	RT OF:
E E-PERM	ITTING <swe< td=""><td>) INJECTION</td><td>&gt; ] REMEDIA</td><td>AL WORK</td><td></td><td>ALTERING CASING</td></swe<>	) INJECTION	> ] REMEDIA	AL WORK		ALTERING CASING
						<del></del>
DETIILIK	CSION TV	RBDMs MW	COMMEN _	NCE DRILLII	NG OPNS. 🔲	P AND A
U		TA	]   CASING/	CEMENT JO	ов 🗆	
·C —	ENVIRO_	CHG LOC	-			
INTIO	PA P&A N	RP&A R	- i			
THER:			OTHER!	Convert	subject well to in	iection X
	nasad ar aamplata	d approximate (Clearly str				
		d operations. (Clearly sta SEE RULE 1103. For				
or recomplet	• • •	OLE ROLE 1103. For	wampie compien	ons. Tittaen	wendore diagram or p	roposed completion
			See Attached			
					•	
						_
	RUPU 5/14/1	<u> </u>			PU 6/26/15	]
Spud Date:		, , , , , , , , , , , , , , , , , , ,	Rig Release Date:			]
hereby certify the	at the information	above is true and comple	ete to the best of m	y knowledge	and belief.	
	Marks	ton1.0.	Dom:	1 - <b>-</b> Com	nlinnan Amalumt -	0/10/15
IGNATURE	I WAVE J	repuen!	TITLE_ <u>kedu</u>		<u>pliance Analyst</u> D	ATE <u>8/18/15</u>
lina ar nrint nam				Mank C+	onhoneBoyy com	
ype or print nam	e <u>Mark Stephen</u>	ıs	E-mail address		ephens@oxy.com PI	hone <u>(713) 366-515</u> 8
	1	ns .	4	s:	PI	_
For State Use On	1	Stalan.	4	s:	PI	HONE <u>(713) 366-515</u> 8 TE <u>9-15-15</u>

SEP 28 2015

South Hobbs G/SA Unit No. 140 UL L, Sec. 4, T-19-S, R-38-E, Lea Co., NM API No. 30-025-28343

5/14/15 - 5/18/15:

MI x RU pulling unit. ND WH x NU BOP. POOH w/ESP equipment x production tubing. RIH w/5-1/2" RBP x set at 4009'. Load x test casing to 600 psi x 30 min. ND BOP x workfloor. RD pulling unit x send in for repairs.

## 6/12/15 - 6/26/15:

MI x RU pulling unit. NU BOP x workfloor. Latch onto x POOH w/RBP. RIH w/4-3/4" bit x tag CIBP at 4208'. Drill out CIBP x cement to 4299'. Circulate well clean. Pull up above perfs. RU Renegade WL x tag at 4296'. Perforate at 4152'-55', 4216'-18', 4234'-52', 4257'-68', & 4274'-85' (200 shots). RD WL x RIH w/5-1/2" treating packer x set at 4050'. RU Petroplex x acidize perfs at 4089'-4285' w/5900 gal. 15% PAD acid. RD Petroplex x release treating packer. RIH w/5-1/2" Arrow-set injection packer on 126 jts. 2-7/8" injection tubing (packer set at 4044'). Test casing x packer to 600 psi. POOH w/tubing x set 5-1/2" RBP at 1007'. Dig out old wellhead x install new wellhead. Weld 8-5/8" x 5-1/2" casings to surface. Test wellhead to 3000 psi. ND WH x NU BOP x workfloor. Latch onto x POOH w/5-1/2" RBP. RIH w/124 jts. 2-7/8" duoline injection tubing. Circulate well w/100 bbls 10# BW. ND BOP x NU WH. Test wellhead to 5000 psi. Run MIT for the NMOCD - initial pressure 615 psi, final pressure 610 psi. RD x MO x clean location.

NOTE: Well is currently shut-in pending completion of surface work. Injection is expected to commence by the end of August, 2015.

