Submit 1 Copy To Appropriate District Office	State of New Me	Form C-103				
District I - (575) 393-6161	ct I – (575) 393-6161 Energy, Minerals and Natural Resources		Revised July 18, 2013 WELL API NO.			
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283	625 N. French Dr., Hobbs, NM 88240			30-025-30305		
811 S. First St., Artesia, NM 88210	S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION			5. Indicate Type of Lease		
District III - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.			STATE T FEE		
District IV - (505) 476-3460	Santa Fe, NM 87505			Oil & Gas Lease	e No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505			B93	11	3 6 4	
SUNDRY NOTICES AND REPORTS ON WELLS				7. Lease Name or Unit Agreement Name		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO OCO						
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCIP-				West Dollarhide Queen Sand Unit		
1. Type of Well: Oil Well Gas Well Other Injector				Number 148		
2. Name of Operator			9. OGRI	ID Number		
Ram Energy LLC	Ram Energy LLC			309777		
3. Address of Operator		RECEIVED	10. Pool	name or Wildca	at	
6100 E. Skelly Dr., Suit	e 600 Tulsa, OK 74135	RECO	Dollar	hide Queen	Sand	
4. Well Location						
Unit Letter M	700 feet from the Sout	h line and	550	_feet from the _	West_line	
Section 32	Township 24S Ra	ange 38E	NMPM	Lea Coun	ity	
	11. Elevation (Show whether DR	, RKB, RT, GR, etc.)			
	3135' GR			1512		
12. Check	Appropriate Box to Indicate N	lature of Notice,	Report of	r Other Data		
NOTICE OF I	ITENTION TO:	l cup	SEOUE	NT DEDOD	T OF:	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK ☑ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASING ☐						
TEMPORARILY ABANDON						
TEMPORARILY ABANDON						
DOWNHOLE COMMINGLE	MIDETIFEE COMPE	CASING/CEIVIEN	1 300			
CLOSED-LOOP SYSTEM						
OTHER:		OTHER:				
	pleted operations. (Clearly state all					
	ork). SEE RULE 19.15.7.14 NMA	C. For Multiple Co	mpletions:	Attach wellbore	e diagram of	
proposed completion or re	completion.					
			Condition			
Prepare to MIRU work over rig.				of Approval notify		
Prepare to MIRU work over rig. Condition of Approval: Notice OCD Hobbs office A						
Prepare to MIRU work over rig. Determine why well failed Bradenhead test. Description of running Markets and the state of running						
Repair as needed. Field operations will be conducted using closed loop system.						
Field operations	will be conducted using clo	seed loon eyete	m	163	CHAPT.	
		osed loop syste	111.		Constitution of the second	
er Underground Injection Contr	ol Program Manual					
11.6 C Packer shall be set withi	n or less than 100		Conditio	n of Approv	al: notify	
			Condition of Approval: notify			
feet of the uppermost injection perfs or open hole.			OCD Hobbs office 24 hours			
Sand Date	Bio Polosso De	nri	or of rus	ming MIT T	est & Chart	
Spud Date:	Rig Release Da	ne.	OI OI I WI	ming war	Cot Co Camer	
I handy contify that the information	above is two and complete to the b	act of my knowledge	a and balia	£		
I hereby certify that the information	above is true and complete to the b	est of my knowledg	e and belle	I.		
(10)						
SIGNATURE	TITLE Regul	atory Administrato	or	DATE 1	10/06/2015	
- 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				T	040.004.0500	
Type or print name Connie Swar	E-mail address	CSSwan@swan	derlandok.	com PHONE:	918 621-6533	
For State Use Only	0	1 1			1 1	
APPROVED BY:	& Brownine Di	T 5,000	1.600	DATE I	0/13/2015	
Conditions of Approval (if any):	~ IS UNIT CITLE IS A	v. orge	WWW	DATE /	1. 400.3	
11						