Submit 1 Copy To Appropriate District	State of New Me	xico	Form C-103
Office <u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Resources		Revised July 18, 2013
District II - (575) 748-1283 811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION District III - (505) 334-6178 1000 Rio Brazos Rd. Arten NM 87410 1220 South St. Francis Dr.			WELL API NO. 30-041-10138
			5. Indicate Type of Lease
		STATE FEE	
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa Fe, NM 87	505	 State Oil & Gas Lease No. K-1369
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other (INJECTOR)		HOBBS OCD	HALEY SAN ANDRES UNIT - 8. Well Number #18
2. Name of Operator RIDGEWAY ARIZONA OIL CO	/	OCT 1 6 2015	9. OGRID Number 164557
3. Address of Operator	SUITE 150, HOUSTON, TX 77079	RECEIVED	10. Pool name or Wildcat SAN ANDRES; Chaveroo
4. Well Location		The Grant V man	
Unit Letter J: 1980 fee	et from the SOUTH line and 1980 fee	et from the EAST 1	ine /
Section 33	Township 7S Range		MPM County ROOSEVELT
	11. Elevation (Show whether DR,	RKB, RT, GR, etc.,	
A REAL PROPERTY AND A REAL			
12. Check	Appropriate Box to Indicate Na	ature of Notice,	Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK I PLUG AND ABANDON REMEDIAL WOR		K ALTERING CASING	
PULL OR ALTER CASING DOWNHOLE COMMINGLE	MULTIPLE COMPL	CASING/CEMEN	
CLOSED-LOOP SYSTEM			
OTHER:		OTHER:	
of starting any proposed we	ork). SEE RULE 19.15.7.14 NMAC		d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of
proposed completion or recompletion.			The Oil Conservation Division
WELL WILL NOT PASS MIT. INTE	ND TO REPAIR WELL.	1	MUST BE NOTIFIED 24 Hours
1. RU, POOH WITH TUBING	G & EXISTING PACKER.	Pr	ior to the beginning of operations
2. RIH WITH BIT & SCRAPE	R TO BOTTOM & CLEAN OUT FILL		4
			HOLE & SQUEEZE. DRILL OUT CEMENT.
4. RIH WITH 2 3/8" TUBING	G AND PACKER. SET PACKER AT A	PPROXIMATELY	4115'C. O. A. SUBMIT CUPER
5. TEST ANNULUS TO 500 PSI. NIPPLE UP WELL HEAD. RDMO			WELLBORE DIAGRAM.
6. CONTACT OCD TO WITN			WELLTSORE NUMORATI
IF WELL REMAINS INCAPABLE OF		BE MADE TO EIT	HER SLIM HOLE OR P&A WELL
" Underground Injection Con	-		ndition of Approval: notify
Spud Dore Packer shall be set wit		te: O	CD Hobbs office 24 hours
feet of the uppermost injection perfs or open hole.		prior of running MIT Test & Chart	
I hereby certify that the information	above is true and complete to the be	est of my knowledg	e and belief.
SIGNATURE Q	TITLE: VP RI	EGULATORY AFI	FAIRS DATE10-6-2015
Type or print name JAMIE HOGUE	E-mail address: jhogue@enhanced	loilres.com PHON	E: <u>832-485-8522</u>
For State Use Only	1		
APPROVED BY:	MOUNT TITLE DU	st Supe	REPORTEDOCT 2 0 2015
	106 MONTHS-	NOPROD	REPORTEDOCT 2 0 2015