Submit 1 Copy To Appropriate District Office	Copy To Appropriate District State of New Mexico (575) 393-6161 Energy, Minerals and Natural Resources			Form C-103 Revised July 18, 2013
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and	d Natural Resources	WELL API NO.	/ 10, 2015
District II (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION		30-025-24740	
District III - (505) 334-6178	1220 South S	t. Francis Dr.	5. Indicate Type of Les STATE	FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV - (505) 476-3460	Santa Fe, M	NM 87505	6. State Oil & Gas Lea	
1220 S. St. Francis Dr., Santa Fe, NM 87505			E-8327	
SUNDRY NOT (DO NOT USE THIS FORM FOR PROP DIFFERENT RESERVOIR. USE "APPL PROPOSALS.) 1. Type of Well: Oil Well	 7. Lease Name or Unit Agreement Name State W / 8. Well Number / #3 			
2. Name of Operator			9. OGRID Number	
Herman L. Loeb LLC	r	OCT 2 1 2015		
3. Address of Operator			10. Pool name or Wildcat	
PO Box 838, Lawrenceville, Ill. 6	2439	RECEIVED	Jalmat	
4. Well Location	000 fast from the		0 fact from the	Fast line
Unit Letter P : 990 feet from the South line and 330 feet from the East line Section 36 Township 24S Range 36E NMPM Lea County				
Section 36	11. Elevation (Show wheth		the second se	County
	3,256 RT			
12. Check Appropriate Box to Indicate Nature Check Appropriate Box to Indicate Nature Check Appropriate Box to Indicate Nature NOTICE OF INTENTION TO: PLUG AND ABANDON RED PERFORM REMEDIAL WORK PLUG AND ABANDON RED PULL OR ALTER CASING MULTIPLE COMPL CA PULL OR ALTER CASING MULTIPLE COMPL CA COSED-LOOP SYSTEM OTHER: CHANGE PLANS OTHER: OTHER: CHANGE PLANS 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. Note: All work performed on this well will be done with a closed loop system and disposed of at a licensed facility. TACCLBP @ 2.725'. Pressure test esg to 500 ps. If casing tests spot 30 sx cmt on top of CIBP. From estimated top of plug spot 9.5 pg salt gel spacer to 1,400'. 2: Perforate 1,400'L404'. Establish an injection rate. If returns to surface in 4 ½'' casing annulus pmp cmt until good cmt to surface in annulus and leave inside of 4 ½''' csg full. If no circulation pmp 30 sx cmt and displace to 1,300'. If an injection rate is not established spot 30 sx cmt plug @ 1,450'. []] 3: If no circulation tag plug. Spot 9.5 pg salt gel spacer fr/top of plug to surface. Perforate 420'-421'. Pmp cmt until good cm to surface in 4 ½''' csg annulus and leave inside full. </td				
Spud Date:			Oil Conservation Dr T BE NOTIFIED 24	
I hereby certify that the information	above is true and complete to	o the best of my karined	the beginning of op	erations
SIGNATURE	y E-mail address:	_Agent for Herman L. Loe	PHONE: _719-342-5600	
APPROVED BY:	Down TITLE	Dist. Sup	UVGOL DATE	10/22/2015

OCT 2 2 2015

IM

