Submit I Copy To Appropriate District Office	State of New Mexico	Form C-103 Revised July 18, 2013
District I – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283 811 S. First St., Artesia, NM 88210 District III – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	Energy, Minerals and Natural Resources OIL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505	WELL API NO. 30-005- 63191
		5. Indicate Type of Lease STATE ☐ FEE ☒ ✓ 6. State Oil & Gas Lease No.
SUNDRY NOT (DO NOT USE THIS FORM FOR PROPO	CICES AND REPORTS ON WELLS DISALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DICATION FOR PERMIT" (FORM C-101) FOR SUCH Gas Well Other	7. Lease Name or Unit Agreement Name Twin Lakes San Andres Unit 8. Well Number 302
Name of Operator State of New Mexico formerly		9. OGRID Number
Address of Operator	Canyon E&F Company	10. Pool name or Wildcat
811 South 1st Street Artesia,	NM 88210	Twin Lakes, San Andres (Assoc)
4. Well Location Unit Letter N : 950 feet from the Section 25 Township 8S Range 28E NMPM County Chaves 11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or com of starting any proposed w	PLUG AND ABANDON CHANGE PLANS CONVER RETURN CSNG INT TO POPULATION OF THE PLANS CORP. SEE RULE 19.15.7.14 NMAC. For Multiple Corp.	TOTA
HOBBS OCD		
NOV 0 4 2015 See Attached Procedure and Schematic		
RECEIVED	1.0	Conservation Division NOTIFIED 24 Hours
	Prior to the	beginning of operations
Spud Date:	Rig Release Date:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNATURE	TITLE	DATE
Type or print name For State Use Only	E-mail address:	PHONE:
APPROVED BY: Conditions of Approval (if any):	SBrowners Dist Super	NUSON DATE 11/4/2015

NOV 0 4 2015

ha

Canyon E&P Company
Twin Lakes San Andres Unit No. 302
30-005-63191
UL – N, Sec. 25, T8S, R28E

8 5/8" csg at 112' w/ ready mix Circ. 5 ½" 15.5# csg at 2695 ' w/ 965 sx cmt, (7 7/8" hole) Circ. TD – 2700' Perfs 2572' – 2616' CIBP set at 2525' in 2001.

- 1. MIRU plugging equipment.
- 2. Tag CIBP at 2525', circulate hole w/ mud laden fluid, and pressure test csg to 500 psi.
- 3. Spot 25 sx cement on CIBP.
- 4. POOH to 2000'. Spot 25 sx cmt.
- 5. POOH to 1000'. Spot 25 sx cmt.
- 6. POOH to 162'. Fill to surface w/ cmt.
- 7. Cut off wellhead 4 feet below ground level.
- 8. Verify cement to surface on all strings.
- 9. Install upright P&A marker and cut off anchors.

NOTES: Mud laden fluid consists of 9.5 ppg with 25 sx salt gel per 100 bbls of fluid. If casing will not hold pressure, contact the OCD for instructions prior to preceding with P&A.

TWIN LAKES SAN ANDRES UNIT #302

PROPOSED

CUT OFF WELLHEAD & INSTALL DRY HOLE MARKER



POOH TO 162'. FILL TO SURFACE W/CMT.

SPOT 25 SX CMT AT 1000'.

SPOT 25 SX CMT AT 2000'.

CIRCULATE MUD LADEN FLUID

TAG CIBP AT 2525'. CAP WITH 25 SX

Perfs 2572'-2616' 5 1/2 " 15.5# @ 2695' w/ 965 sx.