

.

## HOBBS OCD

# NOV 0 5 2015

340'

#### EOG RESOURCES, INC. MOSLEY 16 STATE COM #2H

## Hydrogen Sulfide Plan Summary

- A. All personnel shall receive proper H2S training in accordance with Onshore Order III.C.3.a.
- B. Briefing Area: two perpendicular areas will be designated by signs and readily accessible.
- C. Required Emergency Equipment:
  - Well control equipment
    - a. Flare line 150' from wellhead to be ignited by flare gun.
    - b. Choke manifold with a remotely operated choke.
    - c. Mud/gas separator
  - Protective equipment for essential personnel.

Breathing apparatus:

- Rescue Packs (SCBA) 1 unit shall be placed at each breathing area, 2 shall be stored in the safety trailer.
- b. Work/Escape packs —4 packs shall be stored on the rig floor th sufficient air hose not to restrict work activity.
- Emergency Escape Packs —4 packs shall be stored in the doghouse for emergency evacuation.

Auxiliary Rescue Equipment:

- a. Stretcher
- b. Two OSHA full body harness
- c. 100 ft 5/8 inch OSHA approved rope
- d. 1-20# class ABC fire extinguisher

H2S detection and monitoring equipment:

The stationary detector with three sensors will be placed in the upper dog house if equipped, set to visually alarm @ 10 ppm and audible @ 14 ppm. Calibrate a minimum of every 30 days or as needed. The sensors will be placed in the following places: Rig floor / Bell nipple / End of flow line or where well bore fluid is being discharged.

(Gas sample tubes will be stored in the safety trailer)

Visual warning systems.

- a. One color code condition sign will be placed at the entrance to the site reflecting the possible conditions at the site.
- A colored condition flag will be on display, reflecting the current condition at the site at the time.
- c. Two wind socks will be placed in strategic locations, visible from all angles.

#### EOG RESOURCES, INC. MOSLEY 16 STATE COM #2H

#### Mud program:

The mud program has been designed to minimize the volume of H2S circulated to surface. The operator will have the necessary mud products to minimize hazards while drilling in H2S bearing zones.

#### Metallurgy:

All drill strings, casings, tubing, wellhead, blowout preventer, drilling spool, kill lines, choke manifold and lines, and valves shall be suitable for H2S service.

To the second

#### Communication:

Communication will be via cell phones and land lines where available.

## EOG RESOURCES, INC. MOSLEY 16 STATE COM #2H

PUBLIC SAFETY:	911 0
Lea County Sheriff's Department	(575) 396-3611
Rod Coffman	
Fire Department:	
Carlsbad	(575) 885-312
Artesia	(575) 746-505
Hospitals:	
Carlsbad	(575) 887-412
Artesia	(575) 748-333
Hobbs	(575) 392-197
Dept. of Public Safety/Carlsbad	(575) 748-971
Highway Department	(575) 885-328
New Mexico Oil Conservation	(575) 476-344
U.S. Dept. of Labor	(575) 887-1174
c.s. Dopt. of Eurof	(575) 567 117
EOG Resources, Inc.	
EOG / Midland	Office (432) 686-360
<b>Company Drilling Consultants:</b>	
Jeremy Rickels	Cell (432) 894-341
Josh Potts	(452) 894-541
505111 0115	
Drilling Engineer	
Kirby Castille	Office (432) 686-365'
	Cell (432) 559-498
Drilling Manager	
Lee Lohoefer	Office (432) 686-671
	Cell (817) 374-968
Drilling Superintendent	(017) 574-900
Jason Richey	Office (432) 686-366
	Cell (817) 879-652
Cactus Drilling	Cell (817) 873-052
Cactus Drilling	Office (580) 799-2752
Cactus 123 Drilling Rig	Rig (432) 894-341
Cactus 125 Diffining Kig	Nig (452) 894-541
Tool Pusher:	
Jack Herndon	Cell (405) 519-655
Larry Slife	Cell (405) 250-636
Safaty	
Safety Reggie Phillips (HSE Manager)	Office (432) 686-374
Reggie Filmps (HSE Manager)	
	Cell (432) 250-750

## **Emergency Assistance Telephone List**