State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-200

FILE IN TRIPLICATE	OIL CONSERV	ATION DIXISIO	N Revised 5-27-2004
DISTRICT I 1625 N. French Dr. , Hobbs, NM 88240	1220 South	St. Francis Dr. NM 87505	WELL API NO. 30-025-37558
DISTRICT II		OCT 2 9 2015	5. Indicate Type of Lease
1301 W. Grand Ave, Artesia, NM 88210		00. 20	STATE FEE X
DISTRICT III 1000 Rio Brazos Rd, Aztec, NM 87410		RECEIVED	6. State Oil & Gas Lease No.
SUNDRY NO	OTICES AND REPORTS ON WE		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR F	PROPOSALS TO DRILL OR TO DEEPEN	OR PLUG BACK TO A	
DIFFERENT RESERVOIR. USE "	APPLICATION FOR PERMIT" (Form C-	101) for such proposals.)	North Hobbs (G/SA) Unit Section 30
Type of Well:			8. Well No. 712
Oil Well 2. Name of Operator	Gas Well Other In	njector X	9. OGRID No. 157984
Occidental Permian Ltd.			3. OOKID No. 13/984
Address of Operator			10. Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, T.	X 79323		
4. Well Location			
Unit Letter E : 2378	Feet From The North	1086	Feet From The West Line
Section 29	Township 18-S	Range	38-E NMPM LEA County
	11. Elevation (Show whether DF, R. 3645' GR	KB, RT GR, etc.)	
Die D.I. a. I. T. I. A. I. a.			
Pit or Below-grade Tank Application or Closure			
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water			
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material			
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF IN			SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLIN	G OPNS. PLUG & ABANDONMENT
PULL OR ALTER CASING	Multiple Completion	CASING TEST AND C	EMENT JOB
OTHER: Wellhead Repair		OTHER:	
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any			
proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.			
I. RUPU&RU.		During this proced	ure we plan to use
ND wellhead/NU BOP. Determine failure and repair.		the closed-loop sy	
4. RBIH with injection packer and equipment tank and haul content			·
5. ND BOP/NU wellhead. disposal per ODC Rule 19.15.17 6. Test casing to 600 PSI for 30 minutes and chart for the NMOCD.			
7. RDPU & RU. Clean location and return			
During this procedure we plan to use the closed loop system with a steel tank and haul contents to the required disposal per ODC Rule 19.15.17			
C.O. A SUBMIT CURRENT WELL BORE Condition of Approval: notify OCD Hobbs office 24 hours			
	DIAGRAM	OCI	Hobbs office 24 hours ertify that any pit or below-grade tank has been/will be
I hereby certify that the information above is constructed or	s true and complete to the best of my know		
constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved			
$\Omega \Lambda$		plan	
SIGNATURE /		TITLE Injection	Well Analyst DATE 10-19-15
TYPE OR PRINT NAME Robbie Un	derhill E-mail address:	Robert_Underhill@o	<u>xy.com</u> TELEPHONE NO. 806-592-6287
For State Use Only	MB100m	Dist	Supervisor DATE 11/12/2018
APPROVED BY		_ TITLE	DATE TYTE

NOV 1 8 2015