

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENTNMOCD  
HobbsFORM APPROVED  
OMB NO. 1004-0135  
Expires: July 31, 2010**SUNDRY NOTICES AND REPORTS ON WELLS**  
*Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.*5. Lease Serial No.  
NMNM78273

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.  
LUCY FEDERAL 29. API Well No.  
30-025-40055-00-S110. Field and Pool, or Exploratory  
LEA YATES  
UNKNOWN11. County or Parish, and State  
LEA COUNTY, NM**SUBMIT IN TRIPLICATE - Other instructions on reverse side.**

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

READ &amp; STEVENS INCORPORATED

Contact: KELLY BARAJAS

E-Mail: kbarajas@read-stevens.com

3a. Address

ROSWELL, NM 88202

3b. Phone No. (include area code)

Ph: 575-622-3770

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Sec 14 T20S R34E NWSW 1980FSL 330FWL

**12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA**

| TYPE OF SUBMISSION                                    | TYPE OF ACTION                                |   |  |   |
|---|---|---|--|---|
| <input type="checkbox"/> Notice of Intent             | <input type="checkbox"/> Acidize              | <input type="checkbox"/> Deepen           | <input type="checkbox"/> Production (Start/Resume) | <input type="checkbox"/> Water Shut-Off |
| <input checked="" type="checkbox"/> Subsequent Report | <input type="checkbox"/> Alter Casing         | <input type="checkbox"/> Fracture Treat   | <input type="checkbox"/> Reclamation               | <input type="checkbox"/> Well Integrity |
| <input type="checkbox"/> Final Abandonment Notice     | <input type="checkbox"/> Casing Repair        | <input type="checkbox"/> New Construction | <input checked="" type="checkbox"/> Recomplete     | <input type="checkbox"/> Other          |
|   | <input type="checkbox"/> Change Plans         | <input type="checkbox"/> Plug and Abandon | <input type="checkbox"/> Temporarily Abandon       |   |
|   | <input type="checkbox"/> Convert to Injection | <input type="checkbox"/> Plug Back        | <input type="checkbox"/> Water Disposal            |   |

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleation in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

10/12/2015 - 10/15/2015

MIRUSU. POH w/rods. NDWH. NUBOP. RU 2" tbg swab and swab tbg dry in 3 swab runs. Making 1 run per hr for 3 hrs. RU pump truck. Load back side w/treated wtr. Pressure up csg to 3650# and hold for 15 min to test DV tool. Held ok. Release pressure. RD pump truck. RU swab. Swab tbg dry in 3 swab runs. 3% oil cut. Making 1 run per hr for 4 hrs. 50' fluid entry per hr. RD swab. Release pkr. RIH w/4 jnts 2 3/8" tbg. Attempt to latch onto RBP. Trash on top of RBP. RU pump truck on backside. Circ 45 bbls treated wtr to vacuum truck. RD pump truck. Latch onto and release RBP. Pull uphole and set @ 3497'. Release from plug and pull uphole and set pkr at 3428' w/12,000# tension. RU swab. Made 4 swab runs swabbing tbg dry. No oil show. Making 1 run per hr for 4 hrs. 100% wtr on every run. RD swab. Release pkr. RIH and latch onto RBP. Release RBP. RIH and set RBP at 3530'. Pull up and set pkr at 3499'. RU to swab test zone at 3502'-3507'. Made 4 runs

14. I hereby certify that the foregoing is true and correct.

Electronic Submission #320297 verified by the BLM Well Information System

For READ &amp; STEVENS INCORPORATED, sent to the Hobbs

Committed to AFMSS for processing by JENNIFER SANCHEZ on 10/29/2015 (16JAS0067SE)

Name (Printed/Typed) TIM COLLIER

Title SR VP DRILLING &amp; EXPLORATION

Signature (Electronic Submission)

Date 10/16/2015

**THIS SPACE FOR FEDERAL OR STATE OFFICE USE**

ACCEPTED FOR RECORD

Approved By

/S/ DAVID R. GLASS

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

**\*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\***

DEC 14 2015

**Additional data for EC transaction #320297 that would not fit on the form**

**32. Additional remarks, continued**

swabbing tbg dry. No oil show. RU swab. Swab tbg dry. RD swab. POH w/rods. Release pkr. RIH and latch onto RBP. Release RBP. POH w/2 3/8" tbg laying dwn pkr, RBP. TIH w/2 3/8" tbg open ended. NDBOP. NUWH. RDMOSU.