	an.						
Form 3160-3 (March 2012)	obbs	HOBBS	2015	ATS FORM OMB1	- 15 - 4 APPROVED No. 1004-0137	165	
UNITED STATI	ES INTERIOR	DEC 21	ZUIJ	5. Lease Serial No.	October 31, 20	14	
BUREAU OF LAND MA	NAGEMENT	DECEN	/ED	BHL: NMNM1884	48 SHL: N	MNM98	826
APPLICATION FOR PERMIT TO	D DRILL OF	REENTER		o. ii indian, rinotee	or moena	unc	
la. Type of work: DRILL REEN	TER			2 If Unit or CA Age	cement, Nan	ie and No	0.
lb. Type of Well: 🗸 Oil Well 🗌 Gas Well 🗌 Other	✓ Sin	ngle Zone 🔲 Multip	ple Zone	 Lease Name and Stray Cat 8 Fed 	Well No. Com 1H	(3	1572
2. Name of Operator Devon Energy Production Company,	L.P. 61	37)		9. API Well No.	11-2	98	2
3a. Address 333 W. Sheridan	3b. Phone No	(include area code)		10. Field and Pool, or	Exploratory	10-	
Oklahoma City, OK 73102-5010	405.228.	7203		Sand Dunes; Bor	ne Spring (53800)	
4. Location of Well (Report location clearly and in accordance with	any State requirem	ents.*)		11. Sec., T. R. M. or E	Blk. and Surv	ey or An	ea
At surface 211 FSL & 660 FWL, Unit M PP: 100 FS	SL & 660 FWL			Sec. 8 T23S R32	2E		
At proposed prod. zone 330 FNL & 660 FWL, Unit D				12 County or Parish		3 State	
 Distance in filles and direction from nearest town or post office* Approximately 22.55 miles Northeast of Malaga, NM 				Lea County		NM	
 Distance from proposed[®] See attached map location to nearest property or lease line, ft. (Also to nearest drig. unit line, if any) 	16. No. of a NMNM188 NMNM988	cres in lease 48 - 1,954.13 ac 26 - 320 ac	17. Spacin 160 ad	ng Unit dedicated to this	well		
8. Distance from proposed location* . See attached map	19. Proposed	i Depth	20. BLM/	I/BIA Bond No. on file			
to nearest well, drilling, completed, applied for, on this lease, ft.	TVD: 10,52 MD: 15,01	20'	CO-110	4; NBM-000801			
1. Elevations (Show whether DF, KDB, RT, GL, etc.)	22. Approxim	nate date work will sta	rt®	23. Estimated duration	n		
3592.9' GL	08/05/201	5		45 Days			
 he following, completed in accordance with the requirements of Onsi Well plat certified by a registered surveyor. A Drilling Plan. A Surface Use Plan (if the location is on National Forest System SUPO must be filed with the appropriate Forest Service Office). 	hore Oil and Gas m Lands, the	 Bond to cover the filter and the cover the second term of term	ttached to the he operation specific inf	is form: ons unless covered by an cormation and/or plans a	n existing bo s may be req	nd on fil uired by	e (see the
5. Signature Juna Col	Name Trina	(Printed/Typed) C. Couch			Date 03/03/20	15	
Regulatory Analyst							
A	Name	(Printed/Typed)			DateEC	15	2015
Approved by (SignaturSteve Caffey	00				1		
itle FIELD MANAGER	Office	CARLS	BAD FIE	LDOFFICE	1		
Approved by (Signature Steve Caffey Title FIELD MANAGER Application approval does not warrant or certify that the applicant ho onduct operations thereon. Conditions of approval, if any, are attached.	Office olds legal or equit	CARLS able title to those righ	BAD FIE	ELD OFFICE	entiale the en	elicanti EAR	S
Approved by (Signature Steve Caffey Title FIELD MANAGER Application approval does not warrant or certify that the applicant ho onduct operations thereon. Conditions of approval, if any, are attached. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a tates any false, fictitious or fraudulent statements or representations a	Office olds legal or equit crime for any pe as to any matter w	CARLS able title to those righ rson knowingly and w ithin its jurisdiction.	BAD FIE	ELD OFFICE gjectlease which would OVAL FOR nake to any department of	entitle the ap	plicantic EAR	S
Approved by (Signature Steve Caffey itle FIELD MANAGER Application approval does not warrant or certify that the applicant he conduct operations thereon. Conditions of approval, if any, are attached. itle 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a tates any false, fictitious or fraudulent statements or representations a (Continued on page 2)	Office olds legal or equit crime for any pe as to any matter w	CARLS able title to those righ rson knowingly and w ithin its jurisdiction.	BAD FIE	LD OFFICE pectlease which would OVAL FOR nake to any department of *(Inst	or agency of	plicantic EAR the Uni	ted e 2)
Approved by (Signature Steve Caffey Title FIELD MANAGER Application approval does not warrant or certify that the applicant he onduct operations thereon. Conditions of approval, if any, are attached. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a tates any false, fictitious or fraudulent statements or representations a (Continued on page 2)	Office olds legal or equit crime for any pe as to any matter w	CARLS able title to those righ rson knowingly and v ithin its jurisdiction.	BAD FIE	ELD OFFICE pjectlease which would OVAL FOR nake to any department *(Inst	or agency of	plicantic EAR the Uni	ted e 2)
Approved by (Signature Steve Caffey Title FIELD MANAGER Application approval does not warrant or certify that the applicant he conduct operations thereon. Conditions of approval, if any, are attached. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a tates any false, fictitious or fraudulent statements or representations a (Continued on page 2)	Office olds legal or equit crime for any pe as to any matter w	CARLS able title to those righ rson knowingly and w ithin its jurisdiction.	BAD FIE	LD OFFICE pertiese which would OVAL FOR nake to any department *(Inst	or agency of	the Uni	ted e 2)
Approved by (Signature Steve Caffey Title FIELD MANAGER Application approval does not warrant or certify that the applicant he conduct operations thereon. Anditions of approval, if any, are attached. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a tates any false, fictitious or fraudulent statements or representations a (Continued on page 2) FISbad Controlled Water Basin	Office olds legal or equit crime for any pe as to any matter w	CARLS able title to those righ rson knowingly and v ithin its jurisdiction.	BAD FIE	LD OFFICE pectlease which would OVAL FOR nake to any department *(Inst	or agency of	the Uni	ted e 2)
Approved by (Signature Steve Caffey itle FIELD MANAGER Application approval does not warrant or certify that the applicant horonduct operations thereon. Nonditions of approval, if any, are attached. itle 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a attes any false, fictitious or fraudulent statements or representations a (Continued on page 2) rIsbad Controlled Water Basin	Office olds legal or equit crime for any pe as to any matter w	CARLS able title to those righ rson knowingly and w ithin its jurisdiction.		LD OFFICE	or agency of tructions	The Uni	ted e 2)

ė

Approval Subject to General Requirements & Special Stipulations Attached

DEC 2 1 2015

SEE ATTACHED FOR CONDITIONS OF APPROVAL

HOBBS OCD

Devon Energy, Stray Cat 8 Fed Com 1H

RECEIVED

DEC 21 2015

1. Geologic Formations

TVD of target	10,520'	Pilot hole depth	N/A	
MD at TD:	15,015'	Deepest expected fresh water:	400'	

Basin

Formation	Depth (TVD) from KB	Water/Mineral Bearing/ Target Zone?	Hazards*
Quaternary Fill	surface	Water	
Rustler	975	Water	
Base of Salt	4,564	Salt	
Lamar	4,746	Barren	
Delaware Group	4,794	Oil/Gas	
Bone Spring	8,598	Oil/Gas	
2 nd Bone Spring Sd.	10,333	Target Zone	
3rd Bone Spring Lm.	10,700		

*H2S, water flows, loss of circulation, abnormal pressures, etc.

Devon Energy, Stray Cat 8 Fed Com 1H

2. Casing Program

Hole Size	Casing	g Interval	Csg.	Weight	Grade	Conn	SF	SF Burst	SF
	From	To	Size	(lbs)			Collapse	Constant and	Tension
17.5"	0	1,075'	13.375"	48	H-40	STC	1.60	3.60	10.48
12.25"	0	4,650'	9.625"	40	HCK-55	BTC	1.590	1.49	4.98
8.75"	0	15,015'	5.5"	17	HCP-110	BTC	1.57	1.95	3.18
				BLM Min	imum Safet	y Factor	1.125	1.00	1.6 Dry 1.8 Wet

All casing strings will be tested in accordance with Onshore Oil and Gas Order #2 III.B.1.h

Must have table for contingency casing

	Y or N
Is casing new? If used, attach certification as required in Onshore Order #1	Y
Does casing meet API specifications? If no, attach casing specification sheet.	Y
Is premium or uncommon casing planned? If yes attach casing specification sheet.	N
Does the above casing design meet or exceed BLM's minimum standards? If not provide justification (loading assumptions, casing design criteria).	Y
Will the intermediate pipe be kept at a minimum 1/3 fluid filled to avoid approaching the collapse pressure rating of the casing?	Y
Is well located within Capitan Reef?	N
If yes, does production casing cement tie back a minimum of 50' above the Reef?	
Is well within the designated 4 string boundary.	
Is well located in SOPA but not in R-111-P?	N
If yes, are the first 2 strings cemented to surface and 3 rd string cement tied back 500' into previous casing?	
Is well located in R-111-P and SOPA?	N
If yes, are the first three strings cemented to surface?	
Is 2 nd string set 100' to 600' below the base of salt?	1.5
Is well located in high Cave/Karst?	N
If yes, are there two strings cemented to surface?	
(For 2 string wells) If yes, is there a contingency casing if lost circulation occurs?	
Is well located in critical Cave/Karst?	N
If yes, are there three strings cemented to surface?	

Devon Energy, Stray Cat 8 Fed Com 1H

3. Cementing Program

Casing	# Sks	Wt. lb/ gal	H ₂ O gal/sk	Yld ft3/ sack	500# Comp. Strength (hours)	Slurry Description
13-3/8" Surface	1150	14.8	6.32	1.33	6	Tail: Class C Cement + 0.125 lbs/sack Poly-E-Flake
9-5/8" Inter.	960	12.9	9.81	1.85	14	Lead: (65:35) Class C Cement: Poz (Fly Ash): 6% BWOC Bentonite + 5% BWOW Sodium Chloride + 0.125 Ibs/sack Poly-E-Flake
	430	14.8	6.32	1.33	6	Tail: Class C Cement + 0.125 lbs/sack Poly-E-Flake
	510	11.9	12.89	2.31	n/a	1 st Lead: (50:50) Class H Cement: Poz (Fly Ash) + 10% BWOC Bentonite + 1 lb/sk of Kol-Seal + 0.3% BWOC HR-601 + 0.5lb/sk D-Air 5000
5-1/2" Prod	330	12.5	10.86	1.96	30	2 nd Lead: (65:35) Class H Cement: Poz (Fly Ash) + 6% BWOC Bentonite + 0.25% BWOC HR-601 + 0.125 Ibs/sack Poly-E-Flake
-	1340	14.5	5.31	1.2	25	Tail: (50:50) Class H Cement: Poz (Fly Ash) + 0.5% bwoc HALAD-344 + 0.4% bwoc CFR-3 + 0.2% BWOC HR-601 + 2% bwoc Bentonite

Casing String	TOC	% Excess
13-3/8" Surface	0'	100%
9-5/8" Intermediate	0'	75%
5-1/2" Production Casing	4150'	25%

4. Pressure Control Equipment

N	A variance is requested for the use of a diverter on the surface casing.	See attached for
IN	schematic.	

BOP installed and tested before drilling which hole?	Size?	Min. Required WP	Тур	96	~	Tested to:
			Annu	ılar	х	50% of working pressure
			Blind	Ram		
12-1/4"	13-5/8"	3M	Pipe F	Ram		214
			Double	Ram	х	5101
	_		Other*	_		
			Annu	ılar	x	50% testing pressure
			Blind	Ram		
0 2/4"	12 5/0"	23.4	Pipe F	Ram		
8-3/4	13-3/8	31/1	Double	Ram	x	3M
			Other *			
			Annu	ılar	X	
			Blind	Ram		
			Pipe F	Ram		
			Double	Ram	x	
			Other *			

*Specify if additional ram is utilized.

BOP/BOPE will be tested by an independent service company to 250 psi low and the high pressure indicated above per Onshore Order 2 requirements. The System may be upgraded to a higher pressure but still tested to the working pressure listed in the table above. If the system is upgraded all the components installed will be functional and tested.

Pipe rams will be operationally checked each 24 hour period. Blind rams will be operationally checked on each trip out of the hole. These checks will be noted on the daily tour sheets. Other accessories to the BOP equipment will include a Kelly cock and floor safety valve (inside BOP) and choke lines and choke manifold. See attached schematics.

Y Formation integrity test will be performed per Onshore Order #2.
 On Exploratory wells or on that portion of any well approved for a 5M BOPE system or greater, a pressure integrity test of each casing shoe shall be performed. Will be tested in accordance with Onshore Oil and Gas Order #2 III.B.1.i.

Y	A variance is requested for the use of a flexible choke line from the BOP to Choke Manifold. See attached for specs and hydrostatic test chart.
•	Y Are anchors required by manufacturer?
Y	A multibowl wellhead is being used. The BOP will be tested per Onshore Order #2 after installation on the surface casing which will cover testing requirements for a maximum of 30 days. If any seal subject to test pressure is broken the system must be tested.
	 Devon proposes using a multi-bowl wellhead assembly (FMC Uni-head). This assembly will only be tested when installed on the surface casing. Minimum working pressure of the blowout preventer (BOP) and related equipment (BOPE) required for drilling below the surface casing shoe shall be 3000 (3M) psi. Wellhead will be installed by FMC's representatives. If the welding is performed by a third party, the FMC's representative will monitor the temperature to verify that it does not exceed the maximum temperature of the seal.
	 FMC representative will install the test plug for the initial BOP test. FMC will install a solid steel body pack-off to completely isolate the lower head after cementing intermediate casing. After installation of the pack-off, the pack-off and the lower flange will be tested to 3M, as shown on the attached schematic. Everything above the pack-off will not have been altered whatsoever from the initial nipple up. Therefore the BOP components will not be retested at that time. If the cement does not circulate and one inch operations would have been possible with a standard wellhead, the well head will be cut and top out operations will be conducted.
	 Devon will pressure test all seals above and below the mandrel (but still above the casing) to full working pressure rating. Devon will test the casing to 0.22 psi/ft or 1500 psi, whichever is greater, as per Onshore Order #2.
	After running the 13-3/8" surface casing, a 13-5/8" BOP/BOPE system with a minimum rating of 3M will be installed on the FMC Uni-head wellhead system and will undergo a 250 psi low pressure test followed by a 3,000 psi high pressure test. The 3,000 psi high and 250 psi low test will cover testing requirements a maximum of 30 days, as per Onshore Order #2. If the well is not complete within 30 days of this BOP test, another full BOP test will be conducted, as per Onshore Order #2. After running the 9-5/8' intermediate casing with a mandrel hanger, the 13-5/8" BOP/BOPE system with a minimum rating of 3M will already be installed on the FMC Uni-head.
	The pipe rams will be operated and checked each 24 hour period and each time the drill pipe is out of the hole. These tests will be logged in the daily driller's log. A 2" kill line and 3" choke line will be incorporated into the drilling spool below the ram BOP. In addition to the rams and annular preventer, additional BOP accessories include a kelly cock, floor safety valve, choke lines, and choke manifold rated at 3,000 psi WP.



Devon requests a variance to use a flexible line with flanged ends between the BOP and the choke manifold (choke line). The line will be kept as straight as possible with minimal turns

See attached schematic.

5. Mud Program

	Depth	Туре	Weight (ppg)	Viscosity	Water Loss	
From	To					
0	1,075'	FW Gel	8.6-8.8	28-34	N/C	
1,075'	4,650'	Saturated Brine	10.0-10.2	28-34	N/C	
4,650'	15,015'	Cut Brine	8.5-9.3	28-34	N/C	

Sufficient mud materials to maintain mud properties and meet minimum lost circulation and weight increase requirements will be kept on location at all times.

What will be used to monitor the loss or gain	PVT/Pason/Visual Monitoring
of fluid?	

6. Logging and Testing Procedures

Log	ging, Coring and Testing.
X	Will run GR/CNL fromTD to surface (horizontal well - vertical portion of hole). Stated
	logs run will be in the Completion Report and submitted to the BLM.
	No Logs are planned based on well control or offset log information.
	Drill stem test? If yes, explain
	Coring? If yes, explain

Ado	litional logs planned	Interval
	Resistivity	Int. shoe to KOP
	Density	Int. shoe to KOP
Х	CBL	Production casing
Х	Mud log	Intermediate shoe to TD
	PEX	

Devon Energy, Stray Cat 8 Fed Com 1H

7. Drilling Conditions

Condition	Specify what type and where?
BH Pressure at deepest TVD	2773 psi
Abnormal Temperature	No

Mitigation measure for abnormal conditions. Describe. Lost circulation material/sweeps/mud scavengers.



Hydrogen Sulfide (H2S) monitors will be installed prior to drilling out the surface shoe. If H2S is detected in concentrations greater than 100 ppm, the operator will comply with the provisions of Onshore Oil and Gas Order #6. If Hydrogen Sulfide is encountered, measured values and formations will be provided to the BLM.

valu	es and formations will be provided to the BLM.
N	H2S is present
Y	H2S Plan attached

8. Other facets of operation

Is this a walking operation? No. Will be pre-setting casing? No.

Attachments <u>x</u> Directional Plan Other, describe

> 7 Drilling Plan







.•

•

NOTES REGARDING BLOWOUT PREVENTERS

Devon Energy Production Company, L.P. Stray Cat 8 Fed Com 1H

- Drilling Nipple will be constructed so it can be removed mechanically without the aid of a welder. The minimum internal diameter will equal BOP bore.
- Wear ring will be properly installed in head.
- Blowout preventer and all associated filings will be in operable condition to withstand a minimum of 3000psi working pressure.
- 4. All fittings will be flanged.
- 5. A fill bore safety valve tested to a minimum of 3000psi WP with proper thread connections will be available on the rotary rig floor at all times.
- All choke lines will be anchored to prevent movement.
- All BOP equipment will be equal to or larger in bore than the internal diameter of the last casing string.
- 8. Will maintain a kelly cock attached to the kelly.
- 9. Hand wheels and wrenches will be properly installed and tested for safe operation.
- Hydraulic floor control for blowout preventer will be located as near in proximity to driller's controls as possible.
- 11. All BOP equipment will meet API standards and include a minimum 40 gallon accumulator having two independent means of power to initiate closing operation.

Ontinental & CONTITECH

Fluid Technology

ContiTech Beattie Corp. Website: <u>www.contitechbeattie.com</u>

Monday, June 14, 2010

RE: Drilling & Production Hoses Lifting & Safety Equipment

To Helmerich & Payne,

A Continental ContiTech hose assembly can perform as intended and suitable for the application regardless of whether the hose is secured or unsecured in its configuration. As a manufacturer of High Pressure Hose Assemblies for use in Drilling & Production, we do offer the corresponding lifting and safety equipment, this has the added benefit of easing the lifting and handling of each hose assembly whitst affording hose longevity by ensuring correct handling methods and procedures as well as securing the hose in the unlikely event of a failure; but in no way does the lifting and safety equipment affect the performance of the hoses providing the hose have been handled and installed correctly. It is good practice to use lifting & safety equipment but not mandatory

Should you have any questions or require any additional information/darifications then please do not hesitate to contact us.

ContiTech Beattle is part of the Continental AG Corporation and can offer the full support resources associated with a global organization.

Best regards,

Robin Hodgson Sales Manager ContiTech Beattie Corp

ContiTech Beattie Corp, 11535 Brittmoore Park Drive, Houston, TX 77041 Phone: +1 (832) 327-0141 Fac: +1 (832) 327-0148 www.contitechbeattie.com



RIG 212



OUALITY DOCUMENT

.

ł.

÷

x

.

.

.

.

1

è

ź

PHOENIX RUBBER

÷

729 Szeged, Budapesti út 10. Hungary • H-6701 Szeged, P. O. Box 152 hone: (3662) 566-737 • Fax: (3662) 566-738 SALES & MARKETING: H-1092 Budapest, Rådayu. 42-44. Hungary - H-1440 Budapest, P. O. Box 26 Phone: (361) 456-4200 · Fax: (361) 217-2972, 456-4273 · www.taurusemerge.hu

INSPECT	TION AND	1001					and the second se		
PURCHASER:	Phoe	inix Beatti	ie Co.			P.O. Nº	1	519FA-87	'1
PHOENIX RUBBER or	der Nº- 170	0466	HOSE TYPE:	3"	ID ·	Che	oke and	Kill Hose	
HOSE SERIAL Nº	34	128	NOMINALIA	CTUAL LE	ENGTH:		11,43	m	
W.P. 68,96 MPa	10000	psi	т.р. 103,4	MPa	1500) psi	Duration	60	mi
Pressure test with wate	w at				1		. N.	-	
-									
						, î.,			
·									
	•	See atta	chment. (1	page)	S.,				•
1				1					
	· • •					×			
									-
	14.								
10 mm = 10 → 10 mm = 25	Min. MPa	5 /							ي م
10 mm = 10 → 10 mm = 25	Min. MPa	s /	COUPL	INGS					- 48
↑ 10 mm = 10 → 10 mm = 25 Type	Min. MPa	s /	COUPL Serial N°	INGS		Quality		He	at N°
↑ 10 mm = 10 → 10 mm = 25 Type 3" coupling w	Min. MPa	s / \$ 720	COUPL Serial N°) 719	INGS	At	Quality SI 4130		Her C7	at N° 626
↑ 10 mm = 10 → 10 mm = 25 Type 3" coupling w 4 1/16" Flang	Min. MPa	s / \$ 720	COUPL Serial Nº 719	INGS	AI	Quality SI 4130 SI 4130		Her C7 47	at N° 626 357
↑ 10 mm = 10 → 10 mm = 25 Type 3" coupling w 4 1/16" Flang	Min. MPa	\$ 720	COUPL Serial N°) 719	INGS	AI	Quality SI 4130 SI 4130		Her C7 47:	at N° 626 357
↑ 10 mm = 10 → 10 mm = 25 Type 3" coupling w 4 1/16" Flang	Min. MPa	5 /	COUPL Serial N°) 719	INGS	AI AI	Quality SI 4130 SI 4130		Hei C7 47:	at N° 626 357
↑ 10 mm = 10 → 10 mm = 25 Type 3" coupling w 4 1/16" Flang	Min. MPa	s / 720	COUPL Serial Nº) 719	INGS	At Al	Quality SI 4130 SI 4130		Her C7 47:	at N° 626 357
↑ 10 mm = 10 → 10 mm = 25 Type 3" coupling w 4 1/16" Flang	Min. MPa	\$ 720	COUPL Serial Nº) 719	API S Temp	AI AI pec 16	Quality SI 4130 SI 4130 C e rate:"f	3"	Her C7 47:	at N° 626 357
↑ 10 mm = 10 → 10 mm = 25 Type 3" coupling w 4 1/16" Flang All metal parts are flawle	Min. MPa	720	COUPL Serial N°) 719	API S Temp	At Al pec 16 erature	Quality SI 4130 SI 4130 C e rate:"f	3"	Her C7 47	at N° 626 357
↑ 10 mm = 10 → 10 mm = 25 Type 3" coupling w 4 1/16" Flang All metal parts are flaw/ WE CERTIFY THAT THE DESENTING THAT THE	Min. MPa 	s / 720	COUPL Serial N° 719 MANUFACTUR	API S Temp	At Al spec 16 erature	Quality SI 4130 SI 4130 C rate:"F	3" I ТНЕ ТЕЯ	Her C7 47:	at N° 626 357 ORDER A
↑ 10 mm = 10 → 10 mm = 25 Type 3" coupling w 4 1/16" Flang All metal parts are flawing WE CERTIFY THAT THE PRESSURE TESTED AS J 2010.	Min. MPa with e end ess ABOVE HOSE I ABOVE WITH S	s 720 720 HAS BEEN ATISFACTO	COUPL Serial N°) 719 MANUFACTUR RY RESULT.	API S Temp	At Al pec 16 erature	Quality SI 4130 SI 4130 C e rate:"f	B"	Her C7 47	at N° 626 357 ORDER A
↑ 10 mm = 10 → 10 mm = 25 Type 3" coupling w 4 1/16" Flang All metal parts are flaw/ WE CERTIFY THAT THE PRESSURE TESTED AS / Date:	Min. MPa ith le end ess ABOVE HOSE I ABOVE WITH S	ATISFACTO	COUPL Serial N°) 719 MANUFACTUR RY RESULT.	API S Temp	At Al pec 16 erature cordan	Quality SI 4130 SI 4130 C e rate:"f cc with cc with	B"	Her C7 47: MS OF THE IBBER	at N° 626 357 ORDER A
↑ 10 mm = 10 → 10 mm = 25 Type 3" coupling w 4 1/16" Flang All metal parts are flaw/w WE CERTIFY THAT THE PRESSURE TESTED AS // Date: 29. April 2002	Min. MPa nith e end ess ABOVE HOSE I ABOVE WITH S	s 720 720 HAS BEEN ATISFACTO	COUPL Serial N° 719 MANUFACTUR RY RESULT.	API S Temp RED IN AC	At Al pec 16 erature corban	Quality SI 4130 SI 4130 C e rate:"f ce with ce with f f f f f f f f f f f f f f f f f f f	B" I THE TERM ENIX RU dustrial	Her C7 47: MS OF THE JBBER Ltd.	at N° 626 357 ORDER A



Nord All start

 $\exp\{k_{ij}f\}$

1.5

Atom .

51 5.1

4.6. 40

÷

-

Contrag C

VERIFIED TRUE CG. PHOENIX RUBBER & C a star

1. Oak 1.



Commitment Runs Deep



Design Plan Operation and Maintenance Plan Closure Plan

SENM - Closed Loop Systems June 2010

I. Design Plan

Devon uses MI SWACO closed loop system (CLS). The MI SWACO CLS is designed to maintain drill solids at or below 5%. The equipment is arranged to progressively remove solids from the largest to the smallest size. Drilling fluids can thus be reused and savings is realized on mud and disposal costs. Dewatering may be required with the centrifuges to insure removal of ultra fine solids.

The drilling location is constructed to allow storm water to flow to a central sump normally the cellar. This insures no contamination leaves the drilling pad in the event of a spill. Storm water is reused in the mud system or stored in a reserve fluid tank farm until it can be reused. All lubricants, oils, or chemicals are removed immediately from the ground to prevent the contamination of storm water. An oil trap is normally installed on the sump if an oil spill occurs during a storm.

A tank farm is utilized to store drilling fluids including fresh water and brine fluids. The tank farm is constructed on a 20 ml plastic lined, bermed pad to prevent the contamination of the drilling site during a spill. Fluids from other sites may be stored in these tanks for processing by the solids control equipment and reused in the mud system. At the end of the well the fluids are transported from the tank farm to an adjoining well or to the next well for the rig.

Prior to installing a closed-loop system on site, the topsoil, if present, will be stripped and stockpiled for use as the final cover or fill at the time of closure.

Signs will be posted on the fence surrounding the closed-loop system unless the closed-loop system is located on a site where there is an existing well, that is operated by Devon.

II. Operations and Maintenance Plan

Primary Shakers: The primary shakers make the first removal of drill solids from the drilling mud as it leaves the well bore. The shakers are sized to handle maximum drilling rate at optimal screen size. The shakers normally remove solids down to 74 microns.

2

Mud Cleaner: The Mud Cleaner cleans the fluid after it leaves the shakers. A set of hydrocyclones are sized to handle 1.25 to 1.5 times the maximum circulating rate. This ensures all the fluid is being processed to an average cut point of 25 microns. The wet discharged is dewatered on a shaker equipped with ultra fine mesh screens and generally cut at 40 microns.



Centrifuges: The centrifuges can be one or two in number depending on the well geometry or depth of well. The centrifuges are sized to maintain low gravity solids at 5% or below. They may or may not need a dewatering system to enhance the removal rates. The centrifuges can make a cut point of 8-10 microns depending on bowl speed, feed rate, solids loading and other factors.

The centrifuge system is designed to work on the active system and be flexible to process incoming fluids from other locations. This set-up is also dependant on well factors.

Dewatering System: The dewatering system is a chemical mixing and dosing system designed to enhance the solids removal of the centrifuge. Not commonly used in shallow wells. It may contain pH adjustment, coagulant mixing and dosing, and polymer mixing and dosing. Chemical flocculation binds ultra fine solids into a mass that is within the centrifuge operating design. The dewatering system improves the centrifuge cut point to infinity or allows for the return of clear water or brine fluid. This ability allows for the ultimate control of low gravity solids.

Cuttings Boxes: Cuttings boxes are utilized to capture drill solids that are discarded from the solids control equipment. These boxes are set upon a rail system that allows for the removal and replacement of a full box of cuttings with an empty one. They are equipped with a cover that insures no product is spilled into the environment during the transportation phase.

Process Tank: (Optional) The process tank allows for the holding and process of fluids that are being transferred into the mud system. Additionally, during times of lost circulation the process tank may hold active fluids that are removed for additional treatment. It can further be used as a mixing tank during well control conditions.

Sump and Sump Pump: The sump is used to collect storm water and the pump is used to transfer this fluid to the active system or to the tank for to hold in reserve. It can also be used to collect fluids that may escape during spills. The location contains drainage ditches that allow the location fluids to drain to the sump.

Reserve Fluids (Tank Farm): A series of frac tanks are used to replace the reserve pit. These are steel tanks that are equipped with a manifold system and a transfer pump. These tanks can contain any number of fluids used during the drilling process. These can include fresh water, cut brine, and saturated salt fluid. The fluid can be from the active well or reclaimed fluid from other locations. A 20 ml liner and berm system is employed to ensure the fluids do not migrate to the environment during a spill.

If a leak develops, the appropriate division district office will be notified within 48 hours of the discovery and the leak will be addressed. Spill prevention is accomplished by maintaining pump packing, hoses, and pipe fittings to insure no leaks are occurring. During an upset condition the source of the spill is isolated and repaired as soon as it is discovered. Free liquid is removed by a diaphragm pump and returned to the mud system. Loose topsoil may be used to stabilize the spill and the contaminated soil is excavated and placed in the cuttings boxes. After the well is finished and the rig has moved, the entire location is scrapped and testing will be performed to determine if a release has occurred.

All trash is kept in a wire mesh enclosure and removed to an approved landfill when full. All spent motor oils are kept in separate containers and they are removed and sent to an approved recycling center. Any spilled lubricants, pipe dope, or regulated chemicals are removed from soil and sent to landfills approved for these products.

These operations are monitored by Mi Swaco service technicians. Daily logs are maintained to ensure optimal equipment operation and maintenance. Screen and chemical use is logged to maintain inventory control. Fluid properties are monitored and recorded and drilling mud volumes are accounted for in the mud storage farm. This data is kept for end of well review to insure performance goals are met. Lessons learned are logged and used to help with continuous improvement.

A MI SWACO field supervisor manages from 3-5 wells. They are responsible for training personnel, supervising installations, and inspecting sites for compliance of MI SWACO safety and operational policy.

III. Closure Plan

A maximum 340' X 340' caliche pad is built per well. All of the trucks and steel tanks fit on this pad. All fluid cuttings go to the steel tanks to be hauled by various trucking companies to an agency approved disposal.

H&P Flex Rig Location Layout

