Submit I Copy To Appropriate District Office	State of New Mexi	Form C-103		
District 1 - (575) 393-6161 Energy, Minerals and Natural Resources			Revised July 18, 2013 WELL API NO.	
District II - (575) 748-1283  811 S. First St. Artesia NM 88240 PDS OCD ØIL CONSERVATION DIVISION			30 - 025-08514	
811 S. First St., Artesia, NM 8824BBS OCD OIL CONSERVATION DIVISION District III – (505) 334-6178 1220 South St. Francis Dr.			5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410  Dietriet IV - (505) 476-3460  Santa Fe, NM 87505			6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa D. M.			E-704	
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or U	Init Agreement Name
(DO NOT USE THIS FORM FORDE CRIMALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			State 8	
1. Type of Well: Oil Well Gas Well Other			8. Well Number 6	
Name of Operator     Kaiser-Francis Oil Company			9. OGRID Number 012361	
3. Address of Operator			10. Pool name or Wildcat	
P.O. Box 21468, Tulsa, OK 74121-1468			Townsend Perm	no (Upper Penn)
4. Well Location Unit Letter	660 feet from the South	line and	2210 feet from	the West line
Section 8	Township 16S Rans			County
11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
S. Clark Co. States	4041' DR			
12 Check Ar	propriate Box to Indicate Nat	ure of Notice	Report or Other D	lata
		E-PER	MITTING <swi< td=""><td></td></swi<>	
NOTICE OF INTENTION TO: CONVERSION PROME				
PERFORM REMEDIAL WORK PLUG AND ABANDON RETURN CO			RN TO	TA
PULL OR ALTER CASING  MULTIPLE COMPL  CA: CSNG_				CHG LOC
DOWNHOLE COMMINGLE   INT TO P			PACTY P&A N	RP&AR
CLOSED-LOOP SYSTEM				- rank
OTHER:	The state of the s	OTHER:	d alone and book dates	in aboding antiqueted data
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of				
proposed completion or recompletion.  Kaiser-Francis Oil Company requests permisstion to plug and abandon the State 8-6 according to the following procedure:				
1. TOOH w/ tbg-laying down.				
2 PULL washesting and THE Start 25 or Class CHSD assert on the of the Q 10 000 CGG				
3. Circ hole w/ approved 9.5# brine-based plugging mud w/ 25 sx gel/100 bbls.				
4 TOOH to 5860' Snot 25ex f/ 5860-5700 (ASK-1 RAK) - WOC? TAG				
5. TOOH to 4750'. Spot 25sx f/ 4750-4650' WOC & tag. SHOE POSSIBLE LEAK @				
6. 100H to 425. Spot 25sx t/ 425-300. WOC & tag. 13por 253x5@ 2900' +/_ 6400'.				
7. TOOH to 100'. Circ cmt to surf.  8. Cut off wellhead and mark location w/ 4' marker as per NM requirements.				
	urface equipment and remediate		s.	A OPPECTABLE.
WBD attached.	arrace equipment and remediate			CORPECTIONS.
			Oil Conservatio	
Spud Date:	Rig Release Date	1 475	ST BE NOTIFIE	E. St. C. Williams Co.
New Comments of the Comments o		Prior	to the beginning	of operations
I hereby certify that the information ab	ove is true and complete to the best	of my knowledge	e and belief.	1,507
^				
SIGNATURE COMPLIANCE Analyst DATE 11/13/15				
Type or print name Teresa Mixon  E-mail address: teresami@kfoc.net PHONE: 918-491-4591				
For State Use Only . A				
APPROVED BY: Maky & Brown TITLE Dist Supervisor DATE 11/25/2015				
Conditions of Approval (if any):				
			- D( )	
			1111 0 0 20	145

Kaiser-Francis Oil Company State 8-6 Location: Sec 8 T-16S, R-35E API: 30-025-08514 Townsend Field: County: Lea Spud Date: 4/14/56 State: **New Mexico** Completed: 6/56 KB - 4042' Elevation: GL - 4030' Diagram Updated: 1/13/15 Work History: 6/56-Drilled to 10,647' by Shell Oil Company 6/56-D/O shoe track w/ 4 3/4" bit to 10,636'. Perfd Wolfcamp 10,614-42' w/ 4 SPF. Washed perfs w/ 1000 gal mud clean-out agent. Injected 1000 gal mud 13 3/8" 48# H-40 @ 358' cmt w/ 350 sx circ clea-out agent into perfs. IP-flowing 232 BOPD & 334 Mcf/d 9/57-Put on pump 9/58-Perforated 10.550-68, 576-88, 606-12 w/ 4 SPF. Washed 10.550-612' OA w/ 250 gal 15% MCA. Injected 1000 gal 15% MCA 1900# @ 5 BPM. 10,550-612 IP'd at 162 BOPD and 2 BWPD. 4/59-Commingled 10.614-62 w/ 10.550-612 8 5/8" 32# J-55 & H-40 @ 4700'. Cmt'd w/ 6/59-Swab-tested perfs below 10,602'-98% water. Set CIBP @ 10,602' 2050 sx. Circ. 9/59-Perforated 10.505-13, 514-16 w/ 2.5 SPF. Az w/ 1000 gal 15% NE. New perfs flowed 116 BOPD + 13 BWPD @ 100# 12/61-Perforated 10.377-84, 316-26 Az w/ 1500 gal 15% Acid. 1 BPM @ 3500#. Commingled w/ existing perfs. Production went from 34 BOPD & 82 BWPD to 44 Csg leak 5766-98'. Sqz'd w/ 600 sx. Circ. BOPD and 126 BWPD 6/99-Located casing leak 5766-89'. Set retainer and est injection 2 BPM @ 800# Shot 4 sqz holes @ 5807' could not pump w/ returns out 8 5/8". Circ 600 sx Class C. Circ 55 sx to surface) Closed 8 5/8" into at 1800# csg valve and staged to 1500#. D/O ret and cement and test casing to 750#. Rough spot in csg ~6400'. May be leaking D/O CIBP and pushed to 10,589°. 7/99-Well producing 6 BOPD, 48 BWPD and 20 Mcf/d 6/05-TL. 285th it split. Rep 3 its. **Tubing Detail** 312 its 2 7/8" (N80??) 7/05-TL-suspected bad casing at 6393' started pumping under packer. 5/06-PC. Az 10,316-588 OA w/ 1500 gal 20% NeFe. 8/06-TL. Split collar 96 its f/ bottom 10/06-Fished parted rods. Pulled tubing and ran CBL. Found TOC @ 8735'. Set RBP at 10,270'. RIH w/ packer and tested casing. Found old leak and rough patch in casing at 6400' to both be leaking. 0-5600' & 6457-10,270' holding 1300# w/ no bleed. Pressured leaking spots to 1700#, but couldn't pump in to. Perfd 4 holes @ 5807, but could not pump into holes at 1500# TOC @ 8,735' (CBL) 10/06-Perfd Wolfcamp 10,116-22, 24-26, 32-38, 204-12, 16-17, 22-24, 32-36 (35) holes). Attempt to Az 10,116-236 OA. Had to circ acid down and spotted it on perfs. Finally got perfs to take acid 0.7 BPM @ 4500#. Commingled w/ existing perfs and pumped well under a packer. Well making 3 BOPD, 19 BWPD and 10 Mcf/d 6/07-Rod part CIBP @ 10.000' (10' cmt on top) 1/08-TL 12/08-TL. Joint above MA split. Isolated perfs and swab-tested f/ 10,010' to surface. Made 15 runs. Rec 150? Bbls black water. Could not swab FL below Wolfcamp 10,116-138' OA 3500'. POOH w/ tubing. Set CIBP @ 10,000'. RBIH w/ tbg. Wolfcamp 10,204-236' OA Wolfcamp 10,310-378' OA Wolfcamp 10,499-510' OA Wolfcamp 10,550-88' OA CIBP remnants pushed down hole to 10,589" CIBP @ 10,602' (1 sk on top) Wolfcamp 10,606-12' OA Wolfcamp 10,614'-42' OA 5-1/2" 15.5 & 17# J-55/N-80 @ 10,636". Cmt'd w/ 400 sx Trinity Inferno PBTD - 10,636 TD - 10.647