Form 3160-5 (April 2004)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

NMOCD

FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007

5. Lease Serial No.

NM-40453

SUNDRY NOTICES AND REPORTS ON WELLS bbs Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE- Other instructions on reverse side. | AN

7 If Unit or CA/Agreement, Name and/or No.

If Indian, Allottee or Tribe Name

1. Type of Well Gas Well Other 2. Name of Operator NADEL AND GUSSMAN HEVCO, LLC 3a. Address 3 3b. Phone No. (include area code)				8. Well Name and No. Young Deep Unit #13 9. API Well No. 3002528966							
						PO BOX 193 ~ ROSWELL NM 88202-1936 575.623.6601 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			10. Field ar	10. Field and Pool, or Exploratory Area Young; Bone Spring North	
						660' FNL & 1980' FWL, Sec.		1		or Parish, State	
12. CHECK AF	PPROPRIATE BOX(ES) T	O INDICATE NATURE OF N	OTICE, REPORT, OF	R OTHER DATA							
TYPE OF SUBMISSION	TYPE OF ACTION										
Notice of Intent Subsequent Report Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Fracture Treat Re New Construction Re Plug and Abandon Te	clamation (Start/Resume) clamation complete mporarily Abandon atter Disposal	Water Shut-Off Well Integrity Other Change of Operator							

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

This is a notification of Change of Operator on the above referenced well.

Harvey E. Yates Company, as new operator, accept all applicable terms, conditions, stipulations and restrictions concerning operatings conducted on this lease or portion of lease described.

SEE ATTACHED FUR CONDITIONS OF APPROVAL

BLM Bond No. NMB000317 Harvey E. Yates Company P.O. Box 1933 Roswell, NM 88202-1933

(Instructions on page 2)

Change of Operator EFFECTIVE 9/1/2014

	1		
undries are being submitted	by Mots	dor/to	take over
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)	Title Production Tech	/ ADDDON	
Signature Carry R. Link	Date Date	09/10/2014	
THIS SPACE FOR FEDERA	L OR STATE OFF	CE USE EC 3	May Ind
Approved by Conditions of approval, if any, are attached. Approval of this notice does not warr certify that the applicant holds legal or equitable title to those rights in the subject which would entitle the applicant to conduct operations thereon.		CARLSBAD FIELD	OFFICE /K2
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for an States any false, fictitious or fraudulent statements or representations as to any matter.	y person knowingly and will er within its jurisdiction.	Ifully to make to any departm	ent or agency of the United

Harvey E. Yates Company December 03, 2015 Change of Operator Conditions of Approval



- 1. Tank battery must be bermed/diked (must be able to contain 1 1/2 times the volume of the largest tank).
- 2. Submit for approval of water disposal method.
- 3. Submit updated facility diagrams as per Onshore Order #3
- 4. This agency shall be notified of any spill or discharge as required by NTL-3A.
- 5. All outstanding environmental issue must be addressed within 90 days. Contact Jim Amos for inspection and to resolve environmental issues. 575-234-5909
- 6. Install legible well sign on location with operator name, well name and number, lease number, unit number, 1/4 1/4, section, township, and range. NMOCD requires the API number on well signs.
- 7. Subject to like approval by NMOCD.
- 8. All Reporting to ONRR (OGOR Reports) must be brought current within 30 days of this approval including any past history.
- 9. If this well is incapable of producing in paying quantities submit NOI to plug and abandon this well or obtain approval to do otherwise within 90 days.
- Submit plan for approval of well operations for all TA/SI wells within 30 days of this approval to change operator.
- 11. If not in place acquire operating rights on this lease within 30 days with BLM office in Santa Fe, NM.

JAM 120315