Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

NMOCD Hobbs


FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on reverse side. 1. Type of Well Oil Well Gas Well Other				NMLC	5. Lease Serial No. NMLC031736A 6. If Indian, Allottee or Tribe Name 7. If Unit or CA/Agreement, Name and/or No. 73885U4940 8. Well Name and No. EMSU 103	
				7. If Unit 73885		
2. Name of Operator XTO ENERGY INCORPORATED Contact: STEPHANIE RABADUE					9. API Well No. 30-025-04331-00-S1	
Ba. Address 500 W ILLINOIS STREET SU MIDLAND, TX 79701	3b. Phone No. (include area code) Ph: 432.620.6714 HOBBS OC		FUNIC	and Pool, or Exploratory CE MONUMENT		
Location of Well (Footage, Sec., 7 Sec 25 T20S R36E NWNE 66		j) /	JAN REC	7 5 2016	y or Parish, and State	
12. CHECK APPI	ROPRIATE BOX(ES) T	O INDICATE I	NATURE OF	NOTICE, REPORT, O	OR OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION					
Notice of Intent	☐ Acidize ☐ Alter Casing	□ Deep		☐ Production (Start/R☐ Reclamation	desume) Water Shut-Off Well Integrity	
☐ Subsequent Report	☐ Casing Repair	□ New Construction		□ Recomplete □ Other		
☐ Final Abandonment Notice	☐ Change Plans	☐ Plug and Abandon		▼ Temporarily Abance	don	
	☐ Convert to Injection	on Plug Back		☐ Water Disposal		
3. Describe Proposed or Completed Op. If the proposal is to deepen directions Attach the Bond under which the word following completion of the involved testing has been completed. Final Attach the site is ready for for the XTO Energy, inc respectfully results of the testing that the site is ready for form the site is ready for for form the site is ready for form the site is ready for for form the site is ready for for form the site is ready for form	ally or recomplete horizontally, rk will be performed or provide a operations. If the operation repandonment Notices shall be final inspection.) requests to TA the reference of the provided and the reference of the provided and the reference of the provided and the provided an	give subsurface to the Bond No. on ssults in a multiple led only after all re nced well with t	cations and meas file with BLM/BL completion or rec quirements, inclu he following p	ured and true vertical depths A. Required subsequent reposition in a new interval, ding reclamation, have been rocedure:	of all pertinent markers and zones. orts shall be filed within 30 days a Form 3160-4 shall be filed once completed, and the operator has	
A closed-loop system will be u	used to perform this opera	ation.	SEE A'	TTACHED FO TIONS OF A	PPROVAL	

Name (Printed/Typed) STEPHANIE RABADUE Title REGULATORY ANALYST Signature (Electronic Submission) Date 11/11/2015 THIS SPACE FOR FEDERAL OR STATE OFFICE USE Title Approved By Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **



JAN 2 5 2016



BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

575-234-59

Approved for a period of 12 months ending 01/19/2017 subject to conditions of approval.

Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
 - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging. CIBP must be capped with minimum 25 sacks cement, placed with tubing, or 35 feet of cement if placed with bailer.
 - b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. Any leak-off will be evaluated.
 - c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
 - d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
 - e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned. 43 CFR 3162.3-4 (a) The operator shall promptly plug and abandon...wells in which oil or gas is not encountered in paying quantities...

Wells that successfully pass the casing integrity test **may** be approved for Temporary Abandonment (TA) status provided that the operator:

- 1. Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval with well bore diagram with all perforations and CIBP's and tops of cement on CIBP's.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

EMSU 103

- 1. Well is approved to be TA/SI for a period of 12 months or until 01/19/2017
- 2. This will be the last TA approval for this well.
- 3. Must submit NOI to recomplete or NOI to P&A. Must be submitted by 01/19/2017
- 4. COA's met at this time.