Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

NMOCD Hobbs

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

Lease Serial No. NMNM78273

SUNDRY	NMNM78273		
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.			6. If Indian, Allottee or Tribe Name
SUBMIT IN TR	7. If Unit or CA/Agreement, Name and/or No.		
Type of Well			8. Well Name and No.
☑ Oil Well ☐ Gas Well ☐ Ot		720	LUCY FEDERAL 2
2. Name of Operator READ & STEVENS INCORP	✓ Contact: ORATEDE-Mail: kbarajas@	KELLY BARAJASHOBB read-stevens.com	9 API Well No. 30-025-40055-00-S1
3a. Address		3b. Phone No. (include area (Ne)) Ph: 575-622-3770	10. Field and Pool, or Exploratory
ROSWELL, NM 88202	UNKNOWN		
4. Location of Well (Footage, Sec., 7	T., R., M., or Survey Description		11. County or Parish, and State
Sec 14 T20S R34E NWSW 1	980FSL 330FWL		LEA COUNTY, NM
		F =	
		E-PER	MITTIA
12. CHECK APP	ROPRIATE BOX(ES) TO	INDICATE N CONVE	MITTING SWD OTHER DATA
munn on auth Magion	T	RETUR	N TO RBDMS
TYPE OF SUBMISSION		CSNG	N TO RBDMS TACO
☑ Notice of Intent	☐ Acidize	Dee, INT TO P	ENVIRO IACR
	☐ Alter Casing	☐ Fracture Treat	P&A NR CHG LOC
☐ Subsequent Report	☐ Casing Repair	☐ New Construction	Recomp. P&AR
☐ Final Abandonment Notice	☐ Change Plans	☐ Plug and Abandon	☑ Temporarily Abandon
	☐ Convert to Injection	□ Plug Back	☐ Water Disposal
If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involved	ally or recomplete horizontally, rk will be performed or provide d operations. If the operation re- bandonment Notices shall be file final inspection.)	give subsurface locations and measur the Bond No. on file with BLM/BIA. sults in a multiple completion or recor ed only after all requirements, including	date of any proposed work and approximate duration thereof, ed and true vertical depths of all pertinent markers and zones. Required subsequent reports shall be filed within 30 days in a new interval, a Form 3160-4 shall be filed once in greclamation, have been completed, and the operator has

SEE ATTACHED FOR CONDITIONS OF APPROVAL

		_	
14. I hereby certify that	t the foregoing is true and correct. Electronic Submission #320569 verifie For READ & STEVENS INCOR Committed to AFMSS for processing by JENN	PORAT	TED, sent to the Hobbs
Name (Printed/Type	d) TIM COLLIER	Title	SR VP DRILLING &/EXPLORATION/
Signature	(Electronic Submission)	Date	10/19/2015 APPROVED
1825	THIS SPACE FOR FEDERA	L OR	STATE OFFICE USE
Approved By		Title	Jam Ma Jan Jam J
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		Office	BUREAU OF LAND JANAS MENT CARLSBAD FIELD OFFICE
Title 18 U.S.C. Section 1 States any false, fictitio	001 and Title 43 U.S.C. Section 1212, make it a crime for any pe us or fraudulent statements or representations as to any matter w	erson kno ithin its j	owingly and willfully to make to any department or agency of the United jurisdiction.

** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **

MUB/OCD 1/25/2016

JAN 2 5 2016

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Approved for a period of 12 months ending 01/19/2017 subject to conditions of approval.

Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
 - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging. CIBP must be capped with minimum 25 sacks cement, placed with tubing, or 35 feet of cement if placed with bailer.
 - b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. Any leak-off will be evaluated.
 - c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
 - d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
 - e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned. 43 CFR 3162.3-4 (a) The operator shall promptly plug and abandon...wells in which oil or gas is not encountered in paying quantities...

Wells that successfully pass the casing integrity test **may** be approved for Temporary Abandonment (TA) status provided that the operator:

- Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval with well bore diagram with all perforations and CIBP's and tops of cement on CIBP's.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

Lucy Federal 2

- 1. Well is approved to be TA/SI for a period of 12 months or until 01/19/2017
- 2. This will be the last TA approval for this well.
- 3. Must submit NOI to recomplete or NOI to P&A. Must be submitted by 01/19/2017
- 4. COA's met at this time.