Office	State of	f New Mexic	0			n C-103
<u>District I</u> – (575) 393-6161	Energy, Minerals	s and Natural	Resources		Revised Jul	y 18, 2013
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283				WELL API NO	30-025-03772	/
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION			5. Indicate Type of Lease		
District III - (505) 334-6178	1220 Sout	th St. Francis	Dr.	STATE		
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460	Santa F	e, NM 8750	5	6. State Oil &		
1220 S. St. Francis Dr., Santa Fe, NM					1770	
87505	ICEC AND DEPONTO	NUMBELLO		100		. 27
(DO NOT USE THIS FORM FOR PROPO	ICES AND REPORTS OF SALS TO DRILL OR TO DE		BACK TO A	7. Lease Name	or Unit Agreemen	t Name
DIFFERENT RESERVOIR. USE "APPLI	CATION FOR PERMIT" (FO	RM C-101) FOR S	UCH .	LOVINGTON	PADDOCK UNIT	. /
PROPOSALS.) 1. Type of Well: Oil Well	Gas Well Other	WATER INJE	CTION	8. Well Number		
1. Type of well. On well	Gas well Other	"HOB	B8 OCD		43	
2. Name of Operator		1 23		9. OGRID Nur	nber 11222	
CHEVRON MIDCONTINENT, L	. P. /	MAR	0 8 2016	10.0	241333	
3. Address of Operator	7.70705		40 2010	10. Pool name		
1500 SMITH RD. MIDLAND, TX		REC	FIVED	LOVINGTON	PADDOCK	
4. Well Location DATUM		112	LIAED			
Unit Letter_P_:66	0feet from the	SOUTHlin	ne and460	feet from	theEAST	line
Section 35	Township 16-S	Range	36-E	NMPM	County LEA	/
	11. Elevation (Show w	whether DR, RK	B, RT, GR, etc.)	Market Market		
	3,854' GR		A S. Agarta			
12. Check	Appropriate Box to I	ndicate Natu	re of Notice,	Report or Othe	er Data	
			N. Y.			
NOTICE OF IN				SEQUENT R		
PERFORM REMEDIAL WORK	INT TO PA		EMEDIAL WOR		ALTERING CAS	SING
TEMPORARILY ABANDON	P&A NR			LLING OPNS.	P AND A	X
PULL OR ALTER CASING	P&AR	C	ASING/CEMENT	T JOB		
DOWNHOLE COMMINGLE		_				
CLOSED-LOOP SYSTEM		7				
OTHER:			THER:			
13. Describe proposed or comp						
of starting any proposed w						
proposed completion or rec		6# @ 3,245' TO	OC EST. SURF	. 5 ½" 14&15.5#	@ 6,093' TOC @	3,613'
OH 6,093'-6,285', TD 6,2						
		OP & TEST C	ALL NMOCD	OK TO PLIMP C	MT TO PKR	
03/03/16 MOVE IN RIG & CMT E	QUIP. ND TREE, NU B		ALL NMOCD	OK TO PUMP C	MT TO PKR.	
	QUIP. ND TREE, NU B		ALL NMOCD	OK TO PUMP C	MT TO PKR.	
03/03/16 MOVE IN RIG & CMT E MIX & SPOT 25 SX CL "C" CEMI	QUIP. ND TREE, NU B ENT TO 6,022' W/ ISIP	1000 PSI.				
03/03/16 MOVE IN RIG & CMT E MIX & SPOT 25 SX CL "C" CEMI 03/04/16 RIH TAG @ 5,664', CAL	QUIP. ND TREE, NU B ENT TO 6,022' W/ ISIP L NMOCD OK TO CUT	1000 PSI. TBG. CIR W	10# SWG, RIH	I W/ 5 ½" CIBP &	& SET 5,660',	
03/03/16 MOVE IN RIG & CMT E MIX & SPOT 25 SX CL "C" CEMI	QUIP. ND TREE, NU B ENT TO 6,022' W/ ISIP L NMOCD OK TO CUT	1000 PSI. TBG. CIR W	10# SWG, RIH	I W/ 5 ½" CIBP &	& SET 5,660',	
03/03/16 MOVE IN RIG & CMT E MIX & SPOT 25 SX CL "C" CEMI 03/04/16 RIH TAG @ 5,664', CAL MIX & SPOT 25 SX CL "C" CEMI 03/05/16 PERF @ 3,295' NO INJ. 1	QUIP. ND TREE, NU BENT TO 6,022' W/ ISIP L NMOCD OK TO CUTENT FROM 5,660'-5,460	TBG. CIR W/0', MIX & SPC	10# SWG, RIH OT 25 SX CL "C	I W/ 5 ½" CIBP &	& SET 5,660', DM 4,705'-4,458'.	
03/03/16 MOVE IN RIG & CMT E MIX & SPOT 25 SX CL "C" CEMI 03/04/16 RIH TAG @ 5,664', CAL MIX & SPOT 25 SX CL "C" CEMI	QUIP. ND TREE, NU BENT TO 6,022' W/ ISIP L NMOCD OK TO CUTENT FROM 5,660'-5,460	TBG. CIR W/0', MIX & SPC	10# SWG, RIH OT 25 SX CL "C	I W/ 5 ½" CIBP &	& SET 5,660', DM 4,705'-4,458'.	
03/03/16 MOVE IN RIG & CMT E MIX & SPOT 25 SX CL "C" CEMIO 03/04/16 RIH TAG @ 5,664', CAL MIX & SPOT 25 SX CL "C" CEMIO 03/05/16 PERF @ 3,295' NO INJ. NOC & TAG @ 2,719', RIH & PE	QUIP. ND TREE, NU BENT TO 6,022' W/ ISIP L NMOCD OK TO CUTENT FROM 5,660'-5,460' NMOCD OK DROP 50', RF @ 2,100'.	TBG. CIR W/O', MIX & SPOT	10# SWG, RIH OT 25 SX CL "C 61 SX CL "C"	I W/ 5 ½" CIBP & " CEMENT FRO CEMENT FROM	& SET 5,660', DM 4,705'-4,458'.	
03/03/16 MOVE IN RIG & CMT E MIX & SPOT 25 SX CL "C" CEMIO 03/04/16 RIH TAG @ 5,664', CAL MIX & SPOT 25 SX CL "C" CEMIO 03/05/16 PERF @ 3,295' NO INJ. NOW WOC & TAG @ 2,719', RIH & PE	QUIP. ND TREE, NU BENT TO 6,022' W/ ISIP L NMOCD OK TO CUTENT FROM 5,660'-5,460 NMOCD OK DROP 50', RF @ 2,100'.	1000 PSI. T TBG. CIR W/0', MIX & SPC MIX & SPOT 00'-1,800', WC	10# SWG, RIH OT 25 SX CL "C" 61 SX CL "C" OC & TAG 1,840	I W/ 5 ½" CIBP & " CEMENT FROM CEMENT FROM 5',	& SET 5,660', DM 4,705'-4,458'.	
03/03/16 MOVE IN RIG & CMT E MIX & SPOT 25 SX CL "C" CEMI 03/04/16 RIH TAG @ 5,664', CAL MIX & SPOT 25 SX CL "C" CEMI 03/05/16 PERF @ 3,295' NO INJ. I WOC & TAG @ 2,719', RIH & PE	QUIP. ND TREE, NU BENT TO 6,022' W/ ISIP L NMOCD OK TO CUTENT FROM 5,660'-5,460 NMOCD OK DROP 50', RF @ 2,100'.	1000 PSI. T TBG. CIR W/0', MIX & SPC MIX & SPOT 00'-1,800', WC	10# SWG, RIH OT 25 SX CL "C" 61 SX CL "C" OC & TAG 1,840	I W/ 5 ½" CIBP & " CEMENT FROM CEMENT FROM 5',	& SET 5,660', DM 4,705'-4,458'.	
03/03/16 MOVE IN RIG & CMT E MIX & SPOT 25 SX CL "C" CEMIO 03/04/16 RIH TAG @ 5,664', CAL MIX & SPOT 25 SX CL "C" CEMIO 03/05/16 PERF @ 3,295' NO INJ. I WOC & TAG @ 2,719', RIH & PE 03/06/16 MIX & SQZ 75 SX CL "C" CEME	QUIP. ND TREE, NU BENT TO 6,022' W/ ISIP L NMOCD OK TO CUTENT FROM 5,660'-5,460 NMOCD OK DROP 50', RF @ 2,100'. "CEMENT FROM 2,10 NT FROM 100' BACK	TBG. CIR W/0', MIX & SPOT MIX & SPOT 00'-1,800', WO TO SURFACE	10# SWG, RIH OT 25 SX CL "C" 61 SX CL "C" OC & TAG 1,840 ON BOTH STI	W/5½" CIBP & CEMENT FROM	& SET 5,660', DM 4,705'-4,458'. I 3,345'-2,770',	CION
03/03/16 MOVE IN RIG & CMT E MIX & SPOT 25 SX CL "C" CEMIO 03/04/16 RIH TAG @ 5,664', CAL MIX & SPOT 25 SX CL "C" CEMIO 03/05/16 PERF @ 3,295' NO INJ. NOW WOC & TAG @ 2,719', RIH & PE	QUIP. ND TREE, NU BENT TO 6,022' W/ ISIP L NMOCD OK TO CUTENT FROM 5,660'-5,460 NMOCD OK DROP 50', RF @ 2,100'. "CEMENT FROM 2,10 NT FROM 100' BACK	TBG. CIR W/0', MIX & SPOT MIX & SPOT 00'-1,800', WO TO SURFACE	10# SWG, RIH OT 25 SX CL "C" 61 SX CL "C" OC & TAG 1,840 ON BOTH STI	W/5½" CIBP & CEMENT FROM	& SET 5,660', DM 4,705'-4,458'. I 3,345'-2,770',	TION.
03/03/16 MOVE IN RIG & CMT E MIX & SPOT 25 SX CL "C" CEMIO 03/04/16 RIH TAG @ 5,664', CAL MIX & SPOT 25 SX CL "C" CEMIO 03/05/16 PERF @ 3,295' NO INJ. IN WOC & TAG @ 2,719', RIH & PE 03/06/16 MIX & SQZ 75 SX CL "C" PERF & CIR 35 SX CL "C" CEMIO CUT ALL CASING & ANCHORS	QUIP. ND TREE, NU BENT TO 6,022' W/ ISIP L NMOCD OK TO CUTENT FROM 5,660'-5,460' NMOCD OK DROP 50', RF @ 2,100'. "CEMENT FROM 2,10' NT FROM 100' BACK & REMOVED 3' BELO	TBG. CIR W/0', MIX & SPOT MIX & SPOT 00'-1,800', WC TO SURFACE	10# SWG, RIH OT 25 SX CL "C" 61 SX CL "C" OC & TAG 1,846 ON BOTH STI	W/5½" CIBP & CEMENT FROM	& SET 5,660', DM 4,705'-4,458'. I 3,345'-2,770',	TION.
03/03/16 MOVE IN RIG & CMT E MIX & SPOT 25 SX CL "C" CEMIO 03/04/16 RIH TAG @ 5,664', CAL MIX & SPOT 25 SX CL "C" CEMIO 03/05/16 PERF @ 3,295' NO INJ. I WOC & TAG @ 2,719', RIH & PE 03/06/16 MIX & SQZ 75 SX CL "C" CEME	QUIP. ND TREE, NU BENT TO 6,022' W/ ISIP L NMOCD OK TO CUTENT FROM 5,660'-5,460' NMOCD OK DROP 50', RF @ 2,100'. "CEMENT FROM 2,10' NT FROM 100' BACK & REMOVED 3' BELO	TBG. CIR W/0', MIX & SPOT MIX & SPOT 00'-1,800', WC TO SURFACE	10# SWG, RIH OT 25 SX CL "C" 61 SX CL "C" OC & TAG 1,846 ON BOTH STI	W/5½" CIBP & CEMENT FROM	& SET 5,660', DM 4,705'-4,458'. I 3,345'-2,770',	TION.
03/03/16 MOVE IN RIG & CMT E MIX & SPOT 25 SX CL "C" CEMI 03/04/16 RIH TAG @ 5,664', CAL MIX & SPOT 25 SX CL "C" CEMI 03/05/16 PERF @ 3,295' NO INJ. I WOC & TAG @ 2,719', RIH & PE 03/06/16 MIX & SQZ 75 SX CL "C" CEME CUT ALL CASING & ANCHORS ALL CEMENT PLUGS CLASS "	QUIP. ND TREE, NU BENT TO 6,022' W/ ISIP L NMOCD OK TO CUTENT FROM 5,660'-5,460' NMOCD OK DROP 50', RF @ 2,100'. "" CEMENT FROM 2,10' NT FROM 100' BACK & REMOVED 3' BELOCOME.	TBG. CIR W/0', MIX & SPOT MIX & SPOT 00'-1,800', WC TO SURFACE OW GRADE. W	10# SWG, RIH OT 25 SX CL "C" 61 SX CL "C" OC & TAG 1,846 ON BOTH STI	W/5½" CIBP & CEMENT FROM	& SET 5,660', DM 4,705'-4,458'. I 3,345'-2,770',	TION.
03/03/16 MOVE IN RIG & CMT E MIX & SPOT 25 SX CL "C" CEMIO 03/04/16 RIH TAG @ 5,664', CAL MIX & SPOT 25 SX CL "C" CEMIO 03/05/16 PERF @ 3,295' NO INJ. IN WOC & TAG @ 2,719', RIH & PE 03/06/16 MIX & SQZ 75 SX CL "C" PERF & CIR 35 SX CL "C" CEMIO CUT ALL CASING & ANCHORS	QUIP. ND TREE, NU BENT TO 6,022' W/ ISIP L NMOCD OK TO CUTENT FROM 5,660'-5,460' NMOCD OK DROP 50', RF @ 2,100'. "" CEMENT FROM 2,10' NT FROM 100' BACK & REMOVED 3' BELOCOME.	TBG. CIR W/0', MIX & SPOT MIX & SPOT 00'-1,800', WC TO SURFACE	10# SWG, RIH OT 25 SX CL "C" 61 SX CL "C" OC & TAG 1,846 ON BOTH STI	W/5½" CIBP & CEMENT FROM	& SET 5,660', DM 4,705'-4,458'. I 3,345'-2,770',	TION.
03/03/16 MOVE IN RIG & CMT E MIX & SPOT 25 SX CL "C" CEMI 03/04/16 RIH TAG @ 5,664', CAL MIX & SPOT 25 SX CL "C" CEMI 03/05/16 PERF @ 3,295' NO INJ. I WOC & TAG @ 2,719', RIH & PE 03/06/16 MIX & SQZ 75 SX CL "C" CEME CUT ALL CASING & ANCHORS ALL CEMENT PLUGS CLASS "	QUIP. ND TREE, NU BENT TO 6,022' W/ ISIP L NMOCD OK TO CUTENT FROM 5,660'-5,460' NMOCD OK DROP 50', RF @ 2,100'. "" CEMENT FROM 2,10' NT FROM 100' BACK & REMOVED 3' BELOCOME.	TBG. CIR W/0', MIX & SPOT MIX & SPOT 00'-1,800', WC TO SURFACE OW GRADE. W	10# SWG, RIH OT 25 SX CL "C" 61 SX CL "C" OC & TAG 1,846 ON BOTH STI	W/5½" CIBP & CEMENT FROM	& SET 5,660', DM 4,705'-4,458'. I 3,345'-2,770',	TION.
03/03/16 MOVE IN RIG & CMT E MIX & SPOT 25 SX CL "C" CEMIO 03/04/16 RIH TAG @ 5,664', CAL MIX & SPOT 25 SX CL "C" CEMIO 03/05/16 PERF @ 3,295' NO INJ. IN WOC & TAG @ 2,719', RIH & PE 03/06/16 MIX & SQZ 75 SX CL "C" CEMIO CUT ALL CASING & ANCHORS ALL CEMENT PLUGS CLASS "Spud Date:	QUIP. ND TREE, NU BENT TO 6,022' W/ ISIP L NMOCD OK TO CUTENT FROM 5,660'-5,460 NMOCD OK DROP 50', RF @ 2,100'. "" CEMENT FROM 2,10 NT FROM 100' BACK & REMOVED 3' BELO C" W/ CLOSED LOOP	TBG. CIR W/0', MIX & SPOT MIX & SPOT 00'-1,800', WC TO SURFACE OW GRADE. W P SYSTEM US Release Date:	10# SWG, RIH OT 25 SX CL "C" 61 SX CL "C" 60 & TAG 1,846 ON BOTH STI VELD ON DRY	I W/ 5 ½" CIBP & "CEMENT FROM CEMENT FROM 5', RINGS.	& SET 5,660', DM 4,705'-4,458'. I 3,345'-2,770',	TION.
03/03/16 MOVE IN RIG & CMT E MIX & SPOT 25 SX CL "C" CEMI 03/04/16 RIH TAG @ 5,664', CAL MIX & SPOT 25 SX CL "C" CEMI 03/05/16 PERF @ 3,295' NO INJ. I WOC & TAG @ 2,719', RIH & PE 03/06/16 MIX & SQZ 75 SX CL "C" CEME CUT ALL CASING & ANCHORS ALL CEMENT PLUGS CLASS "	QUIP. ND TREE, NU BENT TO 6,022' W/ ISIP L NMOCD OK TO CUTENT FROM 5,660'-5,460 NMOCD OK DROP 50', RF @ 2,100'. "" CEMENT FROM 2,10 NT FROM 100' BACK & REMOVED 3' BELO C" W/ CLOSED LOOP	TBG. CIR W/0', MIX & SPOT MIX & SPOT 00'-1,800', WC TO SURFACE OW GRADE. W P SYSTEM US Release Date:	10# SWG, RIH OT 25 SX CL "C" 61 SX CL "C" 60 & TAG 1,846 ON BOTH STI VELD ON DRY	I W/ 5 ½" CIBP & "CEMENT FROM CEMENT FROM 5', RINGS.	& SET 5,660', DM 4,705'-4,458'. I 3,345'-2,770',	TION.
03/03/16 MOVE IN RIG & CMT E MIX & SPOT 25 SX CL "C" CEMI 03/04/16 RIH TAG @ 5,664', CAL MIX & SPOT 25 SX CL "C" CEMI 03/05/16 PERF @ 3,295' NO INJ. I WOC & TAG @ 2,719', RIH & PE 03/06/16 MIX & SQZ 75 SX CL "C" CEME CUT ALL CASING & ANCHORS ALL CEMENT PLUGS CLASS "Spud Date:	QUIP. ND TREE, NU BENT TO 6,022' W/ ISIP L NMOCD OK TO CUTENT FROM 5,660'-5,460' NMOCD OK DROP 50', RF @ 2,100'. "" CEMENT FROM 2,10' NT FROM 100' BACK & REMOVED 3' BELO C" W/ CLOSED LOOP Rig	TBG. CIR W/0', MIX & SPOT MIX & SPOT 00'-1,800', WO TO SURFACE W GRADE. W P SYSTEM US Release Date:	10# SWG, RIH OT 25 SX CL "C" 61 SX CL "C" OC & TAG 1,840 ON BOTH STI VELD ON DRY SED.	I W/ 5 ½" CIBP & "CEMENT FROM 6', RINGS. HOLE MARKEI	& SET 5,660', DM 4,705'-4,458'. I 3,345'-2,770', R. CLEAN LOCAT	ION.
03/03/16 MOVE IN RIG & CMT E MIX & SPOT 25 SX CL "C" CEMI 03/04/16 RIH TAG @ 5,664', CAL MIX & SPOT 25 SX CL "C" CEMI 03/05/16 PERF @ 3,295' NO INJ. I WOC & TAG @ 2,719', RIH & PE 03/06/16 MIX & SQZ 75 SX CL "C" CEME CUT ALL CASING & ANCHORS ALL CEMENT PLUGS CLASS "Spud Date: I hereby certify that the information SIGNATURE	QUIP. ND TREE, NU BENT TO 6,022' W/ ISIP L NMOCD OK TO CUTENT FROM 5,660'-5,460' NMOCD OK DROP 50', RF @ 2,100'. "" CEMENT FROM 2,10' NT FROM 100' BACK & REMOVED 3' BELO C" W/ CLOSED LOO! Rig	TOOO PSI. TO TBG. CIR W/0', MIX & SPOT MIX & SPOT OO'-1,800', WO TO SURFACE OW GRADE. W P SYSTEM US Release Date: ete to the best of ILE_Agent fo	10# SWG, RIH OT 25 SX CL "C" 61 SX CL "C" OC & TAG 1,840 ON BOTH STI VELD ON DRY SED.	I W/ 5 ½" CIBP & "CEMENT FROM CEMENT FROM 5', RINGS. HOLE MARKEI e and belief.	& SET 5,660', 0M 4,705'-4,458'. I 3,345'-2,770', R. CLEAN LOCAT	TION.
03/03/16 MOVE IN RIG & CMT E MIX & SPOT 25 SX CL "C" CEMI 03/04/16 RIH TAG @ 5,664', CAL MIX & SPOT 25 SX CL "C" CEMI 03/05/16 PERF @ 3,295' NO INJ. I WOC & TAG @ 2,719', RIH & PE 03/06/16 MIX & SQZ 75 SX CL "C" PERF & CIR 35 SX CL "C" CEME CUT ALL CASING & ANCHORS ALL CEMENT PLUGS CLASS " Spud Date: I hereby certify that the information SIGNATURE Type or print name Monty L. M	QUIP. ND TREE, NU BENT TO 6,022' W/ ISIP L NMOCD OK TO CUTENT FROM 5,660'-5,460' NMOCD OK DROP 50', RF @ 2,100'. "" CEMENT FROM 2,10' NT FROM 100' BACK & REMOVED 3' BELO C" W/ CLOSED LOO! Rig	TBG. CIR W/O', MIX & SPOT MIX & SPOT OO'-1,800', WO TO SURFACE OW GRADE. W P SYSTEM US Release Date: ete to the best of ILE_Agent for sss:monty.mo	10# SWG, RIH OT 25 SX CL "C" 61 SX CL "C" 60 & TAG 1,846 ON BOTH STI VELD ON DRY SED.	W/5 ½" CIBP & "CEMENT FROM CEMENT FROM S', RINGS. HOLE MARKED E and belief. A DATE M PHONE:	© SET 5,660', OM 4,705'-4,458'. I 3,345'-2,770', R. CLEAN LOCAT	
03/03/16 MOVE IN RIG & CMT E MIX & SPOT 25 SX CL "C" CEMI 03/04/16 RIH TAG @ 5,664', CAL MIX & SPOT 25 SX CL "C" CEMI 03/05/16 PERF @ 3,295' NO INJ. I WOC & TAG @ 2,719', RIH & PE 03/06/16 MIX & SQZ 75 SX CL "C" CEME CUT ALL CASING & ANCHORS ALL CEMENT PLUGS CLASS "Spud Date: I hereby certify that the information SIGNATURE	QUIP. ND TREE, NU BENT TO 6,022' W/ ISIP L NMOCD OK TO CUTENT FROM 5,660'-5,460' NMOCD OK DROP 50', RF @ 2,100'. "" CEMENT FROM 2,10' NT FROM 100' BACK & REMOVED 3' BELO C" W/ CLOSED LOO! Rig	TBG. CIR W/O', MIX & SPOT MIX & SPOT OO'-1,800', WO TO SURFACE OW GRADE. W P SYSTEM US Release Date: ete to the best of ILE_Agent for sss:monty.mo	10# SWG, RIH OT 25 SX CL "C" 61 SX CL "C" 60 & TAG 1,846 ON BOTH STI VELD ON DRY SED.	W/5 ½" CIBP & "CEMENT FROM CEMENT FROM S', RINGS. HOLE MARKED E and belief. A DATE M PHONE:	& SET 5,660', 0M 4,705'-4,458'. I 3,345'-2,770', R. CLEAN LOCAT	

MAR 1 5 2016

MAR 1 5 2016

M