Submit 1 Copy To Appropriate Di	strict Office								Form C-103	
District I	State of New Mexico Energy, Minerals and Natural Resources				Revised August 1, 2011 WELL API NO.					
1625 N. French Dr., Hobbs, NM 8	Energy, Willerals and Natural Nessurces				30-025-12467					
District II 811 A. First St., Artesia, NM 8821	OIL CONSERVATION DIVISION				5. Indicate Type of Lease					
Disrtict III 1000 Rio Brazos Rd. Aztec, NM 8	1220 South St. Francis Dr.				STATE ☑ FEE □ /					
District IV			Santa Fe, NM 87505				6. State Oil & Gas Lease NO.			
1220 S. St. Francis Dr., Santa Fe, NM 87505						BO-1626-0002				
SUNDRY NOTICES AND REPORTS ON WELLS						7. Lease I	7. Lease Name or Unit Agreement Name			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR DEEP A DIFFERENT RESERVIOR. USE "APPLICATION FOR PERMIT" (FO PROPOSALS.)						State "V"				
1. Type of Well: Oil Well  Gas Well  Other  MAR 1 1 2016						8. Well Number				
2. Name of Operator			. /	DEGE		9. OGRID	Numer			
Apache Corporation RECEIVED  3. Address of Operator						10. Pool N	Jame	873	- ·	
303 Veterans Airpark Lane, Ste. 3000, Midland, TX 79705							Eumont Yates/7 Rvrs Qn			
4. Well Location Unit Letter	н	2310'	feet from the	N	line and	330'	feet from	th E	line	
Section	36	Township	198	Range	36E	NMPM	reet from	County	Lea	
	1	1. Elevation (S		DR, RKB,R7 <b>593' GL</b>	T, GR, etc.)					
3393 GL										
12. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data										
NOTICE OF INTENTION TO:						SUBSEQUENT				
PERFORM REMEDIAL WOR	PLUG ANI	O ABANDON	REMEDIAL	EMEDIAL WORK IN			A DM			
TEMPORARILY ABANDON PULL OR ALTER CASING		=			COMMENCE DRILLING OPN CASING/CEMENT JOB			P&A NR		
PULL OR ALTER CASING   MULTIPLE COMPL   CASING/O DOWNHOLE COMMINGLE   ALTERING						DX A D				
P AND A										
OTHER:	completed of	nerations (Cla	arly state all r	pertinent det	OTHER:	nertinent d	atos incli	uding estima	ted date of	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram or proposed completion or recompletion.										
Apache Corporation pro						-			system will	
be used t	or all fluid	s from this w	velibore and	i aisposea	or required	ву ОСБ	Rule 19.	15.17.		
Saud Date:					4 HOURS PE	RIOR TO I	BEGINNI	NG		
Spud Date:			PLU	GGING OP	ERATIONS					
I hereby certify that the information	n above is true	e and complete t	o the best of my	y knowledge a	and belief.					
SIGNATURE	Sudin	Buchs	TITLE	Sr. Red	lamation Fo	oreman	DATE	3	/2/16	
Type or print name	Guinn	Burks	E-mail add.	guinn.bur	rks@apache	corp.com	PHONE:	432-5	556-9143	
For State Use Only	11	$\Theta$	P	etroleur	Eur	Sout !	+	12/11	1/2011	
APPROVED BY: \ \( \text{\lambda} \)	anul:	Wita Mu	TITLE \	~110101	n wyr.	SPUCK	DATE	2016	1/2016	
Conditions of Approval (if	arry).					P	IAK 13	7010		

M



 LEASE NAME
 State "V"

 WELL #
 3

 API #
 30-025-12467

 COUNTY
 LEA

WELL BORE INFO.

17 1/2" Hole 12 1/2" 40# @ 191' w/ 200 sx to surf

TOF @ 502'

EOT @ 3328'

TOP of Fish @ 3347'

1175

783

0

392

1566

1958

2349

2741

3132

3524

3915

7 7/8" Hole 6 5/8" 20# @ 3796' w/ 100 sx cmt OH 3796' - 3915'

11" Hole 8 5/8" 32# @ 2373' w/ 600 sx to surf



Perfs @ 3165' - 3450'

TOF @ 3780'



 LEASE NAME
 State "V"

 WELL #
 3

 API #
 30-025-12467

 COUNTY
 LEA

WELL BORE INFO.

0

17 1/2" Hole 12 1/2" 40# @ 191' w/ 200 sx to surf

392

783

1175

1566

1958

2349

16.37

2741

3132

3524

3915

7 7/8" Hole 6 5/8" 20# @ 3796' w/ 100 sx cmt OH 3796' - 3915'

11" Hole 8 5/8" 32# @ 2373'

w/ 600 sx to surf

TOF @ 502' EOT @ 3328' TOP of Fish @ 3347'

PUH & perf @ 241' & attempt to sqz 80 sx Class "C" cmt from 241' to surf. (Surf shoe & water board)

per 1592. W/4050

4. PUH & spot 30 sx Class "C" cmt from 1206' - 1106", WOC/TAG (Top of salt)

Perf : 582 w | 50 5x

3. PUH & spot 35 sx Class "C" cmt from 2433' - 2273', WOC/TAG (Base of Salt & shoe)

 MIRU P&A rig & RIH w/ tbg & CIRC w/ MLF & spot 30 sx Class "C" cmt on top of CIBP @ 3100' (Eumont perfs)

 MIRU service rig & fish tbg & clean out to 3100'. Set CIBP @ 3100' & RDMO service rig.

TOF @ 3780'

PBTD @ 3483'

TD @ 3915'