HOBBS OCD Stand of New Mexico Submit One Copy To Appropriate District Form C-103 Energy Minerals and Natural Resources Office Revised November 3, 2011 District I WELL API NO. 1625 N. French Dr., Hobbs, NM 88240 30-025-24022 District II OIL CONSERVATION DIVISION 811 S. First St., Artesia, NM 88210 5. Indicate Type of Lease District III 1220 South St. Francis Dr. STATE FEE 🗸 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 6. State Oil & Gas Lease No. District IV 1220 S. St. Francis Dr., Santa Fe, NM SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH H T MATTERN NCT B PROPOSALS.) 8. Well Number 1. Type of Well: Oil Well Gas Well Other: Injection 1 #014 2. Name of Operator 9. OGRID Number CHEVRON US A INC 4323 3. Address of Operator 10. Pool name or Wildcat 15 SMITH ROAD, MIDLAND, TEXAS 79705 4. Well Location . 660 feet from the SOUTH line and 660 Unit Letter feet from the WEST line Section 30 Township 21S Range 37E **NMPM** County LEA 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3519 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING | TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS.□ PANDA **PULL OR ALTER CASING** MULTIPLE COMPL CASING/CEMENT JOB OTHER: ✓ Location is ready for OCD inspection after P&A All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. 1 Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. 1 A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the following: OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other \checkmark production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.) All other environmental concerns have been addressed as per OCD rules. 1 Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease; all electrical service poles and lines have been removed from lease and well location, except for utility's distribution infrastructure. When all work has been completed, return this form to the appropriate District office to schedule an inspection. TITLE: Project Rep DATE: 3-17-2016 SIGNATURE: TYPE OR PRINT NAME Chris Gibbons E-MAIL: cgibbons@chevron.com PHONE: 985-228-0582

TITLE P.E.S.

Conditions of Approval (if any):

For State Use Only

APRRQVED

MAR 7 & 2016

DATE 03/23/2016