Submit 1 Copy To Appropriate District Office	State of New Mexico	Form C-103
District I	Energy, Minerals and Natural Resources	October 13, 2009
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION	30-025-05724
District III	1220 South St. Francis Dr.	STATE FEE V
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		5. Simile on 6. Sub 25th35 1.5.
SUNDRY NOT	CES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLIO	SALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A CATION FOR PERMIT" (FORM C-101) FOR SUCH	North Monument G/SA Unit Blk. 11
PROPOSALS.)  1. Type of Well: Oil Well	Gas Wall  Other Injection 1000 000	0 11/11/1 1 10
2. Name of Operator	Gas Well Other Injection 18BS OC	9. OGRID Number 873
Apache Corp.		9. OGRID Nullibel 8/3
3. Address of Operator	MAR 1 6 2016	10. Pool name or Wildcat
P O box Drawer D Monument NM	88265	Eunice Monument G/SA
4. Well Location	RECEIVE	)
The state of the s	660 feet from the S line and	d 660 feet from the
W line		a _oooleet nom the
Section	20 Township 10S Bonco	OTE NIMBM Lee County
Section	29 Township 19S Range 3 11. Elevation (Show whether DR, RKB, RT, GR, or	B7E NMPM Lea County
	11. Elevation (Snow whether DR, RRB, R1, GR, C	etc.)
NEW YORK THE RESERVE THE RESER		
12 Check	Appropriate Box to Indicate Nature of Notice	ce Report or Other Data
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF IN	ITENTION TO: SU	JBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL W	
TEMPORARILY ABANDON	CHANGE PLANS   COMMENCE	DRILLING OPNS. P AND A
PULL OR ALTER CASING	MULTIPLE COMPL CASING/CEM	ENT JOB
DOWNHOLE COMMINGLE		
OTHER: Pressure test	OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
proposed completion of recompletion.		
Intend to move in a pump truck to perform pressure test on casing. Will pressure up to 520 psi for 32 minutes and chart the results.		
interest to move in a painty state to perform pressure test on easing. With pressure up to 220 psi for 32 minutes and chart the results.		
Spud Date:	Rig Release Date:	
I hereby certify that the information	above is true and complete to the best of my knowle	edge and belief.
$\bigcirc$	2 -	
		71/1/
SIGNATURE	TITLEInstrument Tech_	DATE 3-16-16
The state of the s		
Type or print name Jim Ellison E-mail address: _JD.Ellison@apacheccorp.com_ PHONE:575-441-7734		
For State Use Only		
APPROVED BY: Sill Son	manah TITLE Staff M	away * DATE 4/1/16 1
Conditions of Approval (if any):		
		APR 0 5 2016
		ULIV 0 2 7010