UNITED STATES DEPARTMENT OF THE INTERIOR

NMOCD

FORM APPROVED OMB NO. 1004-0135

	UREAU OF LAND MANA NOTICES AND REPO is form for proposals to II. Use form 3160-3 (API	RTS ON WELLS	obbs	5. Lease Serial No. NMLC060944 6. If Indian, Allottee	or Tribe Name
SUBMIT IN TRIPLICATE - Other instructions on reverse side.				7. If Unit or CA/Agreement, Name and/or No. NMNM87877X 8. Well Name and No. SJU TR-C 160	
Type of Well					
2. Name of Operator LEGACY RESERVES OPERA	9. API Well No. 30-025-32085-00-S1				
Sa. Address 303 W WALL SUITE 1600 MIDLAND, TX 79702		3b. Phone No. (include area code) Ph: 432-689-5200 Ext: 5273		10. Field and Pool, or Exploratory JUSTIS	
Location of Well (Footage, Sec., T.				and State	
Sec 14 T25S R37E SWNE 150		APR 25 DINDICATE NATURE OF		LEA COUNTY,	
TYPE OF SUBMISSION	TYPE OF ACTION				
□ Notice of Intent Subsequent Report	☐ Acidize ☐ Alter Casing ☐ Casing Repair	☐ Deepen ☐ Fracture Treat ☐ New Construction	☐ Production (Start/Resume) ☐ Reclamation ☐ Recomplete ☑ Temporarily Abandon ☐ Water Disposal		☐ Water Shut-Off ☐ Well Integrity ☐ Other

testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

04/05/16 Ran MIT, pressure casing to 543#, held. Well is now TA'd.

which would entitle the applicant to conduct operations thereon.

Legacy's future plans on this well will involve the performance of a wellbore cleanout and acid stimulation throughout the perforated Blinebry interval 5361'-5478'. Also, we may re-perforate the previously perforated and currently cement squeezed Upper Blinebry interval 5149'-5333' during this cleanout operation. We plan to do this work in the 1st quarter of 2017, pending improved oil

We were unsuccessful in cleaning this well out on 01/16/2015 using coiled tubing and subsequently attempted to make a simple bit run cleanout on tubing on 04/01/2015. From this work we realized a more extensive cleanout procedure will be required and we TA'ed this well on 04/02/2015 by setting

a CIBP at 5082' using wireline and cappi	ng with 35' of cement usi	ng wireline dump bailer.	
Releaded - submit as	1001 fro	TH exensión	give fineframe.
F	Submission #336094 veri or LEGACY RESERVES OF	fied by the BLM Well Information System ERATING LP, sent to the Hobbs INFER SANCHEZ on 04/18/2016 (16DLM0508S	SE)
Name (Printed/Typed) LAURA PINA		Title REGULATORY TECH	
Signature (Electronic Submission)		Date 04/08/2016	
, / / тні	S SPACE FOR FEDE	RALOR STATE OFFICE USE	
Approved By onditions of approval, if any, are attached. Approval or tify that the applicant holds legal or equitable title to			Date

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.


** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **



Additional data for EC transaction #336094 that would not fit on the form

32. Additional remarks, continued

Current low oil prices make extensive remedial work on this injection well uneconomical to perform at the present time.



WELLBORE SCHEMATIC

