Submit I Copy To Appropriate Distriction State of New Mer	Form C-103
District 1 – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II - (575) 748-1283 811 S. First St., Artesia, NM 88210	DIVISION 30-025-31429
District 111 - (505) 334-6178 1000 Rio Brazos Rd. Aztec. NM 87410	cis Dr. STATE STATE FEE
District IV - (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLU DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR PROPOSALS.)	G BACK TO A SUCH 7. Lease Name or Unit Agreement Name South Hobbs (G/SA) Unit
1. Type of Well: Oil Well Gas Well Other: Injector	8. Well Number: 236
2. Name of Operator Occidental Permian Ltd.	9. OGRID Number: 157984
3. Address of Operator	10. Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX 79323	
Unit Letter K : 1403 feet from the South line	and 1746 feet from the West line
Section 4 Township 19S	Range 38E NMPM Lea County
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
3019 KB	
12. Check Appropriate Box to Indicate Na	ture of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PULL OR ALTER CASING MULTIPLE COMPL	CASING/CEMENT JOB
OTHER:	OTHER:
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.</li> </ol>	
1 MIDII Dulling Unit	
2. Mill through BPs and test casing	During this procedure we plan to use
3. Cement squeeze existing perfs 4089'-4208' the closed-loop system with a steel the closed-loop system with a steel the closed-loop system with a steel	
<ol> <li>Do cement to shoe, test squeeze noies, re-squeeze if necessary</li> <li>Deepen well open hole from shoe @ 4294' to 5200'</li> <li>disposal per ODC Rule 19.15.17</li> </ol>	
6. Log open hole section	
7. RIH with liner and cement liner in open hole. Top of liner to be set above 4089' (above previously squeezed perforations).	
<ol> <li>Based on logging results, selectively perforate liner 4294'-5200'</li> </ol>	
9. Acid treat new perforations.	
11. Return well to production.	
12.	
Spud Date: Rig Release Date:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
stel alle	
SIGNATURE / Mill Mile TITLE Ind En DATE 4/29/16	
Type or print name Rick Reeves E-mail address rick reeves@oxy.com PHONE: 713-215-7653	
APPROVED BY: Jakus Shown THE Dist. Superisonate 5/3/2011	
Conditions of Approval (if any)	

MAY 0 3 2016

MB



## SHU 236 Current Wellbore Diagram (as of April-2016)



Squeezed Below CICR: 4214'-64'

TD - 4,294' (driller)

PBTD ~ Current: 4210' (top of CICR)

4,291' (original)