	ES NMOCD INTERIOR Hobbs		bs	FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010 5. Lease Serial No.				
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.					LC065151 6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRIPLICATE – Other instructions on page 2. 1. Type of Well Gas Well Other 2. Name of Operator Horseshoe Operating, Inc. Other					7. If Unit of CA/Agreement, Name and/or No. NM71117 (14-08-0001-7330) 8. Well Name and No. McDermott Federal #2			
					3a. Address 110 W. Louisiana Ste 200 Midland, TX 79701		3b. Phone No. (include area code) 432-683-1448	
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Descript 660' FSL & 1980' FWL N Sec19-T09S-R38E		on)			11. Country or Parish, State Lea, NM			
12. CHI	ECK THE APPROPRIATE B	OX(ES) TO INDICA	TE NATURE O	F NOTICE, I	REPORT OR OTH	ER DATA		
TYPE OF SUBMISSION TYPE OF AG					TION			
Notice of Intent	Acidize	Deepen Fracture 1		Production (Start/Resume) Water Shut-Off Reclamation Well Integrity Recomplete Other			1.1	
Subsequent Report	Change Plans	Plug and Plug Back	Abandon	Temporarily Abandon Water Disposal				
	H	OBBS O MAY 1 9 201 RECEIVI	6 5		ITACHEI	D FOR F APPROVAL		
 14. I hereby certify that the foregoing is 	true and correct.)	A	\sum	
Name (Printed/Typed) olby Welch Title Revenue/Prod				roduction Ad	countant		1	
Signature all	Wlch	Dat	.,	201	SPROVE			
()	THIS SPACE	FOR FEDERA	L OR STAT	E OFFIC	EUSE			
Approved by Conditions of approval, if any, are attach that the applicant holds legal or equitable			Title Office	BUKEAK	AY 13 201	Sate MI	M	
entitle the applicant to conduct operation Title 18 U.S.C. Section 1001 and Title 4 fictitious or fraudulent statements or rep	3 U.S.C. Section 1212, make it		knowingly and w	villfully to ma	SBAD FIELD OF	t or agency of the United State	es any false	
(Instructions on page 2)	2. 11 4 1	for Record O	mly 120	16		V		

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Approved for a period of 12 months ending 05/13/2017 subject to conditions of approval.

Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.

a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging. CIBP must be capped with minimum 25 sacks cement, placed with tubing, or 35 feet of cement if placed with bailer.

b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. Any leak-off will be evaluated.

c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.

d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.

e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.

3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned. 43 CFR 3162.3-4 (a) The operator shall promptly plug and abandon...wells in which oil or gas is not encountered in paying quantities...

Wells that successfully pass the casing integrity test **may** be approved for Temporary Abandonment (TA) status provided that the operator:

- 1. Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval <u>with well bore diagram</u> with all perforations and CIBP's and tops of cement on CIBP's.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

McDermott Federal 2

- 1. Well is approved to be TA/SI for a period of 12 months or until 05/13/2017
- 2. This will be the last TA approval for this well.
- 3. Must submit NOI to recomplete or NOI to P&A. Must be submitted by 05/13/2017
- 4. COA's met at this time.