

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised August 1, 2011

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-22943	✓
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>	✓
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name Royalty Holding	✓
8. Well Number 4	✓
9. OGRID Number 149972	✓
10. Pool name or Wildcat Undesignated SAN ANDRES	✓

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)
1. Type of Well: Oil Well ☐ Gas Well ☒ Other SWD

2. Name of Operator
Sundance Services Inc.

3. Address of Operator
P.O. Box 1737 Eunice, NM. 88231

4. Well Location
Unit Letter A : 660 feet from the North line and 660 feet from the East line
Section 25 Township 21-S Range 37-E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO
PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
DOWNHOLE COMMINGLE ☐
OTHER: ☐
INT TO PA
P&A NR Pm x
P&A R

SUBSEQUENT REPORT OF:
REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☒
CASING/CEMENT JOB ☐
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

6-15-15 Notify NMOCD of R/U and intent to Plug. Attempt to release AD1 packer. Not able to release. 6-16-15 NOTIFY Mark Whitaker NMOCD of stuck packer. He approved squeeze below packer and WOC. Squeeze 140 sacks Class C 4950'-4050'. WOC. Test plug 1000 PSI for 15 minutes. Back off safety joint. POH 1 joint then run back in hole and tag packer. POH L/D production tubing. 6-17-15 TIH AD1 packer. Tag @ 3818'. L/D excess. Spot 30 sacks Class C 2781'-2567'. WOC Tag plug @ 2550'. L/D Excess. Set Packer @ 1099'. Perforate @ 1670'. Establish rate 1 BPM @ 750 PSI. Attempt to squeeze 75 sacks Class C. Perforations locked up on displacement. RIH to 1720'. Reverse clean. POH to 1500'. 6-18-15 Talk W/ Mark Whitaker NMOCD. TIH to 1720'. Spot 30 sacks Class C 1720'-1537'. WOC. Tag plug @ 1548'. Set packer @ 439'. Perforate @ 916'. Attempt to establish rate. Pressured up. No rate. Notify Mark Whitaker NMOCD. Spot 30 sacks Class C 966'-783'. POH WOC overnight. 6-19-15 Tag plug @ 770'. L/D excess. Perforate @ 250'. Attempt to establish rate. No rate. Notify Mark Whitaker NMOCD. Spot 50 sacks Class C 300'- Surface. POH top off.

Spud Date: Rig Release Date:
Approved for Plugging of wellbore only. Liability under bond is retained pending restoration and completion of the C-103, Specific for Subsequent Report of Well Plugging, which may be found on the OCD web page under forms.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terry McBeth TITLE Service Coordinator DATE 6-30-16
Type or print name Terry McBeth E-mail address: tmcbeth@keyenergy.com PHONE: 432-523-5155
For State Use Only
APPROVED BY: Mark Whitaker TITLE P.E.S. DATE 7/5/2016
Conditions of Approval (if any):

MW