Do not use the abandoned we	is form for proposals to II. Use form 3160-3 (AP	drill or to re D) for such p	-enter an proposa <mark>ls</mark> O E	BS O	Conf India	an, Allottee or Tri	be Name
SUBMIT IN TRI	PLICATE - Other instruc	ctions on rev	verse side. JUN	3 0 201	7. If Unit	or CA/Agreemen	t, Name and
 Type of Well Oil Well Gas Well Oth 	ner		DE	CEIVE		ame and No. RA RIDGE 25 F	ED 1
2. Name of Operator EOG RESOURCES INCORPO	Contact:	STAN WAG	VER	/	9. API We 30-02	ell No. 5-28533-00-S	2
3a. Address		3b. Phone No. Ph: 432-68	o. (include area code 36-3689)		and Pool, or Expl HILLS	oratory
MIDLAND, TX 79702							
4. Location of Well (Footage, Sec., 7		n)		/		ty or Parish, and S	State
Sec 25 T24S R33E NWSW 19	980FSL 660FWL			V	LEAC	COUNTY, NM	
12. CHECK APPI	ROPRIATE BOX(ES) TO	O INDICATE	ENATURE OF	NOTICE, R	EPORT, C	OR OTHER D	ATA
TYPE OF SUBMISSION			TYPE O	F ACTION			
□ Notice of Intent	Acidize	Dee	epen	D Produc	tion (Start	INT TO F	Δ
-	Alter Casing	🗖 Fra	cture Treat	Reclar	nation	P&A NR	
Subsequent Report	Casing Repair	Nev	w Construction	Recon	plete	P&A R	-
Final Abandonment Notice	Change Plans	🛛 Plu	Plug and Abandon 🔲 Tem		rarily Aba	· art rt_	11.
If the proposal is to deepen directions Attach the Bond under which the woi following completion of the involved testing has been completed. Final At determined that the site is ready for fi 4/25/16 MIRU to P&A. 4/26/16 Hot oil to pull tubing a 4/27/16 Finish POOH w/ tubin	ally or recomplete horizontally, rk will be performed or provide l operations. If the operation re bandonment Notices shall be fil inal inspection.) and rods. ho and rods. RIH and tag	, give subsurface e the Bond No. o esults in a multip led only after all	locations and measure n file with BLM/BL le completion or rec requirements, includ	A. Required so ompletion in a ling reclamati Accepte Liability	ertical depths ubsequent rep new interval on, have been d as to plu under boy	s of all pertinent r ports shall be filed , a Form 3160-4 s a completed, and t	markers and within 30 shall be file the operator
If the proposal is to deepen directions Attach the Bond under which the wor following completion of the involved testing has been completed. Final At determined that the site is ready for final 4/25/16 MIRU to P&A.	ally or recomplete horizontally, rk will be performed or provide l operations. If the operation re oandonment Notices shall be fil inal inspection.) and rods. ng and rods. RIH and tag 11760' to 11644'. t 10000'. Pressure test ca 9800'. PUH to 9250'. ug from 9250' to 9060'. casing at 6550'. l set at 6240'. Squeeze 48 tte at 5320'. RIH w/ 7" par	, give subsurface e the Bond No. o esults in a multip led only after all at 11760'. Jo asing to 500 p 5 sx Class C cker and set a	Incations and measure In file with BLM/BL le completion or rec requirements, include In Staton - BLM psi. Test good. S cement. Unset p at 4791', Attemp	A. Required so ompletion in a ling reclamati Accepte Liability withersee pot 35 sx C acker and r ted to	retrical depths absequent rep new interval on, have been d as to plu under boy spaces ion lass	s of all pertinent norts shall be filed borts shall be filed i, a Form 3160-4 s in completed, and the incompleted, and the incompleted of the is completed	narkers and l within 30 i shall be file the operator well bore until
If the proposal is to deepen direction: Attach the Bond under which the woi following completion of the involved testing has been completed. Final At determined that the site is ready for fi 4/25/16 MIRU to P&A. 4/26/16 Hot oil to pull tubing a 4/27/16 Finish POOH w/ tubin sx Class H cement plug from 4/28/16 RIH w/ 7" CIBP set at H cement plug from 10000' to Spot 35 sx Class H cement plu 4/29/16 RIH and perforate 7" 5/02/16 RIH and perforate 7" 5/02/16 RIH and perforate establish rate. Well communic 5/03/16 Spot 60 sx Class C co	ally or recomplete horizontally, rk will be performed or provide l operations. If the operation re sandonment Notices shall be fil inal inspection.) and rods. ng and rods. RIH and tag 11760' to 11644'. t 10000'. Pressure test ca 9800'. PUH to 9250'. ug from 9250' to 9060'. casing at 6550'. l set at 6240'. Squeeze 44 te at 5320'. RIH w/ 7" par ated up 2-7/8" X 7". Unal ement plug from 5370' to true and correct. Electronic Submission # For EOG RESOU mitted to AFMSS for proce	, give subsurface e the Bond No. o esults in a multip led only after all at 11760'. Jo asing to 500 p 5 sx Class C cker and set a ble to pump ir 5 5000'. WOC	Incations and measin n file with BLM/BL/ le completion or rec requirements, include on Staton - BLM we bai. Test good. S cement. Unset p at 4791'. Attemp to perfs. POOH 4 hrs. RIH and t d by the BLM We PORATED, sent SCILLA PEREZ of	A Required so ompletion in a ling reclamati Accepte Liability withoussed? pot 35 sx C acker and r ted to w/ packer. ag TOC at Il Informatic to the Hobb n 06/01/2016	retrical depths absequent rep new interval on, have been d as to plu under bor spaces ion lass hove up 5026'.RE DU	s of all pertinent r ports shall be filed , a Form 3160-4 s a completed, and the respire of the rad is retained is completed is completed	narkers and l within 30 shall be file the operator well bore untri
Attach the Bond under which the wor following completion of the involved testing has been completed. Final AH determined that the site is ready for fi 4/25/16 MIRU to P&A. 4/26/16 Hot oil to pull tubing a 4/27/16 Finish POOH w/ tubin sx Class H cement plug from 10000' to Spot 35 sx Class H cement plu 4/28/16 RIH w/ 7" CIBP set at H cement plug from 10000' to Spot 35 sx Class H cement plu 4/29/16 RIH and perforate 7" 5/02/16 RIH w/ 7" packer and hole to 4854'. RIH and perfora establish rate. Well communic 5/03/16 Spot 60 sx Class C co 14. I hereby certify that the foregoing is Name (<i>Printed/Typed</i>) STAN WA	ally or recomplete horizontally, rk will be performed or provide l operations. If the operation re sandonment Notices shall be fil inal inspection.) and rods. ng and rods. RIH and tag 11760' to 11644'. t 10000'. Pressure test ca 9800'. PUH to 9250'. ug from 9250' to 9060'. casing at 6550'. l set at 6240'. Squeeze 4! te at 5320'. RIH w/ 7" par ated up 2-7/8" X 7". Unal ement plug from 5370' to true and correct. Electronic Submission # For EOG RESOL mitted to AFMSS for proce GNER	, give subsurface e the Bond No. o esults in a multip led only after all at 11760'. Jo asing to 500 p 5 sx Class C cker and set a ble to pump ir 5 5000'. WOC	Incations and measu n file with BLM/BL/ le completion or rec requirements, include an Staton - BLM we be the state of the state of the state cement. Unset p at 4791'. Attemp to perfs. POOH 4 hrs. RIH and t d by the BLM We PORATED, sent SCILLA PEREZ of Title REGUL	A. Required so ompletion in a ling reclamati Accepte Liability withoussed? pot 35 sx C acker and r ted to w/ packer. ag TOC at II Informatic to the Hobb n 06/01/2016 ATORY AN	retrical depths absequent rep new interval on, have been d as to plu under bor spaces ion lass hove up 5026'.RE DU	s of all pertinent r ports shall be filed , a Form 3160-4 s a completed, and the respire of the rad is retained is completed is completed	narkers and l within 30 shall be file the operator well bore until
If the proposal is to deepen direction: Attach the Bond under which the woi following completion of the involved testing has been completed. Final At determined that the site is ready for fi 4/25/16 MIRU to P&A. 4/26/16 Hot oil to pull tubing a 4/27/16 Finish POOH w/ tubin sx Class H cement plug from 4/28/16 RIH w/ 7" CIBP set at H cement plug from 10000' to Spot 35 sx Class H cement plu 4/29/16 RIH and perforate 7" 5/02/16 RIH and perforate 7" 5/02/16 RIH and perforate establish rate. Well communic 5/03/16 Spot 60 sx Class C co	ally or recomplete horizontally, rk will be performed or provide l operations. If the operation re nandonment Notices shall be fil inal inspection.) and rods. ng and rods. RIH and tag 11760' to 11644'. t 10000'. Pressure test ca 9800'. PUH to 9250'. ug from 9250' to 9060'. casing at 6550'. l set at 6240'. Squeeze 44 ite at 5320'. RIH w/ 7" par ated up 2-7/8" X 7". Unal ement plug from 5370' to true and correct. Electronic Submission # For EOG RESOL mitted to AFMSS for proce GNER	, give subsurface e the Bond No. o essults in a multip led only after all at 11760'. Jo asing to 500 p 5 sx Class C cker and set a ble to pump in 5 5000'. WOC	Incations and measu n file with BLM/BL le completion or rec requirements, include an Staton - BLM we pat 4791'. Attemp to perfs. POOH 4 hrs. RIH and t d by the BLM We PORATED, sent SCILLA PEREZ of Title REGUL Date 05/18/2	A. Required so ompletion in a ling reclamati Accepte Liability withoussed? pot 35 sx C acker and r ted to w/ packer. ag TOC at II Informatic to the Hobb n 06/01/2016 ATORY AN	retrical depths absequent rep new interval on, have been d as to plu under bor space 25 iou lass nove up 5026'.RE DU n System s (16CRW00 IALYST	s of all pertinent r ports shall be filed , a Form 3160-4 s a completed, and the respire of the rad is retained is completed is completed	narkers and l within 30 shall be file the operator well bore until
If the proposal is to deepen direction: Attach the Bond under which the wor following completion of the involved testing has been completed. Final At determined that the site is ready for final 4/25/16 MIRU to P&A. 4/26/16 Hot oil to pull tubing at 4/27/16 Finish POOH w/ tubin sx Class H cement plug from 4/28/16 RIH w/ 7" CIBP set at H cement plug from 10000' to Spot 35 sx Class H cement plu 4/29/16 RIH and perforate 7" 5/02/16 RIH w/ 7" packer and hole to 4854'. RIH and perfora establish rate. Well communic 5/03/16 Spot 60 sx Class C com 14. I hereby certify that the foregoing is Name (<i>Printed/Typed</i>) STAN WA	ally or recomplete horizontally, rk will be performed or provide l operations. If the operation re sandonment Notices shall be fil inal inspection.) and rods. ng and rods. RIH and tag 11760' to 11644'. t 10000'. Pressure test ca 9800'. PUH to 9250'. ug from 9250' to 9060'. casing at 6550'. l set at 6240'. Squeeze 4! te at 5320'. RIH w/ 7" par ated up 2-7/8" X 7". Unal ement plug from 5370' to true and correct. Electronic Submission # For EOG RESOL mitted to AFMSS for proce GNER	, give subsurface e the Bond No. o essults in a multip led only after all at 11760'. Jo asing to 500 p 5 sx Class C cker and set a ble to pump in 5 5000'. WOC	Incations and measu n file with BLM/BL le completion or rec requirements, include an Staton - BLM we pat 4791'. Attemp to perfs. POOH 4 hrs. RIH and t d by the BLM We PORATED, sent SCILLA PEREZ of Title REGUL Date 05/18/2	A. Required so ompletion in a ling reclamati Accepte Liability withoussed? pot 35 sx C acker and r ted to w/ packer. ag TOC at II Informatic to the Hobb n 06/01/2016 ATORY AN	retrical depths absequent rep new interval on, have been d as to plu under bor space 25 iou lass nove up 5026'.RE DU n System s (16CRW00 IALYST	s of all pertinent r ports shall be filed , a Form 3160-4 s a completed, and the respire of the rad is retained is completed is completed	narkers and l within 30 i shall be file the operator well bore until
If the proposal is to deepen direction: Attach the Bond under which the woi following completion of the involved testing has been completed. Final At determined that the site is ready for fi 4/25/16 MIRU to P&A. 4/26/16 Hot oil to pull tubing a 4/27/16 Finish POOH w/ tubin sx Class H cement plug from 1 4/28/16 RIH w/ 7" CIBP set at H cement plug from 10000' to Spot 35 sx Class H cement plu 4/29/16 RIH and perforate 7" 5/02/16 RIH w/ 7" packer and hole to 4854'. RIH and perfora establish rate. Well communic 5/03/16 Spot 60 sx Class C co 14. I hereby certify that the foregoing is Com Name (<i>Printed/Typed</i>) STAN WA Signature (Electronic S	ally or recomplete horizontally, rk will be performed or provide loperations. If the operation re bandonment Notices shall be fil inal inspection.) and rods. Ing and rods. RIH and tag 11760' to 11644'. t 10000'. Pressure test ca 9800'. PUH to 9250'. ug from 9250' to 9060'. casing at 6550'. set at 6240'. Squeeze 4! te at 5320'. RIH w/ 7" parated up 2-7/8" X 7". Unal ement plug from 5370' to true and correct. Electronic Submission # For EOG RESOL mitted to AFMSS for proce GNER Submission)	, give subsurface e the Bond No. o ssults in a multip led only after all at 11760'. Jo asing to 500 p 5 sx Class C cker and set a ble to pump ir 5000'. WOC	Incations and measu n file with BLM/BL le completion or rec requirements, include an Staton - BLM we pat 4791'. Attemp to perfs. POOH 4 hrs. RIH and t d by the BLM We PORATED, sent SCILLA PEREZ of Title REGUL Date 05/18/2	A. Required so ompletion in a ling reclamati Accepte Liability withoussed? pot 35 sx C acker and r ted to w/ packer. ag TOC at II Informatic to the Hobb n 06/01/2016 ATORY AN	retrical depths absequent rep new interval on, have been d as to plu under bor space 25 iou lass nove up 5026'.RE DU n System s (16CRW00 IALYST	s of all pertinent r ports shall be filed , a Form 3160-4 s a completed, and the rest of the filed is completed, and the rest of the filed is completed is completed CLAMA E_U/5/1	narkers and l within 30 shall be file the operator well bore untri
If the proposal is to deepen direction: Attach the Bond under which the woi following completion of the involved testing has been completed. Final At determined that the site is ready for fi 4/25/16 MIRU to P&A. 4/26/16 Hot oil to pull tubing a 4/27/16 Finish POOH w/ tubin sx Class H cement plug from 4/28/16 RIH w/ 7" CIBP set at H cement plug from 10000' to Spot 35 sx Class H cement plu 4/29/16 RIH and perforate 7" 5/02/16 RIH w/ 7" packer and hole to 4854'. RIH and perfora establish rate. Well communic 5/03/16 Spot 60 sx Class C co 14. I hereby certify that the foregoing is Name (<i>Printed/Typed</i>) STAN WA Signature (Electronic S	ally or recomplete horizontally, rk will be performed or provide l operations. If the operation re andonment Notices shall be fil inal inspection.) and rods. ng and rods. RIH and tag 11760' to 11644'. t 10000'. Pressure test ca 9800'. PUH to 9250'. ug from 9250' to 9060'. casing at 6550'. l set at 6240'. Squeeze 44 ite at 5320'. RIH w/ 7" parated up 2-7/8" X 7". Unal ement plug from 5370' to true and correct. Electronic Submission # For EOG RESOL mitted to AFMSS for proce GNER Submission) THIS SPACE FC	, give subsurface e the Bond No. o essults in a multip led only after all at 11760'. Jo asing to 500 p 5 sx Class C cker and set a ble to pump in 5000'. WOC	In cations and meass in file with BLM/BL le completion or rec requirements, include in Staton - BLM in osi. Test good. S cement. Unset p at 4791'. Attemp to perfs. POOH 4 hrs. RIH and t d by the BLM We PORATED, sent SCILLA PEREZ or Title REGUL Date 05/18/2	A. Required so ompletion in a ling reclamati Accepte Liability withoussed? pot 35 sx C acker and r ted to w/ packer. ag TOC at II Informatic to the Hobb n 06/01/2016 ATORY AN	retrical depths absequent rep new interval on, have been d as to plu under bor space 25 iou lass nove up 5026'.RE DU n System s (16CRW00 IALYST	s of all pertinent r ports shall be filed , a Form 3160-4 s a completed, and the respire of the rad is retained is completed is completed	narkers and l within 30 shall be file the operator well bore until

Additional data for EC transaction #339618 that would not fit on the form

32. Additional remarks, continued

POOH. RIH and perforate at 3200'. RIH w/ 7" packer set at 2902'. Pressure to 800 psi to establish rate. POOH w/ packer. Spot 30 sx Class C cement plug from 3250' to 3120'. 5/04/16 RIH and tag TOC at 3107'. Jon Staton - BLM witnessed. POOH. RIH and perforate at 1806'. Set 7" packer at 1512'. Pressure to 800 psi. POOH w/ packer. Spot 30 sx Class C cement plug from 1856' to 1676'. WOC 4 hrs. RIH and tag TOC at 1687'. Jon Staton - BLM witnessed. RIH and perforate at 1500'. RIH and set packer at 1260'. Pressure to 800 psi to establish rate. Squeezed 45 sx Class C cement.

5/05/16 POOH w/ packer. RIH and tag TOC at 1386'. RIH and perforate at 660'. RIH and set 7" packer at 441'. Pressure test to 1000 psi. POOH w/ packer.

Spot 30 sx Class C cement plug from 710' to 526'. WOC 4 hrs. RIH and tag TOC at 498'. BLM witnessed. RIH and perforate at 100'. Set packer and pressure to 1000 psi. POOH w/ packer. BLM witnessed. Fill casing from 153' to surface w/ 30 sx Class C cement. 5/17/16 Cut off wellhead and install P&A marker.