HOBBS OCD JUL 112016

Submit One Copy To Appropriate District Office	State of New Mexico		
1625 N. French Dr., Hobbs, NM 88240 District II	N. French Dr., Hobbs, NM 88240		$\begin{array}{r} \text{Revised November 3, 2011} \\ \hline \text{WELL API NO.} \\ \hline \textbf{30-025-11580} \end{array}$
Bill S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION District III 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410 1220 South St. Francis Dr. District IV Santa Fe, NM 87505 1220 S. St. Francis Dr., Santa Fe, NM Santa Fe, NM 87505			5. Indicate Type of Lease
			STATE FEE
			6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			LAnglie MATTIX Queen Unit
1. Type of Well: Oil Well Gas Well AOther			8. Well Number 13
2. Name of Operator LINN OPERAting LLC			9. OGRID Number 9324
3. Address of Operator			10. Pool name or Wildcat
600 TRAVIS, STE SIDD, HUNSTON, TX 7022			LA TRUETLQUEEN UNIX
4. Well Location			
Unit Letter : le le feet from the N line and SD feet from the W line			
Section <u>14</u> Township <u>255</u> Range <u>375</u> NMPM County <u>264</u> 11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
JIIS BR			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTI	ON TO:	SUE	SEQUENT REPORT OF:
ERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR			
EMPORARILY ABANDON CHANGE PLANS COMMENCE DE			RILLING OPNS. PANDA
PULL OR ALTER CASING MULTI		CASING/CEMEN	
OTHER:		Location is	ready for OCD inspection after P&A
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.			
 Bat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the 			
A steel market at least 4 in diameter and at least 4 above ground level has been set in concrete. It shows the			
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR			
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.			
FERMANENTLI STAMFED ON THE MARKER'S SURFACE.			
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and			
other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.			
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with			
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed			
from lease and well location.			
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)			
All other environmental concerns have been addressed as per OCD rules.			
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-			
retrieved flow lines and pipelines.			
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well location, except for utility's distribution infrastructure.			
When all work has been completed, return this form to the appropriate District office to schedule an inspection.			
SIGNATURE Kick Kickman	TITLE	Ron. Foren	DATE 2-29.16
TYPE OR PRINT NAME	E-MAIL:		PHONE:
For State Use Only	LL TITLE	P.E.S.	DATE 7/21/2016

1