

## H<sub>2</sub>S Contingency Plan

H<sub>2</sub>S Contingency Plan Holders:

Attached is an H<sub>2</sub>S Contingency Plan for COPC Permian Drilling working in the West Texas and Southeastern New Mexico areas operated by ConocoPhillips Company.

If you have any questions regarding this plan, please call Jet Brown at ConocoPhillips Company, 432.688.6849.

## **Table of Contents**

## **Section**

- I. Purpose
- II. Scope
- III. Procedures
- IV. Emergency Equipment and Maintenance

Emergency Equipment Suppliers General Information H2S Safety Equipment and Monitoring Systems

- V. Emergency Call List
- VI. Public/Media Relations
- VII. Public Notification/Evacuation
- VIII. Forms/Reports



# HYDROGEN SULFIDE (H<sub>2</sub>S) OPERATIONS

Contingency Plan
For
Permian Drilling Operations

ConocoPhillips Company Mid-Continent Business Unit Permian Asset Area

#### I. PURPOSE

The purpose of this Contingency Plan is to provide an organized plan of action for alerting and protecting the public following the release of a potentially hazardous volume of hydrogen sulfide. This plan prescribes mandatory safety procedures to be followed in the event of a release of  $H_2S$  into the atmosphere from exploration and production operations included in the scope of this plan. The extent of action taken will be determined by the supervisor and will depend on the severity and extent of the  $H_2S$  release. Release of  $H_2S$  must be reported to the Drilling Superintendent and documented on the IADC report and in Wellview.

#### II. SCOPE

This Contingency plan shall cover the West Texas and Southeastern New Mexico areas, which contain H2S gas and could result in a release in which the 100 ppm radius of exposure is greater than 50' yet less than 3000' and does not include a public area, and in which the 500 ppm radius of exposure does not include a public road. Radius of exposure is defined as the maximum distance from the source of release that a specified calculated average concentration of H<sub>2</sub>S could exist under specific weather conditions.

# III. PROCEDURES

First Employee on Scene
Assess the incident and ensure your own safety.
Note the following:
<ul> <li>Location of the incident.</li> <li>Nature of the incident.</li> <li>Wind direction and weather conditions.</li> <li>Other assistance that may be needed.</li> </ul>
Call local supervisory personnel (refer to Section V: Emergency Call List) unpersonal contact is made with a person on the list.
Perform emergency assessment and response as needed. The response mainclude rescue and/or evacuation of personnel, shutting in a system and/onotification of nearby residents/public (refer to Section VII: Publi Notification/Evacuation).
Secure the site.
Follow the direction of the On-scene Incident Commander (first ConocoPhillip supervisor arriving on-scene).
First Supervisor on Scene (ConocoPhillips On-scene Incident Commander)
—— Becomes ConocoPhillips' On-scene Incident Commander upon arrival location.
—— Follow the principles of the <b>D.E.C.I.D.E.</b> process below to assess the incident. (Note wind direction and weather conditions and ensure everyone's safety).
DETECT the problem ESTIMATE likely harm without intervention CHOOSE response objectives IDENTIFY action options DO the best option EVALUATE the progress
Complete the Preliminary Emergency Information Sheet (refer to Section VIII: Forms/Reports).
Call your supervisor (refer to Section V: Emergency Call List).

Perform emergevacuation of a Public Notification personnel or or obtaining any Emergency Equation 1.	all pers ation/E utside a safety e	onnel and/ vacuation) agencies (requipment	or nead, requested that m	rby residently residen	idents/ ssistan n V: E	public ce fron merger	(refer to a Conocicy Call	o Secti coPhil l List)	ion VII: llips and
 Notify appropriation Also notify the Call List).									
 Ensure site sec	curity.								
	s of exp	nd /or war posure (RC uitor and a	DE). A	all man					
— Set roadb	olocks a	nd staging	area a	as deter	mined.				
 Establish the In response perso			l Struc	cture by	design	nating a	appropr	iate or	n-scene
Recording Sec. Public Informa Safety/Medica Decontaminati	ation Of	er							
 Have the "Rece Log" (refer to					enting	the inc	ident o	n the '	"Incident
 If needed, requ that, until furth communication	er notic	ce, the cha							stating
 Perform a Site	Charac	terization	and de	signate	the fo	llowing	g:		
Hot Zone Warm Zone Cold Zone	 	Hazardou Preparatio Safe Area	n & D		minatio	on Area	ı		

# AND

On-Scene Incident Command Post Public Relations Briefing Area Staging Area Triage Area Decontamination Area	(Cold Zone) (Cold Zone) (Cold Zone) (Cold Zone) (Warm Zone)				
 <ul> <li>Refer all media personnel to ConocoPhillips' On-Scene Public Information Officer (refer to Section VI: Public Media Relations).</li> </ul>					
 Coordinate the attempt to stop the release of H <sub>2</sub> S. You should consider closing upstream and downstream valves to shut-off gas supply sources, and/or plugging or clamping leaks. Igniting escaping gas to reduce the toxicity hazard should be used <b>ONLY AS A LAST RESORT</b> . (It must first be determined if the gas can be safely ignited, taking into consideration if there is a possibility of a widespread flammable atmosphere.)					
 Once the emergency is over, return the situation to normal by:					
Confirming the absence of H <sub>2</sub> S and combustible gas through	out the area,				
Discontinuing the radio silence on all channels, stating that the incident is over,	ne emergency				
Removing all barricades and warning signs,					
Allowing evacuees to return to the area, and					
Advising all parties previously notified that the emergency ha	as ended.				
 Ensure the proper regulatory authorities/agencies are notified of the to Section V: Emergency Call List).	incident (refer				
 Clean up the site. (Be sure all contractor crews have had appropriat HAZWOPER training.)	e				
Report completion of the cleanup to the Asset Environmentalist. (Environmentalist will report this to the proper State and/or Federal	agencies.)				

Fill out all required incident reports and send originals to the Safety Department. (Keep a copy for your records.) • Company employee receiving occupational injury or illnesses. • Company employee involved in a vehicle accident while driving a company vehicle. • Company property that is damaged or lost. Accident involving the public or a contractor; includes personal injuries, vehicle accidents, and property damage. Also includes any situation which could result in a claim against the Company. Hazardous Material Spill/Release Report Form Emergency Drill Report Assist the Safety Department in the investigation of the incident. Review the factors that caused or allowed the incident to occur, and modify operating, maintenance, and/or surveillance procedures as needed. Make appropriate repairs and train or retrain employees in the use and operation of the system. If this incident was simulated for practice in emergency response, complete the Emergency Drill Report found in Section VIII: Forms/Reports and submit a copy to the Drilling Manager. (Keep one copy in area files to document exercising of the plan.)

# **Emergency Procedures Responsibility**

In the event of a release of potentially hazardous amounts of H2S, all personnel will immediately proceed upwind/ crosswind to the nearest designated briefing area. The COPC Drilling Rep. will immediately, upon assessing the situation, set this into action by taking the proper procedures to contain the gas and notify appropriate people and agencies.

- 1. In an emergency situation, the Drilling Rep. on duty will have complete responsibility and will take whatever action is deemed necessary to ensure the personnel's safety, to protect the well, and to prevent property damage.
- 2. The Toolpusher will assume all responsibilities of the Drilling Rep. in an emergency situation in which the Drilling Rep. becomes incapacitated.
- 3. Advise each contractor, service company, and all others entering the site that H2S may be encountered and of the potential hazards that may exist.
- 4. Authorize the evacuation of local residents if H2S threatens their safety.
- 5. Keep the number of persons on location to a minimum during hazardous operations.
- 6. Direct corrective actions to control the flow of gas.
- 7. The COPC Drilling Rep. has full responsibility for igniting escaping gas to reduce the toxicity hazard. This should be used **ONLY AS A LAST RESORT**.

# IV. EMERGENCY EQUIPMENT and MAINTENANCE

## **Emergency Equipment Suppliers**

#### DXP Safety International - Odessa, TX

H<sub>2</sub>S monitors Breathing air including cascade systems First aid and medical supplies Safety equipment H2S Specialist 432.580.3770

#### EnerSafe Inc. - Odessa, TX

H<sub>2</sub>S monitors (personal and fixed) Breathing air including cascade systems First aid and medical supplies Safety equipment 432.550.0600

#### Indian Fire & Safety - Hobbs, NM

H<sub>2</sub>S monitors Breathing air including cascade systems (trailer mounted) 30 minute air packs Safety Equipment 575.393.3093

#### **Emergency Equipment and Maintenance (continued)**

#### General Information

Materials used for repair should be suitable for use where H<sub>2</sub>S concentrations exceed 100 ppm. In general, carbon steels having low yield strengths and a hardness below RC-22 are suitable. The engineering staff should be consulted if any doubt exists on material specifications.

Appropriate signs should be maintained in good condition at location entrance and other locations as specified in Texas Rule 36 and NMOCD Rule 118.

All notification lists should be kept current with changes in names, telephone numbers, etc.

All shutdown devices, alarms, monitors, breathing air systems, etc., should be maintained in accordance with applicable regulations.

All personnel working in  $H_2S$  areas shall have received training on the hazards, characteristics, and properties of  $H_2S$ , and on procedures and safety equipment applicable for use in  $H_2S$  areas.

#### **H2S Safety Equipment and Monitoring Systems**

An H2S emergency response package will be maintained at locations requiring H2S monitoring. The package will contain at a minimum the following:

- 3 Fixed H2S sensors located as follows:
  - 1 -on the rig floor
  - 1 at the Bell Nipple
  - 1 at the Shale Shaker or Flowline
- 1 <u>Entrance Warning Sign</u> located at the main entrance to the location, with warning signs and colored flags to determine the current status for entry into the location.
- 2 Windsocks that are clearly visible.
- $1 \underline{\text{Audible}}$  warning system located on rig floor
- 2 <u>Visual</u> warning systems (Beacon Lights)
  - 1 located at the rig floor
  - 1 located in the mud mixing room

#### Note: All alarms (audible and visual) should be set to alarm at 10 ppm.

- 2 Briefing areas clearly marked
  - 2 SCBA's at each briefing area
  - 1- SCBA located at the Drilling Rep's office

#### Note:

- 1. All SCBA's must be positive pressure type only.
- 2. All SCBA's must be either Scott or Drager brand.
- 3. All SCBA's face pieces should be <u>size large</u>, unless otherwise specified by the Drilling Supervisor.
- 5 Emergency Escape Packs located at Top Doghouse.

Note: Ensure provisions are included for any personnel working above rig floor in derrick.

1 – <u>Tri or Quad gas monitor</u> located at the Drilling Rep's office. This will be used to determine if the work area is safe to re-enter prior to returning to work following any alarm.

# V. EMERGENCY CALL LIST:

The following is a priority list of personnel to contact in an emergency situation:

Supervisory Personnel	Office No.	Home	Cellular
Sam Hyden	432.688.9163	432.561.9958	432.557.1999
Permian Drilling Supt.			
Tim Garrett	432.688.9057		505.330.5638
Jerry Moore	432.688.9057		806.683.6852
Terry Brumley	432.688.6850		432.238.9069
Permian Drilling Field Supt.			
Jet Brown	432.688.6849		432.638.0509
WSER			
R.E. (Gene) True	432.688.9050	281.546.1034	281.217.8492
Operations Manager, Permian			
Conventional Asset			
Kyle O'Dell	432.688.9051		432.250.4912
Safety and Environmental Coordinator			
Gene Schwall	281.206.5159	281.579.2914	713.301.7590
Drilling Mngr.	1 1		

**EMERGENCY CALL LIST: State Officials** 

**Regulatory Agencies** 

**Texas Railroad Commission** 

512.463.6838

1701 N. Congress

24 Hour Emergency: 512.463.6788

Austin, TX 78701

**New Mexico Oil Conservation Commission** 

Office: 575.393.6161

P. O. Box 1980

Hobbs, New Mexico 88240-1980

**Bureau of Land Management** 

Carlsbad Field Office

Office: 575.234.5972

620 E. Greene St.

Fax: 575.885.9264

Carlsbad, NM 88220

BLM 24 Hr on call # Lea County: 575-393-3612

**EMERGENCY CALL LIST: Local Officials** 

Refer to the Location Information Sheet Note: The LIS should include any area residents (i.e. rancher's house, etc)

# ConocoPhillips Emergency Call List and Location Information Sheet

# ConocoPhillips- 281-293-3600

Drilling Superintendent	Sam Hyden	Office: 432-688-9163
		Cell: 432-557-1999
Safety (WSER)	Jet Brown	Office: 432-688-6849
		Cell: 432-638-0509
Drilling Engineer	Cord Denton	Office: 281-206-5406
		Cell: 832-754-7363
	Stephanie Basse	Office: 281-206-5239
		Cell: 832-231-1159
	Nancy Luo	Office: 281-206-5280
		Cell: 281-546-8154
Regulatory Contact	Susan Maunder	Office: 432-688-6913
		Cell: 432-269-4378

# **Emergency Numbers**

Hospital: Lea Co. Regional Medical Center (Hobbs)	575-492-5000
Ambulance: Hobbs Fire Dept.	575-397-9308
Air Ambulance: Care Star	888-624-3571
Aero Star	800-627-2376
Fire Dept. (Hobbs)	575-397-9308
(Maljamar non-emerg)	575-676-4100
State Police (Artesia)	
(Hobbs)	
Sheriff (Lovington)	
Police (Lovington)	
NMOCD	
(Emerg)	575-370-3186
BLM Switchboard	
BLM 24 Hr on Call, Lea County	575-393-3612
New Mexico Emergency Response Comm (Santa Fe)	
New Mexico State Emerg Ops Ctr	505-476-9635
National Emergency Response Center	800-424-8802

**Number of Residences within 1 mile of Well:** There are no residences within one mile of the well to be drilled.

#### VI. Public Media Relations

The **Public Information Officer** becomes the ConocoPhillips on-scene contact (once designated by the ConocoPhillips On-Scene Incident Commander).

The Public Information Officer confers with Houston Office's Human Relations Representative, who is responsible for assisting in the coordination of local public relations duties.

If you are the Public Information Officer, answer media questions honestly and <u>only with</u> <u>facts</u>, do not speculate about the cause, amount of damage, or the potential impact of the incident on the community, company, employees, or environment. (This information will be formally determined in the incident investigation.)

If you are not comfortable answering a question or if you are unsure of the answer, use terms such as the following:

- "I do not know. I will try to find out."
- I am not qualified to answer that question, but I will try to find someone who is."
- "It is under investigation."

#### Note:

Do Not Say "No Comment." (This implies a cover-up.)

**Do Not Disclose Names of Injured or Dead!** Confer with the Houston Office's Human Relations Representative, who is responsible for providing that information.

# VII. Public Notification/Evacuation

# Alert and/or Evacuate People within the Exposure Area

1. <u>Public Notification</u> – If the escape of gas could result in a hazard to area residents, the general public, or employees, the person <u>first</u> observing the leak should take <u>immediate</u> steps to cause notification of any nearby residents. The avoidance of injury or loss of life should be of prime consideration and given top priority in all cases. If the incident is of such magnitude, or at such location as to create a hazardous situation, local authorities will be requested to assist in the evacuation and roadblocks of the designated area until the situation can be returned to normal.

Note: Bilingual employees may be needed to assist in notification of residents.

2. Evacuation Procedures – Evacuation will proceed upwind from the source of the release of H<sub>2</sub>S. Extreme caution should be exercised in order to avoid any depressions or low-lying areas in the terrain. The public area within the radius of exposure should be evacuated in a southwesterly and southeasterly direction so as to avoid the prevailing southern wind direction.

Roadblocks and the staging area should be established as necessary for current wind conditions.

**Note:** In all situations, consideration should be given to wind direction and weather conditions. H<sub>2</sub>S is heavier than air and can settle in low spots. Shifts in wind direction can also change the location of possible hazardous areas.

# VIII. FORMS & REPORTS

- I. Incident Log
- II. Preliminary Emergency Information Sheet
- III. Emergency Drill Report
- IV. Onshore Hazardous Material Spill/Release Report Form
- V. Immediate Report of Occupational Injury or Illness Report of Accident-Public Contractor Report of Loss or Damage to Company Property Report of Automotive Incident

