HOBBS OUL AUG 1 0 2016 Form 3160-3 (March 2012) ECEIVED CONFI UNITED STATE DEPARTMENT OF THE BUREAU OF LAND MA APPLICATION FOR PERMIT TO	INTERIOR NAGEMENT	THOE ATIO	FORM OMB	APPROV No. 1004-01 October 31,	37 2014
1a. Type of work: DRILL REEN	TER		7. If Unit or CA Age NMNM088526X	reement, N	ame and No.
Ib. Type of Well: Oil Well Gas Well Other	Single Zone Mult	tiple Zone	8. Lease Name and Thistle Unit 122H	Well No. (3088	(4)
2. Name of Operator Devon Energy Production Company,	L.P. (6137)		9. API Well No. 30-025	- 43	3382
3a. Address 333 West Sheridan Avenue Oklahoma City, OK 73102-5010	3b. Phone No. (include area code) 405-552-7848		10. Field and Pool, or Triple X: Bone Spri	Explorato	
 Location of Well (Report location clearly and in accordance with At surface Unit B, Sec 21-T23S-R33E, 260' FNL 2375' FEI At proposed prod. zone Unit G, Sec 28-T23S-R33E, 2600' F 	PP: 930' FNL 2275' FEL		11. Sec., T. R. M. or SHL: Sec 21-T23S- BHL: Sec 28-T23S-	R33E	irvey or Area
 Distance in miles and direction from nearest town or post office* Approximately 15.7 miles SW of Eunice, NM 			12. County or Parish Lea		13. State NM
15. Distance from proposed* location to nearest property or lease line, ft. (Also to nearest drig, unit line, if any)	16. No. of acres in lease 960 Acres		ing Unit dedicated to this Acres	well	
 Distance from proposed location* to nearest well, drilling, completed, applied for, on this lease, ft. See attached map 	19. Proposed Depth TVD: 9,662' MD: 17,088'		M/BIA Bond No. on file D-1104; NMB-000801		
 Elevations (Show whether DF, KDB, RT, GL, etc.) 3726.5' GL 	22 Approximate date work will st 10/31/2016	tart*	23. Estimated duration 45 Days		
 Padded w/Thistle Unit 77H & Thistle Unit #107H The following, completed in accordance with the requirements of Onst 1. Well plat certified by a registered surveyor. 2. A Drilling Plan. 3. A Surface Use Plan (if the location is on National Forest System SUPO must be lined with the appropriate Forest Service Office). 25. Signature 	n Lands, the local data of the content of the conte	the operati). fication	this form: tons unless covered by a formation and/or plans a		
Title Regulatory Compliance Specialist					
Approved by (Signature)/S/George MacDonell	Name (Printed/Typed)			AUG	1 - 2016
FIELD MANAGER	Office	CA	ARLSBAD FIELD	OFFIC	E
Application approval does not warrant or certify that the applicant ho conduct operations thereon. Conditions of approval, if any, are attached.	lds legal or equitable title to those rig	ghts in the su	APPRO	entitle the	applicant to FOR TWO
				or agency	

Carlsbad Controlled Water Basin

08/10/16

SEE ATTACHED FOR CONDITIONS OF APPROVAL

Approval Subject to General Requirements & Special Stipulations Attached

Devon Energy, Thistle Unit 122H

1. Geologic Formations

TVD of target	9,662'	Pilot hole depth	N/A	
MD at TD:	17,088'	Deepest expected fresh water:	400'	

Basin

Depth (TVD)	Water/Mineral Bearing/	Hazards*
of the same particular the rest of the second s	Target Lone:	
4948		
5213		
6174		
8861		
9076	The Contract of the Contract o	
9178		
9637		
9975		
10220		
	from KB 1393 1650 4948 5213 6174 8861 9076 9178 9637 9975	from KB Target Zone? 1393 1650 1650 4948 5213 6174 8861 9076 9178 9637 9975 9975

*H2S, water flows, loss of circulation, abnormal pressures, etc.

2. Casing Program

Hole	Casin	g Interval	Csg.	Weight	Grade	Conn.	SF	SF	SF
Size	From	То	Size	(lbs)			Collap se	Burst	Tension
17.5"	0	1,450'	13.375"	54.5	J-55	BTC	1.64	3.68	10.73
12.25"	0	4,300'	9.625"	40	J-55	BTC	1.15	3.43	4.69
	4,300'	5,100	9.625"	40	HCK-55	BTC	1.57	4.63	6.07
8.75"	0	17,088'	5.5"	17	P-110RY	BTC	1.79	2.55	3.68
	1	I	1	BLM	Minimum S	afety Factor	1.125	1.00	1.6 Dry 1.8 Wet

All casing strings will be tested in accordance with Onshore Oil and Gas Order #2 III.B.1.h

Must have table for contingency casing

	Y or N
Is casing new? If used, attach certification as required in Onshore Order #1	Y
Does casing meet API specifications? If no, attach casing specification sheet.	Y
Is premium or uncommon casing planned? If yes attach casing specification sheet.	N
Does the above casing design meet or exceed BLM's minimum standards? If not provide justification (loading assumptions, casing design criteria).	Y
Will the intermediate pipe be kept at a minimum 1/3 fluid filled to avoid approaching the collapse pressure rating of the casing?	Y
Is well located within Capitan Reef?	N
If yes, does production casing cement tie back a minimum of 50' above the Reef?	
Is well within the designated 4 string boundary.	and the
Is well located in SOPA but not in R-111-P?	N
If yes, are the first 2 strings cemented to surface and 3 rd string cement tied back 500' into previous casing?	
Is well located in R-111-P and SOPA?	N
If yes, are the first three strings cemented to surface?	
Is 2 nd string set 100' to 600' below the base of salt?	
Is well located in high Cave/Karst?	N
If yes, are there two strings cemented to surface?	
(For 2 string wells) If yes, is there a contingency casing if lost circulation occurs?	
Is well located in critical Cave/Karst?	N
If yes, are there three strings cemented to surface?	

3. Cementing Program

Casing	# Sks	Wt. lb/ gal	H20 gal/sk	Yld ft3/ sack	500# Comp. Strength (hours)	Slurry Description
13-3/8"	760	13.5	9.28	1.74	10	Lead: Class C Cement + 4% Gel + 1% Calcium Chloride + 0.125 lbs/sack Poly-E-Flake
Surface	550	14.8	6.32	1.33	6	Tail: Class C Cement + 0.125 lbs/sack Poly-E-Flake
12 2 101	520	13.5	9.28	1.74	10	1 st Stage Lead: Class C Cement + 4% Gel + 1% Calcium Chloride + 0.125 lbs/sack Poly-E-Flake
13-3/8" Surface	550	14.8	6.32	1.33	6	1 st Stage Tail: Class C Cement + 0.125 lbs/sack Poly-E- Flake
Two					D	V Tool = 300ft
Stage	320	14.8	6.32	1.33	6	2 nd Stage Primary: Class C Cement + 0.125 lbs/sack Poly-E-Flake
9-5/8" Inter.	1050	12.9	9.81	1.85	14	Lead: (65:35) Class C Cement: Poz (Fly Ash): 6% BWOC Bentonite + 5% BWOW Sodium Chloride + 0.125 Ibs/sack Poly-E-Flake
	430	14.8	6.32	1.33	6	Tail: Class C Cement + 0.125 lbs/sack Poly-E-Flake
5-1/2" Prod	590	11.9	12.89	2.31	n/a	Lead: (50:50) Class H Cement: Poz (Fly Ash) + 10% BWOC Bentonite + 1 lb/sk of Kol-Seal + 0.3% BWOC HR-601 + 0.5lb/sk D-Air 5000
Single Stage	2090	14.5	5.31	1.2	25	Tail: (50:50) Class H Cement: Poz (Fly Ash) + 0.5% bwoc HALAD-344 + 0.4% bwoc CFR-3 + 0.2% BWOC HR-601 + 2% bwoc Bentonite

DV tool depth(s) will be adjusted based on hole conditions and cement volumes will be adjusted proportionally. DV tool will be set a minimum of 50 feet below previous casing and a minimum of 200 feet above current shoe. Lab reports with the 500 psi compressive strength time for the cement will be onsite for review.

Casing String	TOC	% Excess
13-3/8" Surface Single Stage Option	0'	100%
13-3/8" Surface Two Stage Option	1 st Stage = 300' / 2 nd Stage = 0'	100%
9-5/8" Intermediate	0'	75%
5-1/2" Production Casing	4900'	25%

4. Pressure Control Equipment - See COA

N	A variance is requested for the use of a diverter on the surface casing. schematic.	See attached for
---	---	------------------

BOP installed and tested before drilling which hole?	Size?	Min. Required WP	T	уре		Tested to:			
			An	nular	X	50% of working pressure			
			Blin	d Ram					
12-1/4"	12-1/4" 13-5/8" 3M Pipe Ram Double Ram	3M		3M					
			Doub	le Ram	X	5141			
			Other*						
			An	nular	X	50% testing pressure			
	12 5/02					Blind Ram			
8-3/4"		23.6	Pipe	Pipe Ram					
0-3/4	13-5/8"	3M	Doub	le Ram	X	3M			
			Other *						
			An	nular					
			Blin	d Ram					
			Pipe	Ram		·			
				le Ram					
			Other *						

*Specify if additional ram is utilized.

BOP/BOPE will be tested by an independent service company to 250 psi low and the high pressure indicated above per Onshore Order 2 requirements. The System may be upgraded to a higher pressure but still tested to the working pressure listed in the table above. If the system is upgraded all the components installed will be functional and tested.

Pipe rams will be operationally checked each 24 hour period. Blind rams will be operationally checked on each trip out of the hole. These checks will be noted on the daily tour sheets. Other accessories to the BOP equipment will include a Kelly cock and floor safety valve (inside BOP) and choke lines and choke manifold. See attached schematics.

Y Formation integrity test will be performed per Onshore Order #2.
 On Exploratory wells or on that portion of any well approved for a 5M BOPE system or greater, a pressure integrity test of each casing shoe shall be performed. Will be tested in accordance with Onshore Oil and Gas Order #2 III.B.1.i.

Devon Energy, Thistle Unit 122H

.

Y	A variance is requested for the use of a flexible choke line from the BOP to Choke
Y	Manifold. See attached for specs and hydrostatic test chart.
	Y Are anchors required by manufacturer?
Y	A multibowl wellhead may be used. The BOP will be tested per Onshore Order #2 after installation on the surface casing which will cover testing requirements for a maximum of 30 days. If any seal subject to test pressure is broken the system must be tested.
	Devon proposes the option of using a multi-bowl wellhead assembly. This assembly wil only be tested when installed on the surface casing. Minimum working pressure of the blowout preventer (BOP) and related equipment (BOPE) required for drilling below the surface casing shoe shall be 3000 (3M) psi.
	 Wellhead will be installed by vendor's representatives.
	• If the welding is performed by a third party, the vendor's representative will monitor the temperature to verify that it does not exceed the maximum temperature of the seal.
ee A	 Vendor representative will install the test plug for the initial BOP test. Vendor will install a solid steel body pack-off to completely isolate the lower hear after cementing intermediate casing. After installation of the pack-off, the pack-off and the lower flange will be tested to 3M, as shown on the attached schematic Everything above the pack-off will not have been altered whatsoever from the initial nipple up. Therefore the BOP components will not be retested at that time. If the cement does not circulate and one inch operations would have been possibl with a standard wellhead, the well head will be cut and top out operations will be
	 conducted. Devon will pressure test all seals above and below the mandrel (but still above th casing) to full working pressure rating. Devon will test the casing to 0.22 psi/ft or 1500 psi, whichever is greater, as per Onshore Order #2.
	After running the 13-3/8" surface casing, a 13-5/8" BOP/BOPE system with a minimum rating of 3M will be installed on the wellhead system and will undergo a 250 psi low pressure test followed by a 3,000 psi high pressure test. The 3,000 psi high and 250 psi low test will cover testing requirements a maximum of 30 days, as per Onshore Order #2 If the well is not complete within 30 days of this BOP test, another full BOP test will be conducted, as per Onshore Order #2. After running the 9-5/8' intermediate casing with a mandrel hanger, the 13-5/8" BOP/BOPE system with a minimum rating of 3M will already be installed on the
	wellhead. The pipe rams will be operated and checked each 24 hour period and each time the drill pipe is out of the hole. These tests will be logged in the daily driller's log. A 2" kill line and 3" choke line will be incorporated into the drilling spool below the ram BOP. In

Devon requests a variance to use a flexible line with flanged ends between the BOP and the choke manifold (choke line). The line will be kept as straight as possible with minimal turns.

See attached schematic.

5. Mud Program

Depth		Туре	Weight (ppg)	Viscosity	Water Loss	
From	То					
0	1,450'	FW Gel	8.6-8.8	28-34	N/C	
1,450'	5,100'	Saturated Brine	10.0-10.2	28-34	N/C	
5,100'	17,088'	Cut Brine	8.5-9.3	28-34	N/C	

Sufficient mud materials to maintain mud properties and meet minimum lost circulation and weight increase requirements will be kept on location at all times.

What will be used to monitor the loss or gain	PVT/Pason/Visual Monitoring
of fluid?	

6. Logging and Testing Procedures

Log	ging, Coring and Testing.
х	Will run GR/CNL fromTD to surface (horizontal well - vertical portion of hole). Stated
	logs run will be in the Completion Report and submitted to the BLM.
	No Logs are planned based on well control or offset log information.
	Drill stem test? If yes, explain
	Coring? If yes, explain

Additional logs planned		Interval				
	Resistivity	Int. shoe to KOP				
	Density	Int. shoe to KOP				
Х	CBL	Production casing				
Х	Mud log	Intermediate shoe to TD				
	PEX					

7. Drilling Conditions

Condition	Specify what type and where?
BH Pressure at deepest TVD	4673 psi
Abnormal Temperature	No

Mitigation measure for abnormal conditions. Describe. Lost circulation material/sweeps/mud scavengers.




Hydrogen Sulfide (H2S) monitors will be installed prior to drilling out the surface shoe. If H2S is detected in concentrations greater than 100 ppm, the operator will comply with the provisions of Onshore Oil and Gas Order #6. If Hydrogen Sulfide is encountered, measured values and formations will be provided to the BLM.


N	H2S is present	
Y	H2S Plan attached	

8. Other facets of operation

Is this a walking operation? No. Will be pre-setting casing? No.

Attachments <u>x</u> Directional Plan Other, describe







NOTES REGARDING BLOWOUT PREVENTERS

Devon Energy Production Company, L.P. THISTLE UNIT 122H

- Drilling Nipple will be constructed so it can be removed mechanically without the aid of a welder. The minimum internal diameter will equal BOP bore.
- 2. Wear ring will be properly installed in head.
- Blowout preventer and all associated filings will be in operable condition to withstand a minimum of 3000psi working pressure.
- All fittings will be flanged.
- A fill bore safety valve tested to a minimum of 3000psi WP with proper thread connections will be available on the rotary rig floor at all times.
- All choke lines will be anchored to prevent movement.
- All BOP equipment will be equal to or larger in bore than the internal diameter of the last casing string.
- Will maintain a kelly cock attached to the kelly.
- 9. Hand wheels and wrenches will be properly installed and tested for safe operation.
- 10. Hydraulic floor control for blowout preventer will be located as near in proximity to driller's controls as possible.
- 11. All BOP equipment will meet API standards and include a minimum 40 gallon accumulator having two independent means of power to initiate closing operation.





Ontinental & CONTITECH

Fluid Technology

ContiTech Beattie Corp. Website: www.contitechbeattie.com

Monday, June 14, 2010

RE: Drilling & Production Hoses Lifting & Safety Equipment

To Helmerich & Payne,

A Continental ContiTech hose assembly can perform as intended and suitable for the application regardless of whether the hose is secured or unsecured in its configuration. As a manufacturer of High Pressure Hose Assemblies for use in Drilling & Production, we do offer the corresponding lifting and safety equipment, this has the added benefit of easing the lifting and handling of each hose assembly whilst affording hose longevity by ensuring correct handling methods and procedures as well as securing the hose in the unlikely event of a failure; but in no way does the lifting and safety equipment affect the performance of the hoses providing the hoses have been handled and installed correctly it is good practice to use lifting & safety equipment but not mandatory

Should you have any questions or require any additional information/clarifications then please do not hesitate to contact us.

ContiTech Beattie is part of the Continental AG Corporation and can offer the full support resources associated with a global organization.

Best regards,

Robin Hodgson Sales Manager ContiTech Beattie Corp

ContiTech Seattle Corp, 11535 Brithmoore Park Drive, Houston, TX 77041 Phone: +1 (832) 327-0141 Fac: +1 (832) 327-0148 www.contilechibeattle.com



R16 212

PHOENIX 2

PHOENIX RUBBER

OUALITY DOCUMENT

6

5

•

C

4


.

agad, Budapaal úl: 10. Hungary - H-6701 Szagad, P. O. Box 152 12) 566-737 - Parc (3052) 566-738 5728 S

INDUSTRIAL LTD.

SALES & MARIGETING: H-1092 Budgent, Riday u. 42-44. Hungary - H-1440 Budgent, P. O. Box 25 Phone: (361) 458-4200 - Far: (361) 217-2972, 455-4273 - www.taurusemerge.hu

PURCHASER:	Dha	enix Beal	tie Co	and the second second			-	-	519F	A-871	
			-			•	P.O. Nº				-
PHOENIX RUBBER ord	ler Nº- 17	0466	HOSE	TYPE:	3"	ID · ·	Ch	oke and		068	
HOSE SERIAL Nº	34	1128		NALIAC	TUAL LE	ENGTH:		11,4	3 m		
W.P. 68,96 MPa	10000	pst	T.P.	103,4	MPa	1500) psi	Duration	nc .	60	mi
Pressure test with water ambient temperature	at "		•						•••		
		· · · · ·			• • •		•				
	:	See atta	chme	nt. (1	page)			-	`		
	·					•	· .				
1				• .	1		•	•			*
10 mm = 10	Min.	÷ !									
→ 10 mm = 25	MPa										
		\$	c	OUPLIN	IGS						L 120
Туре	· · · ·		C Serial N	OUPLIN	IGS		Quality			Heat Nº	- 12
Type 3° coupling with	h	720	Serial N		IGS		Quality SI 4130			Heat N° C7626	
Туре	h		Serial N	6	IGS	A					- 12
Type 3° coupling with	h		Serial N	6	IGS	A	SI 4130	-		C7626	
Type 3° coupling with	h		Serial N	6	API Sr	Al:	SI 4130 SI 4130	-		C7626	
Type 3" coupling with 4 1/16" Flange	h end		Serial N	6		Al:	SI 4130 SI 4130			C7626	
Type 3° coupling with	end s	720	Serial N D 7	е 19	API St Tempe	Al: Al: Dec 16 erature	SI 4130 SI 4130 C rate:"E		MS OF	C7626 47357	



.

Ser Other

Warne .

5 × 4 (

31:00

. •

: Lag

24

VERIFIED TRUE CO. PHOENIE RUBBER Q.C.



Commitment Runs Deep



Design Plan Operation and Maintenance Plan Closure Plan

SENM - Closed Loop Systems June 2010

I. Design Plan

Devon uses MI SWACO closed loop system (CLS). The MI SWACO CLS is designed to maintain drill solids at or below 5%. The equipment is arranged to progressively remove solids from the largest to the smallest size. Drilling fluids can thus be reused and savings is realized on mud and disposal costs. Dewatering may be required with the centrifuges to insure removal of ultra fine solids.

The drilling location is constructed to allow storm water to flow to a central sump normally the cellar. This insures no contamination leaves the drilling pad in the event of a spill. Storm water is reused in the mud system or stored in a reserve fluid tank farm until it can be reused. All lubricants, oils, or chemicals are removed immediately from the ground to prevent the contamination of storm water. An oil trap is normally installed on the sump if an oil spill occurs during a storm.

A tank farm is utilized to store drilling fluids including fresh water and brine fluids. The tank farm is constructed on a 20 ml plastic lined, bermed pad to prevent the contamination of the drilling site during a spill. Fluids from other sites may be stored in these tanks for processing by the solids control equipment and reused in the mud system. At the end of the well the fluids are transported from the tank farm to an adjoining well or to the next well for the rig.

Prior to installing a closed-loop system on site, the topsoil, if present, will be stripped and stockpiled for use as the final cover or fill at the time of closure.


Signs will be posted on the fence surrounding the closed-loop system unless the closed-loop system is located on a site where there is an existing well, that is operated by Devon.

II. Operations and Maintenance Plan

Primary Shakers: The primary shakers make the first removal of drill solids from the drilling mud as it leaves the well bore. The shakers are sized to handle maximum drilling rate at optimal screen size. The shakers normally remove solids down to 74 microns.

2

Mud Cleaner: The Mud Cleaner cleans the fluid after it leaves the shakers. A set of hydrocyclones are sized to handle 1.25 to 1.5 times the maximum circulating rate. This ensures all the fluid is being processed to an average cut point of 25 microns. The wet discharged is dewatered on a shaker equipped with ultra fine mesh screens and generally cut at 40 microns.



Centrifuges: The centrifuges can be one or two in number depending on the well geometry or depth of well. The centrifuges are sized to maintain low gravity solids at 5% or below. They may or may not need a dewatering system to enhance the removal rates. The centrifuges can make a cut point of 8-10 microns depending on bowl speed, feed rate, solids loading and other factors.

The centrifuge system is designed to work on the active system and be flexible to process incoming fluids from other locations. This set-up is also dependant on well factors.

Dewatering System: The dewatering system is a chemical mixing and dosing system designed to enhance the solids removal of the centrifuge. Not commonly used in shallow wells. It may contain pH adjustment, coagulant mixing and dosing, and polymer mixing and dosing. Chemical flocculation binds ultra fine solids into a mass that is within the centrifuge operating design. The

dewatering system improves the centrifuge cut point to infinity or allows for the return of clear water or brine fluid. This ability allows for the ultimate control of low gravity solids.

Cuttings Boxes: Cuttings boxes are utilized to capture drill solids that are discarded from the solids control equipment. These boxes are set upon a rail system that allows for the removal and replacement of a full box of cuttings with an empty one. They are equipped with a cover that insures no product is spilled into the environment during the transportation phase.

Process Tank: (Optional) The process tank allows for the holding and process of fluids that are being transferred into the mud system. Additionally, during times of lost circulation the process tank may hold active fluids that are removed for additional treatment. It can further be used as a mixing tank during well control conditions.

Sump and Sump Pump: The sump is used to collect storm water and the pump is used to transfer this fluid to the active system or to the tank for to hold in reserve. It can also be used to collect fluids that may escape during spills. The location contains drainage ditches that allow the location fluids to drain to the sump.

Reserve Fluids (Tank Farm): A series of frac tanks are used to replace the reserve pit. These are steel tanks that are equipped with a manifold system and a transfer pump. These tanks can contain any number of fluids used during the drilling process. These can include fresh water, cut brine, and saturated salt fluid. The fluid can be from the active well or reclaimed fluid from other locations. A 20 ml liner and berm system is employed to ensure the fluids do not migrate to the environment during a spill.

If a leak develops, the appropriate division district office will be notified within 48 hours of the discovery and the leak will be addressed. Spill prevention is accomplished by maintaining pump packing, hoses, and pipe fittings to insure no leaks are occurring. During an upset condition the source of the spill is isolated and repaired as soon as it is discovered. Free liquid is removed by a diaphragm pump and returned to the mud system. Loose topsoil may be used to stabilize the spill and the contaminated soil is excavated and placed in the cuttings boxes. After the well is finished and the rig has moved, the entire location is scrapped and testing will be performed to determine if a release has occurred.

All trash is kept in a wire mesh enclosure and removed to an approved landfill when full. All spent motor oils are kept in separate containers and they are removed and sent to an approved recycling center. Any spilled lubricants, pipe dope, or regulated chemicals are removed from soil and sent to landfills approved for these products.

These operations are monitored by Mi Swaco service technicians. Daily logs are maintained to ensure optimal equipment operation and maintenance. Screen and chemical use is logged to maintain inventory control. Fluid properties are monitored and recorded and drilling mud volumes are accounted for in the mud storage farm. This data is kept for end of well review to insure performance goals are met. Lessons learned are logged and used to help with continuous improvement.

A MI SWACO field supervisor manages from 3-5 wells. They are responsible for training personnel, supervising installations, and inspecting sites for compliance of MI SWACO safety and operational policy.

III. Closure Plan

A maximum 340' X 340' caliche pad is built per well. All of the trucks and steel tanks fit on this pad. All fluid cuttings go to the steel tanks to be hauled by various trucking companies to an agency approved disposal.

H&P Flex Rig Location Layout 3 Well Pad

