
Submit I Copy To Appropriate District Office	State of New Mexico	Form C-103
District I Energy, Minerals and Natural Resources		October 13, 2009 WELL API NO.
District II		30-025-34163
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION		5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NMSEP10 0 7 2016 District IV	1220 South St. Francis Dr.	STATE FEE
	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fent CEIVEL 87505	,	
SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		J H Williams
1. Type of Well: Oil Well Gas Well Other		8. Well Number 2
2. Name of Operator Apache Corp.		9. OGRID Number 000873
3. Address of Operator		10. Pool name or Wildcat SKAGGS
P O box Drawer D Monument NM 88265		(DRINKARD) & MONUMENT (TUBB)
4. Well Location		
Unit Letter P : 470	feet from theS line and	990feet from theEline
Section 34 Township 19S Range 37E NMPM Lea County		
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
3569 GR		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
12. Check rippropriate Box to indicate rature of recipe, report of other Bata		
E-PERMITTING <swd injections="" of:<="" report="" subsequent="" td=""></swd>		
HEMEDIAL WORK		
GOIVING BITTELING OF NO.		
		:NT JOB
	LOC	
INT TO PA P&A NRP8	AR OTHER: TA	TEST
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of		
proposed completion or recompletion	n.	
	This Approval	of Temporary 1
0/4/202		
FCIIS 1UBB. 0418-0014 DRINKARD. 0812-0904		
<ol> <li>MIRU. POOH &amp; LD RODS. NU-BOP. POOH W/ TBG</li> <li>SET CIBP @ 6340. DUMP BAIL 35' CMT ON CIBP.</li> </ol>		
3. LOAD CSG W/ PKR FLUID & TEST 550#.		
4. NOTIFY OCD 24 HRS BEFORE TESTING & CHART RECORD		
5. MEET OCD REP. GEORGE BOWER. PRESSURE UP ON CSG. TO 580#.		
6. RECORD TEST ON CHART. ENDING PRESS. 580#. SEE CHART.		
7. REQUEST TA STATUS FOR WEL	L.	
Spud Date:	Rig Release Date:	
I hereby certify that the information above is t	true and complete to the best of my knowle	dge and belief.
CICNATURE And like		
SIGNATURE TITLE_SR PUMPERDATE9/7/2016		
Type or print nameJOEL SISK E-mail address: _joel.sisk@apacheccorp.com_ PHONE:575-441-0793		
For State Use Only		
APPROVED BY: Wally Stown TITLE SIST Supervisor DATE 9/8/2016		
Conditions of Approval (if any):		



## GL=3569' KB=3579' Spud:10/26/97

## Apache Corporation – J.H. Williams #2

Wellbore Diagram - Current

API: 30-025-34163

Date: 8/26/2016 K. Grisham



470' FSL & 990' FEL, Lot P Sec 34, T19S, R37E, Lea County, NM

**Surface Casing** 9-5/8" 36# @ 1241' w/ 600 sxs to surface

TOC @ 3565'

**Intermediate Casing** 7" 23# J-55 @ 4030' w/ 400 sxs. TOC @ 2862'

8/16: Set CIBP @ 6380' capped w/ 35' cmt. New PBTD @ 3645'

7/12: Treat for paraffin. Acid frac Drinkard w/ 64,386 gals acid. Acidize Tubb w/ 2500 gals 15% HCl, drop 120 ball sealers, no ball action.

5/98: Perf Tubb @ 6418-6614 w/ 2 jspf (90 holes) Acidized w/ 10,000 gal 15 % NEFE w/ 136 mcf N2 8/12: Acidized w/ 2500 gallons 15% NEFE

11/97: Perf Drinkard @ 6812-6904 w/ 2 jspf (118 holes) Acidized w/ 5000 gal 15% HCL 8/12: Acid frac with 860 bbs 12# XL assist and 64,386 gal 15% Divert

S acid system.

PBTD = 3,645'MD = 7,000'


**Production Casing** 4-1/2" 10.5# J-55 @ 7000' w/ 265 sxs



Hole Size =12-1/4"



Hole Size =6-1/8"



STATE OF THE PARTY