

District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS OGD
OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505
OCT 04 2016

WELL API NO. 30-025-22020
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-9560
7. Lease Name or Unit Agreement Name New Mexico BG State NCT 1
8. Well Number 4
9. OGRID Number 213190
10. Pool name or Wildcat Saunders; Permo Upper Penn

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator
CrownQuest Operating, LLC

3. Address of Operator
PO Box 53310, Midland, TX 79710

4. Well Location

Unit Letter **E** : **1980** feet from the **N** line and **660** feet from the **W** line
Section **14** Township **14-S** Range **33-E** NMPM County **Lea**

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
4200 GL

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTI

PERFORM REMEDIAL WORK ☐ INT TO PA
TEMPORARILY ABANDON ☐ P&A NR **Em**
PULL OR ALTER CASING ☐ P&A R
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☒
CASING/CEMENT JOB ☐

OTHER: _____

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

07/25/16 MIRU plugging equipment. Dug out cellar. Started to bleed down casing pressure. 07/26/16 ND wellhead, NU BOP. RIH w/ tbg and tagged @ 8842'. Spotted 25 sx cement @ 8842-8464. (per Mark Whitaker). 07/27/16 NO Tag. Re-Spot 25 sx cement @ 8842-8464. WOC. Cemented tbg in hole. 07/28/16. Freepointed tbg. Cut tubing @ 5962'. Spotted 25 sx cement @ 5962-5530'. (per Mark Whitaker). WOC. Tagged plug @ 5530'. POH and ND wellhead. 07/29/16 Cut casing @ 4150'. POH w/ 4 1/2 casing. 08/01/16 Spotted 40 sx cement @ 4250-4103. WOC. Tagged plug @ 4073'. Spotted 45 sx cement @ 2650-2481. WOC. Tagged @ 2480'. Spotted 40 sx cement @ 1750-1602. WOC. 08/02/16 Tagged plug @ 1580'. Perf'd csg @ 437'. Pressured up to 600 psi. Spotted 40 sx cement @ 487-339. WOC. Tagged plug @ 350'. Perf'd csg @ 100'. Circulated 80 sx cement to surface. Rig down and moved off. 08/02/16 Moved in welder and backhoe. Dug out cellar. Cut off wellhead. Welded on "Above Ground Dry Hole Marker". Backfilled cellar. removed deadmen. and cleaned location. Moved off

Approved for Plugging of wellbore only. Liability under bond is retained pending restoration and completion of the C-103, Specific for Subsequent Report of Well Plugging, which may be found on the OCD web page under forms.

Spud Date:

7-25-2016

Rig Release I

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Saul Leyva

TITLE **Lease Manager**

DATE **9-26-2016**

Type or print name

Saul Leyva

E-mail address: **sleyva@crownquest.com**

PHONE: **432-559-9066**

For State Use Only

APPROVED BY:

Mark Whitaker

TITLE **P.E.S.**

DATE **10/5/2016**

Conditions of Approval (if any):