

Submit 1 Copy To Appropriate District

Office

District I - (575) 393-6161

1625 N. French Dr., Hobbs, NM 88240

District II - (575) 748-1283

811 S. First St., Artesia, NM 88210

District III - (505) 334-6178

1000 Rio Brazos Rd., Aztec, NM 87410

District IV - (505) 476-3460

1220 S. St. Francis Dr., Santa Fe, NM

87505

State of New Mexico

Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.

Santa Fe, NM 87505

Form C-103

Revised August 1, 2011

WELL API NO.

30-025-05249

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

Mexico F

8. Well Number / 4 SWD

9. OGRID Number

258350

10. Pool name or Wildcat

Denton, Devonian

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☐ Other SWD

2. Name of Operator

Vanguard Operating LLC

3. Address of Operator

5847 San Felipe St. Ste. 3000, Houston, TX 77057

4. Well Location

Unit Letter D : 660 feet from the North line and 660 feet from the West line
Section 2 Township 15S Range 37E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

3823' RKB

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Notify OCD 24 hrs prior to MIRU to P&A due to what appears to be parted casing at 3473', the following procedure is requested:
2. RIH with 2 3/8" WS & mule shoe to top of fish @ 10,600'.
3. Spot 25 x class "H" cmt @ 10,600' - 10,400' WOC & tag (TOF).
4. Circ hole w/MLF spot 80 x class "H" cmt @ 9575' - 9160' WOC & tag (sqz'd perms F/9210' - 9500').
5. Spot 20 sx cmt F/8188' - 8085' WOC & tag (sqz'd perms).
6. Spot 20 sx cmt F/6225' - 6125' (Glorieta).
7. Perf @ 4830' (9 5/8" shoe, San Andres) spot 100 sx's cmt @ 4830' - 4730' WOC & tag.
8. Sqz 125 sx cmt @ 3500' - 3050' csg part, (Yates) WOC & tag.
9. Perf @ 2150' sqz 50 sx's cmt 2150' - 2050' (Anhydrite).
10. Perf @ 375' sqz 50 sx's cmt 375' - 275' (13 3/8" shoe) WOC & tag.
11. Perf @ 100' circ cmt to surf vis 5 1/2" x 9 5/8" csg ann
12. Cut off wellheads ensure cmt @ surf on all 3 strings. Install dry hole marker.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Jimmy Bagley

TITLE

Agent

DATE 11/02/2016

Type or print name Jimmy Bagley

E-mail address: sunsetwellservice@yahoo.com

PHONE: 432-561-8600

For State Use Only

APPROVED BY:

Mary Brown

TITLE

Dist Supervisor

DATE

11/17/2016

Conditions of Approval (if any):