Form 3160-5 (August 2007) DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT OCD Hobs Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010 5. Lease Serial No. NMNM15684 6. If Indian, Allottee or Tribe Name			
RECEIVED	PLICATE - Other instruc	tions on reverse side.		7. If Unit or CA/ RNM011	/Agreement, Name and/or No.			
Type of Well Oil Well	her			8. Well Name an MADERA 28	d No. 3 FED C 2			
2. Name of Operator / Contact: STAN WAGNER EOG RESOURCES INCORPORATEDE-Mail: stan_wagner@eogresources.com					9. API Well No. 30-025-29862-00-S1			
3a. Address MIDLAND, TX 79702	3b. Phone No. (include area cod Ph: 432-686-3689	le)	10. Field and Pool, or Exploratory ATOKA					
4. Location of Well (Footage, Sec., 28 T24S R34E SESW 66)		11. County or Parish, and State LEA COUNTY, NM					
12. CHECK APP	ROPRIATE BOX(ES) TO	INDICATE NATURE OF	NOTICE, RI	EPORT, OR O	THER DATA			
TYPE OF SUBMISSION	TYPE OF ACTION							
☑ Notice of Intent☐ Subsequent Report☐ Final Abandonment Notice	☐ Acidize ☐ Alter Casing ☐ Casing Repair ☐ Change Plans ☐ Convert to Injection	☐ Deepen ☐ Fracture Treat ☐ New Construction ☑ Plug and Abandon ☐ Plug Back	☐ Reclama	plete earily Abandon	INT TO PA P&A NR P&A R			
13. Describe Proposed or Completed Op If the proposal is to deepen direction Attach the Bond under which the worfollowing completion of the involve testing has been completed. Final A determined that the site is ready for EOG Resources proposes to 1. Set 3-1/2" CIBP at 13850 2. Circulate well w/ 9 ppg m 3. Spot 55 sx Class H ceme 4. Spot 35 sx Class H ceme 4. Spot 35 sx Class H ceme 5. Spot 25 sx Class C ceme 7. Spot 35 sx Class C ceme 7. Spot 35 sx Class C ceme 8. Spot 25 sx Class C ceme 9. Spot 75 sx Class C ceme 10. Cut off wellhead three features.	ally or recomplete horizontally, or will be performed or provide operations. If the operation re bandonment Notices shall be fil final inspection.) plug and abandon this we be a suppose of Class Fud. 1. Dump bail 35' of Class Fud. 1. Tag at or the plug at 4755'. Tag at or the plug at 4755'. Tag at or the plug at 683'. Tag at or	give subsurface locations and meathe Bond No. on file with BLM/B sults in a multiple completion or reed only after all requirements, including as follows: Comparison of the completion of the completion of the completion of the completion of the comparison of the comparison of the comparison of the completion of the completion of the comparison of the comparison of the comparison of the completion of th	sured and true ve IIA. Required sul ecompletion in a ruding reclamation	ertical depths of all bsequent reports sh new interval, a For n, have been comp	pertinent markers and zones. all be filed within 30 days m 3160-4 shall be filed once eleted, and the operator has Second From 12184 - 11964			
Selow Ground	abandonment	marker Requi	sed	CUNDITIO	ONS OF APPROVA			
14. I hereby certify that the foregoing i		352819 verified by the BLM W	Iell Information	System				

For EOG RESOURCES INCORPORATED, sent to the Hobbs

Committed to AFMSS for processing by PRISCILLA PEREZ on 09/29/2016 (16PP1234SE)

Name (Printed/Typed) STAN WAGNER **REGULATORY ANALYST**

(Electronic Submission) Date 09/28/2016 Signature

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By Title

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Additional data for EC transaction #352819 that would not fit on the form

32. Additional remarks, continued

- 11. Circulate cement from 100' to surface. Ensure cement to surface across all annuluses.12. Weld on P&A marker. Cut off anchors three feet below surface. Clean location.

MADERA 28 FED COM #2 API# 30-025-29862 Sect 28, T245, R34E eog resources 4/23/1987 660' FSL & 2200' FWL energy opportunity growth SMB LEA, NM 47.5001% 40,9180% Formation Tops GL KB Spot Class C from 100' to surface Spot 75sx Class C @ 683', TAG at 573 11-3/4" 42# H40 STC 10-5/8" PLUGGED W / 450 SX CLASS H CMT @ 3,159' 4,350 Spot 35sx Class C @ 4.755', TAG TOC 4,705' (CALC) 5061 70sx Class C @ 5.260°, TAG 4.5 5460-5160 8-5/8" 32# K55 STC ROD DETAIL Spot 25sx Class H @ 7,100' SIZE ITEM DEPTH Spot 35sx Class H @ 2400 TAG at 12,947 TUBING DETAIL TOI. 12,9971 SIZE ITEM DEPTH 2-7/8" 12,938 5-1/2" 17 / 20# P110 / S95 7-7/8" Spot 55sx Class H (a) 13,850" 3-1/2" CIBP à 13-850" АТОКА 13,869' - 13,875' 3-1/2" 12.52# N80 LINER Collapse Tubular Dimensions bbl/ft ID 0

MADERA 28 FED COM #2

API# 30-025-29862 Sect 28, T245, R34E



SPUD DRILLING 3/10/1987 4/23/1987

	660' FSL &	2200' FWL	energy opportuni				LAST REVISED	5/3/2016	NC
	LEA					WI		NRI	
Formation Tops		GL KB	I	Hole	AFE	#			
	11-3/4" 42# H40 STC	623'	15	5-1/4"	Rsh Tos Del	10(64		
		2.810	10	0-5/8''	Del	534	17		
	PLUGGED W / 450 SX CLASS H CMT @ 3,159'		50'		BS WC Alaka	121	34		
	8-5/8" 3.	# K55 STC 5.2	C 4,705' (CALC))-5/8''	Hada	15,4			
						COUNT	ROD SIZE	DETAIL ITEM	DEPTH
	5-1/2" 17 / 20# P		12.997'	-7/8''		COUNT	TUBING SIZE 2-7/8"	G DETAIL ITEM	DEPTH 12,938'
АТОКА	13,869° 3-1/2" 12.52# N8	- 13,875'	,						
	1	,		Į					
					Tubular Dimensions Collapse	Burst	ID	Drift	bbl/ft
				}		-			0
						1			0
				ŀ					0

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval (LPC Habitat)

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. Below Ground Level Cap (Lesser Prairie-Chicken Habitat): All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off. Upon the plugging and subsequent abandonment of wells that are located in lesser prairie-chicken habitat, the casings shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be covered with a metal plate at least ¼ inch thick and welded in place. A weep hole shall be left in the plate and/or casing.

NMOCD also requires the operator to notify NMOCD when this type of dry hole marker is used. This can be done on the subsequent report of abandonment which is submitted to the BLM after the well is plugged. State that a below ground cap was installed as required in the COA's from the BLM.

- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.

<u>Timing Limitation Stipulation/ Condition of Approval for Lesser Prairie-Chicken:</u>
From March 1st through June 15th annually, abandonment activities will be allowed except between the hours from 3:00 am and 9:00 am. Normal vehicle use on existing roads will not be restricted