	Submit 1 Copy To Appropriate District State of New Mexico	Form C-103	
	Office  District I – (575) 393-6161  HOBBSE Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240  District H. (575) 748, 1383	Revised July 18, 2013	
	1625 N. French Dr., Hobbs, NM 88240	WELL API NO.	
	District II – (575) 748-1283 811 S. First St., Artesia, NM 88210 JAN 0 9 211 CONSERVATION DIVISION District III – (505) 334-6178	30-025-07652	
		5. Indicate Type of Lease  STATE FEE 🔀	
	1000 Rio Brazos Rd., Aztec, NM 87410 District IV = (505) 476-3460 Santa Fe, NM 87505	6. State Oil & Gas Lease No.	
	District IV - (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NECEIVED		
	87505 SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name	
	(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name of Omit Agreement Name	
	DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	South Hobbs (G/SA) Unit	
	PROPOSALS.)  1. Type of Well: Oil Well Gas Well Other Temporarily Abandoned	8. Well Number 61	
	2. Name of Operator	9. OGRID Number 157984	
	Occidental Permian, Ltd	)	
	3. Address of Operator	10. Pool name or Wildcat	
	HCR 1 Box 90 Denver City, TX 79323	Hobbs (G/SA)	
	4. Well Location		
Unit Letter A : 330 feet from the North line and 330 feet from the East line			
	Section 8 Township 19-S Range 38-E NMPM Lea County		
	11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
	3598' GL		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:			
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING			
	PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING   TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS.   P AND A		
	PULL OR ALTER CASING   MULTIPLE COMPL   CASING/CEMENT		
	DOWNHOLE COMMINGLE		
	CLOSED-LOOP SYSTEM		
	OTHER: TA status extension request		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of			
proposed completion or recompletion.			
	Run MI test to gain extension on temporarily abandoned status.		
Run wir test to gain extension on temporarily abandoned status.			
	Condition of Approval: notify OCD Hobbs office 24 hours prior of running MIT Test & Chart		
	Spud Date: Rig Release Date:		
	I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
	Mand (1 Carpona		
	SIGNATURE DATE 01/05/2017		
	Type or print name Mendy A. Johnson E-mail address: mendy_johnson@oxy.com PHONE: 806-592-6280		
	For State Use Only A /		
	Wales There was the later of th		
	APPROVED BY: Y COLUMN THE WORLD THE APPROVED BY:	DATE I 7 I	
		DATE 1 1 201	
	Conditions of Approval (if any):	DATE	