Form 3160-5 (June 2013) HOB-1 + 2011 BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an Hobbs abandoned well. Use form 3160-3 (APD) for such proposals.					FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018 5. Lease Serial No.	
					NMNM117126	
					6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agreement, Name and/or No.	
1. Type of Well ☑ Oil Well □ Gas Well □ Other					8. Well Name and No. TALCO 9 26 35 FED 3H	
2. Name of Operator Contact: TINLEE TILTON ENDURANCE RESOURCES LLC E-Mail: tinlee@endurance resourcesllc.com					9. API Well No. 30-025-43458-00-X1	
3a. Address3b. Phone No. (include area code)203 WEST WALL SUITE 1000Ph: 432.242.4680MIDLAND, TX 79701Ph: 432.242.4680					10. Field and Pool or Exploratory Area UNDESIGNATED WOLFCAMP	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish, State	
Sec 9 T26S R35E SWNE 2440FNL 2280FEL 32.058365 N Lat, 104.371185 W Lon					LEA COUNTY, NM	
12. CHECK THE A	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE O	F NOTICE,	REPORT, OR OTH	IER DATA
TYPE OF SUBMISSION	TYPE OF ACTION					
□ Notice of Intent	□ Acidize		Deepen		tion (Start/Resume)	□ Water Shut-Off
Subsequent Report	Alter Casing		Iraulic Fracturing	□ Reclamation		Well Integrity
☐ Final Abandonment Notice	Casing Repair Change Plans	_	v Construction g and Abandon	Recomp		Other Drilling Operations
	Convert to Injection		Plug Back		Temporarily Abandon Water Disposal	
following completion of the involvent testing has been completed. Final A determined that the site is ready for 11/16/2016: Drilled to 11585 @ 5294'. Cement with 510 s ppg, 1.515 cuft/sk, 7.45 gal/s opening device. DVT did not attempt to get cement to sur Established injection rate for 11/18/2016: Ran CBL and di 11/20/2016: TIH w/ cement r cuft/sk, 5.386 gal/sk). Unstin sxs (12.6 ppg, 1.612 cuft/sk, 11/21/2016: Drill out cement 11/22/2016: TIH w/ cement r	Abandopment Notices must be fi final inspection. Automatic Research States Automatic Research States Automatic Result was overdised ace. TIH to shift DVT closes shoe squeeze. scussed plan forward with etainer and set at 11,459'. g from retainer and revers 8.46 gal/sk). retainer, FC, & FS. Run C	led only after al # HCP-110 B 20.12 gal/sk) Ilfunction and placement of ed. Drill out a BLM. Perfor Cement belo e circulate. B CBL.	requirements, includ IC casing at 1158 lead followed with plug did not bum the first stage by nd TIH to float co ate squeeze hole: w with 340 sxs (1 raden head squee	ing reclamatio 35' with DV ⁻ n 240 sxs (1 p. Dropped 89 bbls in a Ilar. s at 11,519' 15.6 ppg, 1. eze with 38	n, have been completed : T & ECP 13.2 DVT an 196 3	and the operator has
14. I hereby certify that the foregoing	Electronic Submission #	#362185 verifi	d by the BLM Wel	Informatio	System	Π
Com	For ENDURAI mitted to AFMSS for proces	NCE RESOUR	ES LLC, sent to FER SANCHEZ o	the Hobbs n 12/29/2016	(17DLM0205SE)	
Name (Printed/Typed) TINLEE			Title ENGINE		ED FOR REC	XORDI //
Signature (Electronic	: Submission)		Date 12/28/20	ALLEP		T //
Diginitate (Dictionin	THIS SPACE FOR FEDERA				SEN 3 2017	AL
			T		JAN J L.	hh /And
Approved By Conditions of approval, if any, are attack certify that the applicant holds legal or e which would entitle the applicant to con	Title Office	BURE	RLSBAD FELDOER	CE		
Title 18 U.S.C. Section 1001 and Title 4 States any false, fictitious or frauduler	3 U.S.C. Section 1212, make it a t statements or representations a	a crime for any p s to any matter v	erson knowingly and vithin its jurisdiction.	willfully to m	ake to any department or	agency of the United
(Instructions on page 2) ** BLM RE	VISED ** BLM REVISE	D ** BLM R	EVISED ** BLN	REVISE) ** BLM REVISE	** 67
						0

Additional data for EC transaction #362185 that would not fit on the form

32. Additional remarks, continued

1.196 cuft/sk, 5.386 gal/sk). Unsting from retainer and reversed out 108 sxs (62 bbls below retainer and behind pipe - 1000'+ of fill). TIH to top of retainer and WOC. 11/24/2016: Drilled to 11605' and performed FIT to 13.5 ppg - successful. 11/30/2016: TD pilot hole at 13170'. TIH to 13170' and set 55 sxs (12.5, 2.075 cuft/sk, 11.64 gal/sk) plug. Pull up to 12805' and circulate pipe clean (2-3 bbls to surface). WOC. Tagged cement at 12819'. Set second plug with 210 sxs (16.4 ppg, 1.073 cuft/sk, 4.46 gal/sk) from 12600' - 11745' (tagged).

12/20/2016: TD 6 3/4" hole at 19,722' MD. Run and set 5" 18# HCP-110 DWC-C-IS-PLUS to 19,722'. Cement with 615 sxs (11 ppg, 2.809 cuft/sk, 17.38 gal/sk) lead and 510 sxs (14.5 ppg, 2.16 cuft/sk, 9.28 gal/sk). Estimated 48 sxs cement to surface. Displaced with FW. WOC.