Submit 1 Copy To Appropriate District State of New Me Office District 1 – (575) 393-6164 CRSS OCENERGY, Minerals and Natu	
1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II – (575) 748-1283 811 S. First St., Artesia, NM 88240 26 2017OIL CONSERVATION	DIVISION 30-025-41712 5. Indicate Type of Lease
<u>District III</u> – (505) 334-6178 1220 South St. Fran	icis Dr. STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410         Santa Fe, NM 87410           District IV - (505) 476-3460         Santa Fe, NM 87           1220 S. St. Francis Dr., Santa Fe, Santa Fe, Santa Fe, NM 87         Santa Fe, NM 87	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLJ DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FO	
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other	8. Well Number 701H
2. Name of Operator EOG Resources, Inc.	/ 9. OGRID Number 7377
3. Address of Operator	10. Pool name or Wildcat
P.O. Box 2267 Midland, TX 79702 WC-025 S263327H; Wolfcamp	
4. Well Location Unit Letter H : 2420 feet from the North line and 947 feet from the East line	
	nge 33E NMPM County Lea
11. Elevation (Show whether DR, 3293' GR	RKB, RT, GR, etc.)
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INT	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK       INT TO PA       REMEDIAL WORK       ALTERING CASING         TEMPORARILY ABANDON       INT TO PA       COMMENCE DRILLING OPNS.       P AND A	
PULL OR ALTER CASING D P&A NR A. CASING/CEMENT JOB	
CLOSED-LOOP SYSTEM	OTHER: P&A
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.	
4715	
6/20/16 MIRU to P&A. 6/24/16 RIH and set 9-5/8" CIBP at 7290'. Tested casing to 1000 psi. Test good.	
6/27/16 Spot 55 sx Class H neat cement on CIBP at 7290. WOC 4 hrs. RIH and tag cement top at 4570'.	
Spot 55 sx Class C cement plug at 2827'. No tag, estimate TOC at 2670'. Spot 60 sx Class C cement plug at 968'.	
6/28/16 RIH and tag cement top at 800'. Notified NMOC	D. POOH.
Circulate cement from 10 <sup>er</sup> to surface. 100 <sup>er</sup> 7/07/16 Cut off wellhead and install P&A marker.	
7107716 Cut on weinead and install P&A marker.	
Approved for Plugging of wellbore only. Liability	
under bond is retained pending restoration and completion of the C-103, Specific for Subsequent	
Report of	Well Plugging, which may be found on
Spud Date: the OCD w	eb page under forms.
RESTORA	TION DUE BY 6/27/2017
I hereby certify that the information above is true and complete to the be	st of my knowledge and belief.
AL I Bea	ulatory Analyst 1/23/2017
SIGNATURE /// IIILE	DATE
Type or print name Stan Wagner // E-mail address	: PHONE:
For State Use Only	
APPROVED BY: Malutitation TITLE P.E	
APPROVED BY: TITLE TITLE TITLE Conditions of Approval (if any):	.S. DATE 01/26/2017