
Submit 1 Copy To Appropriate District Office District I State of New Mexico Energy, Minerals and Natural Resources	Form C-103 October 13, 2009
District I 1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION	30-025-04541
District III 1220 South St. Francis Dr.	5. Indicate Type of Lease STATE ☐ FEE ☒
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe 1919 0 6 2017	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM TO POSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION-FOR PERMIT" (FORM C-101) FOR SUCH	HL HOUSTON GAS COM
PROPOSALS.) 1. Type of Well: Oil Well Gas Well	8. Well Number 3
2. Name of Operator	9. OGRID Number 873
Apache Corp. 3. Address of Operator	10. Pool name or Wildcat
P O box Drawer D Monument NM 88265	EUMONT-QUEEN GAS
4. Well Location	
Unit LetterB:660feet from theN line and	1980feet from theEline
Section 7 Township 21S Range 36E	NMPM Lea County
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
E-PERMITTING SUBSEQUENT REPORT OF:	
PE CONVERSATION RBDMS (NB) REMEDIAL WOR	
TE RETURN TO TA COMMENCE DRI	
PU CSCG ENVIRO CHGLOC CASING/CEMEN	TJOB L
INT TO PAP&A NRP&A R	
OTHER: L OTHER: TAT	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of	
proposed completion or recompletion.	
D. (1.01001.0005)	
Perfs 3108'-3625' This Approval of Tempo	
1.MIRU. POOH & LD RODS & TBG. Abandonment Expires 2/2/202	
2. SET CIBP @ 3050. DUMP BAIL 35' CMT ON TOP.	
3. LOAD CSG W/ PKR FLUID & TEST TO 550# 4. NOTIFY OCD 24 HRS IN ADVANCE OF TA TEST.	
5. MEET OCD REP. GEORGE BOWER. PRESSURE UP ON CSG TO 560#. RECORD T	EST ON CHART FOR 32 MIN. ENDING
PRESSURE 560#. REQUEST TA STATUS FOR WELL. SEE ATTACHED CHART.	
Spud Date: Rig Release Date:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
1 1 0 1	
SIGNATURE God Such TITLE Sr. Pumper_	DATE2-3-17
Type or print nameJoel Sisk E-mail address: _joelsisk@apacheco	
	DATE2-3-17
Type or print nameJoel Sisk E-mail address: _joelsisk@apacheco	DATE2-3-17



Apache Corporation - Houston HL Gas Com #3

Wellbore Diagram - Current

API: 30-025-04541

Date: 6/28/16 K.Grisham



660' FNL & 1980' FEL, Lot B Sec 7, T21S, R36E, Lea County, NM

Surface Casing 12-1/2" 40# @ 272' w/ 150 sxs to surface

Intermediate Casing 8-5/8" 28# @ 2653' w/ 500 sxs to surface

1/17: Set CIBP @ 3050' & cap w/ 35' cmt.

3/36: Original completion

6/54: Run 130' 5" liner set @ 3894' & sqz'd w/ 100 sxs. DO cmt to 3888'. Perf'd 5" csg fr/ 3825-3845' w/ 4 jspf. Tested perfs but concluded there was not commercial quantites of oil. Plug back to 3720' & perf'd 6-5/8" csg fr/ 3108-42'; 33066-36'; 62-3405'; 45-53' & 3509-53' w/3 jspf (819 holes). Acidize w/ 2500 gals 15% LST Acid. Sand oiled above 6-5/8" perfs w/ 10,000 gals oil & 10,000# sd. 12/58: Perf csg fr/ 3590-3625' w/ 2 jspf (70 holes). Sand frac fr/ 3590-3625' w/ 6000 gals famarise refined oil & 6000# 20/40 sd. Then w/


3625' w/ 6000 gals famarise refined oil & 6000# 20/40 sd. Then w/ 4000 gals refined oil & 4000# 20/40 sd (same zone). Frac'd perfs fr/ 3108-3553 w/ 20,000 gals famarise refined oil, 20,000# 20/40 sd. 11/75: Set pumping unit

5/79: Pulled rods & found pump bbl parted. Attempted to fish, then pull tbg - both w/ no results. Cut tbg & pulled fr/ hole. Left tbg & pump in hole, Ran 111 jts tbg, open ended @ 3524'.

10/93: Tagged fish @ 3530', latched on & TOH. RIH w/ prod equip & RTP.

9/01: Pulled rods due to corrosion. RIH w/ inspected used rods & RTP

Production Casing 6-5/8" 24# @ 3795' w/ 100 sxs OH fr/ 3795-3895'



PBTD = 3,720' MD =3,895'