Date: 02/10/2017

Title:

Agent

E-mail Address: mjp1692@gmail.com

Phone: 575-914-1461

District I 1625 N. French Dr., Hobbs, NM 88240 Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720

District III 1000 Rio Brazos Road, Aztec, NM 87410 Phone: (505) 334-6178 Fax: (505) 334-6170

District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico

Form C-101 Revised July 18, 2013

Energy Minerals and Natural Resources

Oil Conservation Division

HOBBS OCHAMENDED REPORT

1220 South St. Francis Dr.

Santa Fe, NM 87505

FEB 1 0 2017

A DDI I			D DEI	оміт т	O DE) 	DE_EN	TER, DI	FEDEN	DII	REC			ZONE
AITLI	CATIO	NTO		erator Name			NE-EN	TER, DI		, 1 L	ODACI	OGRID	Number	ZONE
		;	Stev 3211 In	vard Energ	gy II, LI	_C e 150						3716		
			F	risco, TX	75034							30-02	mber 4 3	//05
* Prope	erty Code	406	T			P	Property N inkman f	ame ee			I		Well No	o. 4H
						7. Sui	rface Lo	cation					***************************************	
UL - Lot	Section	Township	р	Range	Lot	l Idn	Feet fro		/S Line	1	et From	E/W Lin		County
D	23	148		38E		$\overline{}$	470		lorth		330	West		Lea
						T		n Hole Loc						
UL - Lot	Section 14	Township 14S	P	Range 38E	Lot	Idn	Feet fro		/S Line	1	330	E/W Lin		Lea
						9. Por	ol Inform	nation						
						Pool N		iidiioii						Pool Code
					Bronce	o; San A	ndres, S	outh						07500
					A			nformation						
200	k Type Well		12	Well Type Oil			13 Cable/Re Rotar			14 Lease	~ "	1	5 Ground L	evel Elevation
1	ultiple			posed Depth			18. Format	ion		19 Contr				ud Date
Depth to Grou	nd water			9950 Dista	nce from	nearest fr	San A				Distance to	nearest su		5/2017
				Dista	nee non	nourest n	esii water				Distance	J Hourest su	riace water	B
We will b	e using a c	losed-loc	op syste	m in lieu o	f lined p	pits								
				21.	Propo	sed Cas	ing and	Cement Pr	ogram					
Туре	Hole	Size	Casi	ng Size	Ca	asing Wei	ght/ft	Settin	g Depth		Sacks of C	ement	Es	timated TOC
Surf	12	.25	9.	625		36		24	100		900			0
Prod				5.5		20		99	950	50 2000)		0
				Casin	g/Cem	ent Pro	gram: A	dditional	Commen	its				
Propose to	drill a pilo	ot hole to	6300	and run lo	gs. Se	t cmt plu	ig at 425	0', kick off a	nd drill 7	7/8" la	iteral to 99	50' MD.		
				22.	Propo	sed Blov	wout Pr	evention P	ogram					
	Туре					Pressure			Test Pre	essure			Manufa	cturer
Type Annular				3000			1500			Schafer				
Double Ram 3000			00		1500			Schafer						
	owledge an	d belief.	-						OIL	CON	SERVAT	TON DI	VISION	I
best of my knowledge and belief. I further certify that I have complied with 19.15.14.9 (A) NMAC \(\text{ and/or} \) 19.15.14.9 (B) NMAC \(\text{ and and/or} \)						Approved By:								
19.15.14.9 (B) NAAC And/or 19.15.14.9 (A) NMAC And/or 19.15.14.9 (B) NAAC Signature:						Malnub								
Printed name	Melar	nie J. W	ilson					Title:	/	1	V	Pe	troleur	n Engineer

Approved Date: 02

Conditions of Approval Attached

See Attached **Conditions of Approval**

Expiration Date:

CONDITIONS OF APPROVAL

API#	Operator	Well name & Number
30-025-43592	STEWARD ENERGY II LLC	PINKMAN FEE # 004H

Applicable conditions of approval marked with XXXXXX

Administrative Orders Required

Other wells	1
Drilling	
XXXXXXX	Once the well is spud, to prevent ground water contamination through whole or partial conduits from the surface, the operator shall drill without interruption through the fresh water zone or zones and shall immediately set in cement the water protection string

Casing

XXXXXXX	SURFACE & PRODUCTION CASING - Cement must circulate to surface
XXXXXXXX	If cement does not circulate to surface, must run temperature survey or other log to determine top of cement
XXXXXXX	Surface casing must be set 25' below top of Rustler Anhydrite in order to seal off protectable water

Lost Circulation

XXXXXXX	Must notify OCD Hobbs Office if lost circulation is encountered at 575-370-3186

Continued

Water flows

XXXXXXX	Must notify OCD Hobbs Office of any water flow in the Salado formation at 575-370-3186. Report depth
_	and flow rate.

Stage Tool

XXXXXX	Must notify OCD Hobbs Office prior to running Stage Tool at 575-370-3186
XXXXXX	If using Stage Tool on Surface casing, Stage Tool must be greater than 350' and a minimum 200 feet
	above surface shoe.
XXXXXX	When using a Stage Tool on Intermediate or Production Casing Stage must be a minimum of 50 feet
	below previous casing shoe.

Pits

XXXXXXX	If using a pit for drilling and completions, must have an approved pit form prior to spudding the well

Completion & Production

Operator shall notify appropriate District office when setting conductor pipe. The Operator is to notify NMOCD by sundry (Form C-103) within ten (10) days of spudding a well.
The Operator is to notify NMOCD by sundry (Form C-103) within ten (10) days of spudding a well.
It is the operator's responsibility to monitor cancellation dates of approved APDs. APD's are good for 2 years and may be extended for one year. Only one 1 year extension will be granted if submitted by C-103 before expiration date. After expiration date or after a 1 year extension must submit new APD.
If an APD expires and if site construction has occurred, site remediation is required.
ye b

Gas Capture Plan

XXXXXXX	Submit Gas Capture Plan form prior to spudding or initiating recompletion operations	