UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

5. Lease Serial No. NMNM13418

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agree	ment, Name and/or No.	
Type of Well Gas Well □ Other					8. Well Name and No. AMOCO FEDERA	L8 /	
Name of Operator Contact: ROSS PEARSON CROSS BORDER RESOURCES, INCE-Mail: ROSS@REDMOUNTAINRESOURCES.COM					9. API Well No. 30-005-20732-00-S1		
3a. Address 14282 GILLIS ROAD FARMERS BRANCH, TX 752	o. (include area code) 71-0400 Ext: 1019 1-0406)	10. Field and Pool or Exploratory Area TOM TOM-SAN ANDRES				
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish, State		
Sec 26 T7S R31E NESE 2173			CHAVES COUNTY, NM				
12. CHECK THE AF	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE OF	F NOTICE,	REPORT, OR OTH	IER DATA	
TYPE OF SUBMISSION TYPE OF ACTION					×	<i>b</i>	
Notice of Intent	☐ Acidize	□ Deepen □ Produ		□ Product	ion (Start/Resume)	☐ Water Shut-Off	
_	☐ Alter Casing	☐ Hyo	Iraulic Fracturing	☐ Reclama	ation	■ Well Integrity	
☐ Subsequent Report	☐ Subsequent Report ☐ Casing Repair		☐ New Construction ☐ Recon		olete	⊠ Other	
☐ Final Abandonment Notice	☐ Change Plans	Plug	g and Abandon	☐ Tempor	arily Abandon	Production Start-up	
	☐ Convert to Injection	Plug	g Back	☐ Water D	Disposal		
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. MIRU pulling unit. POOH with rods and pump. POOH with production tubing. Check fluid level. Acidize well if it is carrying a fluid level (800 to 1000' above the perfs). Hydrotest tubing back into the hole. Return well to production. Accepted For Record Only! Approval Subject To Putting Well On Continuous Production Or Plugging Well With An Approved Plugging Program!							
14. I hereby certify that the foregoing is true and correct. Electronic Submission #367159 verified by the BLM Well Information System For CROSS BORDER RESOURCES, INC., sent to the Roswell Committed to AFMSS for processing by DAVID GLASS on 02/15/2017 (17DRG0104SE)							
Name (Printed/Typed) ROSS PEARSON			Title VP OPERATION				
Signature (Electronic Submission)			Date 02/15/2017				
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
ACCEPTED FOR RECORD							
Approved By ORKS SCD) DAVID & CLASS			Title Date				
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Office				
Fitle 18 U.S.C. Section 1001 and Yitle 45 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.							

(Instructions on page 2) ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **

