	Form 3160-5 (June 2015) UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT PGD Hobbs SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-entergan abandoned well. Use form 3160-3 (APD) for such proposals 27 DUP PGD Hobbs SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-entergan abandoned well. Use form 3160-3 (APD) for such proposals 27 DUP PGD Hobbs SUBMIT IN TRIPLICATE - Other instructions on page TOP SUBMIT IN TRIPLICATE - Other instructions on page TOP I. Type of Well Gas Well Other 2. Name of Operator SHACKELFORD OIL COMPANY Contact: ARICKA EASTERLING E-Mail: aeasterling@cimarex.com 3a. Address 203 WEST WALL SUITE 200 MIDLAND, TX 79701 3b. Phone No. (include area code) Ph: 918.560.7060 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				0CD	FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018 5. Lease Serial No. NMLC065710A 6. If Indian, Allottee or Tribe Name 7. If Unit or CA/Agreement, Name and/or No. 8. Well Name and No. LUSK FEDERAL A 12 9. API Well No. 30-025-24869-00-S1 10. Field and Pool or Exploratory Area LUSK		
	Sec 20 T19S R32E SWNE 16	<i>y</i>			LEA COUNTY, NM			
	12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION							
	TYPE OF SUBMISSION Notice of Intent Subsequent Report Final Abandonment Notice 13. Describe Proposed or Completed Ope If the proposal is to deepen directional	 Acidize Alter Casing Casing Repair Change Plans Convert to Injection 	 New Plug Plug nt details, includ 	pen raulic Fracturing / Construction g and Abandon g Back ing estimated startin	 Production (Start/Resume) Reclamation Recomplete Temporarily Abandon Water Disposal 		 □ Water Shut-Off □ Well Integrity ☑ Other 	
	Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. Cimarex has reclaimed the Lusk Frac pit located in Section 20-19S-32E of Lea County, NM as shown in the attached plat. Removed fencing, cut and pulled liner, back filled tank. Redistributed dirt and re-seeded. Location is ready for inspection. Advanced							
	14. I hereby certify that the foregoing is true and correct. Electronic Submission #360997 verified by the BLM Well Information System For SHACKELFORD OIL COMPANY, sent to the Hobbs Committed to AFMSS for processing by JIM AMOS on 01/09/2017 (17JA0021SE) Name (Printed/Typed) ARICKA EASTERLING Signature (Electronic Submission) Date 12/15/2016							
N	Accepted For Record THIS SPACE FOR FEDERAL OR STAT				OFFICE US	SE		
*	Approved By Title Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Title Chock Title 18/U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any fake, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Office CHOC (Instructions on page 2) ** BLM REVISED ** BLM REVISED **							
	MUS/OCD 3/27/2017							