	Form C-103
Submit 1 Copy To Appropriate District Office District I 1625 N. French Dr., Hobbs, NM 88240 District II	October 13, 2009
1625 N. French Dr., Hobbs. NM 88240	WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM, 88210 2 2017 OIL CONSERVATION DIVISION	30-025-29771
District III 1220 South St. Francis Dr.	5. Indicate Type of Lease STATE FEE
	6. State Oil & Gas Lease No.
1000 Rio Brazos Rd., Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Ferral Santa Fe, NM 87505 87505	o. State on & das Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" FORM C-101) FOR SUCH	
PROPOSALS.)	North Monument G/SA Unit Blk. 4
1. Type of Well: Oil Well Gas Well Other Injection well.	8. Well Number 9
2. Name of Operator	9. OGRID Number 873
Apache Corp.	10. Pool name or Wildcat
3. Address of Operator P O box Drawer D Monument NM 88265	North Monument G/SA
,	North Monument O/SA
4. Well Location	
Unit LetterI:1654feet from theS line and	330feet from the
Eline)
Section 24 Township 19S Range 36E	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
12. Check Appropriate Box to Indicate Nature of Notice,	Report or Other Data
NOTICE OF INTENTION TO: SUBS	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	
TEMPORARILY ABANDON	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT	
DOWNHOLE COMMINGLE	30B
DOWNTOLL COMMUNICALL	
OTHER: OTHER:	5 year pressure test
	o year pressure test
13. Describe proposed or completed operations. (Clearly state all pertinent details, and	give pertinent dates, including estimated date
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Com	give pertinent dates, including estimated date
13. Describe proposed or completed operations. (Clearly state all pertinent details, and	give pertinent dates, including estimated date
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Com	give pertinent dates, including estimated date
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion.	give pertinent dates, including estimated date appletions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Com	give pertinent dates, including estimated date appletions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. Moved in Maclaskey pump truck to perform pressure test on casing. Pressured the casing to	give pertinent dates, including estimated date appletions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. Moved in Maclaskey pump truck to perform pressure test on casing. Pressured the casing to	give pertinent dates, including estimated date appletions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. Moved in Maclaskey pump truck to perform pressure test on casing. Pressured the casing to	give pertinent dates, including estimated date appletions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. Moved in Maclaskey pump truck to perform pressure test on casing. Pressured the casing to	give pertinent dates, including estimated date appletions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. Moved in Maclaskey pump truck to perform pressure test on casing. Pressured the casing to	give pertinent dates, including estimated date appletions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. Moved in Maclaskey pump truck to perform pressure test on casing. Pressured the casing to	give pertinent dates, including estimated date appletions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. Moved in Maclaskey pump truck to perform pressure test on casing. Pressured the casing to	give pertinent dates, including estimated date appletions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. Moved in Maclaskey pump truck to perform pressure test on casing. Pressured the casing to	give pertinent dates, including estimated date appletions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. Moved in Maclaskey pump truck to perform pressure test on casing. Pressured the casing to	give pertinent dates, including estimated date appletions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. Moved in Maclaskey pump truck to perform pressure test on casing. Pressured the casing to	give pertinent dates, including estimated date appletions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. Moved in Maclaskey pump truck to perform pressure test on casing. Pressured the casing to minutes with a 5 lb. loss to 540 psi.	give pertinent dates, including estimated date appletions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. Moved in Maclaskey pump truck to perform pressure test on casing. Pressured the casing to minutes with a 5 lb. loss to 540 psi.	give pertinent dates, including estimated date appletions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. Moved in Maclaskey pump truck to perform pressure test on casing. Pressured the casing to minutes with a 5 lb. loss to 540 psi. Spud Date: Rig Release Date:	I give pertinent dates, including estimated date appletions: Attach wellbore diagram of 545 psi & recorded the test on a chart for 33
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. Moved in Maclaskey pump truck to perform pressure test on casing. Pressured the casing to minutes with a 5 lb. loss to 540 psi.	I give pertinent dates, including estimated date appletions: Attach wellbore diagram of 545 psi & recorded the test on a chart for 33
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. Moved in Maclaskey pump truck to perform pressure test on casing. Pressured the casing to minutes with a 5 lb. loss to 540 psi. Spud Date: Rig Release Date:	I give pertinent dates, including estimated date appletions: Attach wellbore diagram of 545 psi & recorded the test on a chart for 33 et and belief.
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. Moved in Maclaskey pump truck to perform pressure test on casing. Pressured the casing to minutes with a 5 lb. loss to 540 psi. Spud Date: Rig Release Date:	I give pertinent dates, including estimated date appletions: Attach wellbore diagram of 545 psi & recorded the test on a chart for 33 et and belief.
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. Moved in Maclaskey pump truck to perform pressure test on casing. Pressured the casing to minutes with a 5 lb. loss to 540 psi. Spud Date: Rig Release Date: Thereby certify that the information above is true and complete to the best of my knowledge SIGNATURE TITLE Instrument Tech	give pertinent dates, including estimated date appletions: Attach wellbore diagram of 545 psi & recorded the test on a chart for 33 e and belief.
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. Moved in Maclaskey pump truck to perform pressure test on casing. Pressured the casing to minutes with a 5 lb. loss to 540 psi. Spud Date: Rig Release Date: Thereby certify that the information above is true and complete to the best of my knowledge SIGNATURE Type or print name Jim Ellison E-mail address: _JD.Ellison@apa	I give pertinent dates, including estimated date appletions: Attach wellbore diagram of 545 psi & recorded the test on a chart for 33 et and belief.
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. Moved in Maclaskey pump truck to perform pressure test on casing. Pressured the casing to minutes with a 5 lb. loss to 540 psi. Spud Date: Rig Release Date: Thereby certify that the information above is true and complete to the best of my knowledge SIGNATURE Type or print name Jim Ellison E-mail address: _JD.Ellison@apa For State Use Only	give pertinent dates, including estimated date inpletions: Attach wellbore diagram of 545 psi & recorded the test on a chart for 33 e and belief.
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. Moved in Maclaskey pump truck to perform pressure test on casing. Pressured the casing to minutes with a 5 lb. loss to 540 psi. Spud Date: Rig Release Date: Thereby certify that the information above is true and complete to the best of my knowledge SIGNATURE Type or print name Jim Ellison E-mail address: _JD.Ellison@apa For State Use Only	give pertinent dates, including estimated date inpletions: Attach wellbore diagram of 545 psi & recorded the test on a chart for 33 e and belief.
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. Moved in Maclaskey pump truck to perform pressure test on casing. Pressured the casing to minutes with a 5 lb. loss to 540 psi. Spud Date: Rig Release Date: Thereby certify that the information above is true and complete to the best of my knowledge SIGNATURE Type or print name Jim Ellison E-mail address: _JD.Ellison@apa	give pertinent dates, including estimated date inpletions: Attach wellbore diagram of 545 psi & recorded the test on a chart for 33 e and belief.

