Submit 1 Copy To Appropriate District State of New Mexico					Form C-103			
Office <u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240 Energy, Minerals and Natural Resources					Revised July 18, 2013 WELL API NO.			
District II – (575) 748-1283 811 S. First St., Artesia, NM 88210 S. OCTOIL CONSERVATION DIVISION						30-025-34906		
District III – (505) 334-6178 1220 South St. Francis Dr.					5. Indicate Type of Lease STATE X FEE			
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460 $122017$ Santa Fe, NM 87505						6. State Oil & Gas Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM 2017 87505						19552		
SUNDRY NOTICES AND REPORTS ON WELLS						7. Lease Name or Unit Agreement Name		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH						North Hobbs Unit (G/SA)		
PROPOSALS.) 1. Type of Well: Oil Well X Gas Well Other					8. Well	8. Well Number 511		
2. Name of Operator Occidental Permian Ltd						9. OGRID Number 157984		
3. Address of Operator					10. Pool name or Wildcat			
P.O. Box 4294, Houston, TX 77210					Hobbs (G/SA)			
4. Well Location	D 1210 a		Marth		509		Most	
Unit Letter		et from the	North	line and	598	_feet from the	West line	
Section 3		ownship	18S Range	38E	NMPM	County	Lea	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3643' GR								
12 Check Appropriate Pow to Indicate Nature of Natice Papert or Other Date								
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data								
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:								
							_	
TEMPORARILY ABANDON       CHANGE PLANS       COMMENCE DRILLING OPNS.       P AND A         PULL OR ALTER CASING       MULTIPLE COMPL       CASING/CEMENT JOB       I								
DOWNHOLE COMMINGLE								
CLOSED-LOOP SYST	EM 🗌		_					
OTHER: OTHER:								
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of								
proposed completion or recompletion.								
•	MIRU x NDWH x NUB	OP.						
•	Shot drain holes @ 3898'.							
•	POOH ESP x 126 jts tbg.							
	Disassembled ESP x found very little asphaltenes.							
•	• RIH 4 ¼" bit x tagged @ 4399'.							
Ran gyro 4000' to surface.								
<ul> <li>RIH ESP @ 4015' x 122 jts tbg @ 3893'.</li> </ul>								
RD x NDBOP x NUWH								
		7						
Spud Date: 04/07/1	17	Rig Re	elease Date:	04/13/17				
L								
The state of the state		1 1	to the best of	1 1 1 1 1 1 1 1		£		
I hereby certify that the	information above is true	and complete	to the best of	my knowledg	ge and belle	Ι.		
REIL X KALL								
SIGNATURE						5/08/2017		
Type or print name April Hood E-mail address			il address. An	ril Hood@O	w.com	PHONE: 7	713-366-5771	
Type or print name April Hood       E-mail address: April_Hood@Oxy.com       PHONE: 713-366-5771         For State Use Only       For State Use Only       For State Use Only								
	ah-	-	Dete	alaren 17	•		religion	
APPROVED BY:	Hit about	TITLE	e retr	oleum Eng	ineer	DATE	411 741/	
Conditions of Approval	(II ally).							