Submit 1 Copy To Appropriate District Office State of New Mexico	Form C-103
Submit 1 Copy 10 Appropriate District Office District 1 – (575) 393-6161 State of New Mexico Minerals and Natural Resources 1625 N. French Dr., Hobbs, March 1283	Revised July 18, 2013
1625 N. French Dr., Hobbs. NA86240 District II - (575) 748-1283	WELL API NO. 30-025-02249
811 S First St., Artesia, NM 88219 11N 1 2 20 VIL CONSERVATION DIVISION	5. Indicate Type of Lease
District III - (505) 334-6178 JUN 1220 South St. Francis Dr. 1200 Rio Brazos Rd. Aztec. NM 87410	STATE S FEE (
1000 Rio Brazos Rd , Aztec, NM 87410 District IV – (505) 476-3460 1220 S St Francis Dr., Santa Fe. RECEIVED 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	VACUUM GRAYBURG SAN ANDRES UNIT
1. Type of Well: Oil Well	8. Well Number 41
2. Name of Operator CHEVRON U.S.A. INC.	9. OGRID Number 4323
Address of Operator 6301 DEAUVILLE BLVD, MIDLAND, TX 79706	10. Pool name or Wildcat VACUUM GRAYBURG SAN ANDRES
4. Well Location	
Unit Letter F : 1980 feet from the NORTH line and	1980feet from theWESTline
Section 1 Township 18-S Range 34-	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4,003' (GL)	Charles and the same of the sa
4,003 (GL)	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB	
DOWNHOLE COMMINGLE	
CLOSED-LOOP SYSTEM OTHER: HYDRAULIC FRACTURE TREATMENT OTHER: HYDRAULIC FRACTURE TREATMENT	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of	
proposed completion or recompletion.	
2/23/17 - 3/29/17:	
MIRU. Pulled ESP. RIH w/ bit, but tagged at whipstock, decided to fracture stimulate entire interval. Ran 3.5" tubing string and packer	
and set @ 3862'. RDMO. Fracture stimulate from 3999-4850'. MIRU and kill well. Pull packer and tubing. RIH with new ESP to 3891',	
RMDO, and RTP.	
S. J.D. J. D. J. D. J.	
Spud Date: Rig Release Date:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
mad +	
SIGNATURE TITLE Production Engineer DATE 6/6/17	
Type or print name _Michael Stewart E-mail address:michael.stewart@chevron.com PHONE: _432-687-7431	
For State Use Only	
APPROVED BY: TITLE Petroleum Eng	DATE 06/12/17
Conditions of Approval (if any):	