Form, 3160-5 (June 2015)

## UNITED STATES

FORM APPROVED Expires: January 31, 2018

UNITED STATES

DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WESTAGE

SUNDRY NOTICES AND REPORTS ON WESTAGE

Finding, Allottee or Tribe Name

6. If Indian, Allottee or Tribe Name Do not use this form for proposals to drill or to re-enter an

abandoned wel	I. Use form 3160-3 (APD) for	such plot sais.	obbs of midian, Another of	of Tribe Name	
SUBMIT IN 1	ons on page 2		7. If Unit or CA/Agreement, Name and/or No. NMNM104037X		
Type of Well	HO	8. Well Name and No. RED HILLS NOR			
Name of Operator     EOG RESOURCES INC	MADDOX OGRESOURCES.com	30-025-32577	80-025-32577		
3a. Address 3b. Phone No		Phone No. (include area code)	10. Field and Pool or	10. Field and Pool or Exploratory Area RED HILLS	
4. Location of Well (Footage, Sec., T. Sec 7 T25S R34E SWSW 988		11. County or Parish, LEA COUNTY,	LEA COUNTY, NM		
12. CHECK THE AF	PPROPRIATE BOX(ES) TO I	NDICATE NATURE OF	NOTICE, REPORT, OR OTI	HER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
☑ Notice of Intent ☐ Subsequent Report ☐ Final Abandonment Notice	☐ Acidize ☐ Alter Casing ☐ Casing Repair ☐ Change Plans ☐ Convert to Injection	☐ Deepen ☐ Hydraulic Fracturing ☐ New Construction ☐ Plug and Abandon ☐ Plug Back	☐ Production (Start/Resume) ☐ Reclamation ☐ Recomplete ☑ Temporarily Abandon ☐ Water Disposal	☐ Water Shut-Off ☐ Well Integrity ☐ Other	
13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.  EOG Resources performed a 24 hr injection test, 6/5/2017-6/6/2017 24 hr injection volume 2017 bbls  Average injection pressure of 2735 psi  Justification of TA Status: It is believed that the injection wells in the Red Hills North Unit are SOF APPROV no longer enhancing oil production from the producers. If the WIW's are TA'd and the production is monitored in the producing wells, it can be determined is this is true. If it is, the injection wells will be plugged.  EOG Resources requests permission to TA this well as follows:  1. Unset packer and POOH with existing 2 7/8" tbg  2. RIH w/bridge plug on tbg, set bridge plug at 11,755'-MD (50'- 11800' - 11568')					
Electronic Submission #378395 verified by the BLM Well Information System For EOG RESOURCES INC, sent to the Hobbs Committed to AFMSS for processing by MUSTAFA HAQUE on 06/09/2017 ()  Name (Printed/Typed) KAY MADDOX Title REGULATORY ANALYST					
Signature (Electronic Submission)		Date -06/08/20	Date 06/08/2017		
THIS SPACE FOR FEDERAL OR STATE OFFICE USE					
Approved By Musket Hogye  Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.  Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any personal conductions.		office Office RILL	O Willfully to make to any department or	Date GIV/2013	
States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.					

(Instructions on page 2)

\*\* OPERATOR-SUBMITTED \*\* OPERATOR-SUBMITTED \*\*

MSB/OCD 6/20/2017

## Additional data for EC transaction #378395 that would not fit on the form

## 32. Additional remarks, continued


above whipstock 5 1/2" esg)
3. Pump 25 sxs cmt CL H on top of BP
4. Schedule MIT tst - call BLM, tst the well @ 500 psig for 30 minutes.

Attached schematic

# Seog resources

## Red Hills North Unit No. 703

990' FSL & 990' FWL Sec. 7-25S-34E Lea County, New Mexico



## BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220

575-234-5972

### Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
  - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging. CIBP must be capped with minimum 25 sacks cement, placed with tubing or 35 feet of cement if placed with bailer.
  - b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. Any leak-off will be evaluated.
  - c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
  - d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
  - e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned. 43 CFR 3162.3-4 (a). The operator shall promptly plug and abandon wells in which oil or gas is not encountered in paying quantities.

Wells that successfully pass the casing integrity test may be approved for Temporary Abandonment (TA) status provided that the operator:

- 1. Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval with well bore diagram with all perforations and CIBP's and tops of cement on CIBP's.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

#### Red Hills North Unit 703H

- 1. Well may be approved to be TA/SI for a period of 1 year or until Date: 06/12/2018 after successful MIT and subsequent report is submitted.
- 2. Must submit NOI to recomplete or NOI to P&A. Must be submitted by 06/12/2018
- Contact BLM 24 hrs. prior to setting of plug so as it may be witnessed.