Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018


	Lease Serial No.	
1	MNM85933	

BUREAU OF LAND MANAGEMENT	
BUREAU OF LAND MANAGEMENT Carlsbad SUNDRY NOTICES AND REPORTS ON WELLS	File
Do not use this form for proposals to drill or to re-entermosals abandoned well. Use form 3160-3 (APD) for such proposals	dh

abandoned wel	I. Use form 3160-3 (AP	D) for such prop	osals	Delto	6. If maint Autorize of	Thoe Name			
SUBMIT IN T	7. If Unit or CA/Agree	ment, Name and/or No.							
Type of Well			8. Well Name an			2MD FED COM 1H			
Name of Operator MEWBOURNE OIL COMPAN	JACKIE LATHAN newbourne.com	I	-0	9. API Well No. 30-025-43872					
3a. Address PO BOX 5270 HOBBS, NM 88241			clude area code) 905		10. Field and Pool or E 53560	xploratory Area			
4. Location of Well (Footage, Sec., T.	, R., M., or Survey Description	1)			11. County or Parish, S	state			
Sec 34 T21S R32E Mer NMP	SWSW 270FSL 405FWL	- /			LEA COUNTY, N	NM			
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA									
TYPE OF SUBMISSION	TYPE OF SUBMISSION			TYPE OF ACTION					
Notice of Intent	☐ Acidize	□ Deepen		☐ Product	ion (Start/Resume)	■ Water Shut-Off			
	☐ Alter Casing	☐ Hydraul	ic Fracturing	Fracturing Reclamation		■ Well Integrity			
☐ Subsequent Report	☐ Casing Repair	☐ New Co		☐ Recomp		☑ Other Change to Original A			
☐ Final Abandonment Notice	☐ Change Plans	☐ Plug and			arily Abandon	PD PD			
	☐ Convert to Injection	☐ Plug Ba		□ Water I					
13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. Mewbourne Oil Company has an approved APD for the above well. Mewbourne requests approval to make the following change: Change wellhead to multi-bowl type wellhead. Please see attachments for wellhead schematic. Please contact Andy Taylor with any questions.									
14. I hereby certify that the foregoing is true and correct. Electronic Submission #379299 verified by the BLM Well Information System For MEWBOURNE OIL COMPANY, sent to the Hobbs									
Name (Printed/Typed) ANDREW	TAYLOR	Tit	le ENGINE	EER	***************************************				
Signature (Electronic S	Submission)	Da	te 06/20/2	017					
	THIS SPACE FO	OR FEDERAL O	OR STATE	OFFICER	PEVED				
Approved By Teungku N	Muchlis Krueng	Ti	itle	PETROLEU	IM ENGINEER	Date			
Conditions of approval, if any, are attached certify that the applicant holds legal or equal which would entitle the applicant to condu	itable title to those rights in the	e subject lease	ffice	JUN 2	2 2017				
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdictions on page 2) Carlsbad FIELD OFFICE CARLSBAD FIELD OFFICE									
Instructions on page 2) ** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED **									



13-5/8" MN-DS Wellhead System



PECOS DISTRICT DRILLING OPERATIONS CONDITIONS OF APPROVAL

All previous COA still apply except the following:

Operator has proposed a multi-bowl wellhead assembly. This assembly will only be tested when installed on the surface casing. Minimum working pressure of the blowout preventer (BOP) and related equipment (BOPE) required for drilling below the surface casing shoe shall be 5000 (5M) psi.

- a. Wellhead shall be installed by manufacturer's representatives, submit documentation with subsequent sundry.
- b. If the welding is performed by a third party, the manufacturer's representative shall monitor the temperature to verify that it does not exceed the maximum temperature of the seal.
- c. Manufacturer representative shall install the test plug for the initial BOP test.
- d. Operator shall perform the intermediate casing integrity test to 70% of the casing burst. This will test the multi-bowl seals.
- e. If the cement does not circulate and one inch operations would have been possible with a standard wellhead, the well head shall be cut off, cementing operations performed and another wellhead installed.

TMAK 06222017