Form 3160-5 (June 2015)	bs	FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018									
		5. Lease Serial No. NMLC063798									
Do aba	not use thi ndoned we	6. If Indian, Allottee or Tribe Name									
	SUBMIT IN	7. If Unit or CA/Agreement, Name and/or No. NMNM135592									
1. Type of Well	. Well Name and No. MultipleSee Atta	Well Name and No. MultipleSee Attached									
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals. 0.1 Lease Serial NO. NMLC063798 6. If Indian, Allottee or Tribe Name SUBMIT IN TRIPLICATE - Other instructions on page 100 MIL 7. If Unit or CA/Agreement, Name and/ NMNM135592 1. Type of Well AVE 9. API Well No. MultipleSee Attached 2. Name of Operator COG OPERATING LLC Contact: CATHY SEELY E-Mail: cseely@concho.com 9. API Well No. MultipleSee Attached											
3a. Address ONE CONCHO C	ENTER 60	0 W ILLINOIS AVENUE	(include area code) 8-1549		10. Field and Pool or Exploratory Area RED HILLS-BONE SPRING, NORTH						
4. Location of Well (A		C., R., M., or Survey Description))	11. County or Parish, State							
MultipleSee Atta	ached			LEA COUNTY, N			NM				
12. CHE	CK THE AL	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE O	F NOTICE,	REPORT, OR OTI	HER DA	ATA			
TYPE OF SUBM	TYPE OF SUBMISSION TYPE OF ACTION										
Notice of Intent		Acidize	Dee		Production (Start/Resume)			ater Shut-Off			
□ Subsequent Rep	ort	Alter Casing		raulic Fracturing	C Reclam			ell Integrity			
☐ Final Abandonn		 Casing Repair Change Plans 	-	Construction g and Abandon	Recomp Tempor	arily Abandon		Other Venting and/or Flari			
	iem Notice			ig Back		ng					
FROM 7/29/17 T # OF WELLS TO V ROY BATTY FEE ROY BATTY FEE ROY BATTY FEE ROY BATTY FEE	COG OPERATING LLC RESPECTFULLY REQUEST TO FLARE AT THE ROY BATTY FED COM 3H. FROM 7/29/17 TO 10/27/17. # OF WELLS TO FLARE: 4 / ROY BATTY FED COM 1H: 30-025-41099 ROY BATTY FED COM 4H: 30-025-41334 ROY BATTY FED COM 3H: 30-025-41333 ROY BATTY FED COM 2H: 30-025-41332 BBLS OIL/DAY: 150 MCF/DAY: 400										
14. I hereby certify that	the foregoing is	s true and correct. Electronic Submission #3	381437 verifie	d by the BLM Wei	Information	System					
		For COG nmitted to AFMSS for proce	LC, sent to the Hobbs SCILLA PEREZ on 07/20/2017 (17PP0511SE)								
Name (Printed/Typed	CATHYS	EELY	Title ENGINE	ENGINEERING TECH							
Signature	Signature (Electronic Submission)					Date 07/17/2017					
		THIS SPACE FC	R FEDERA	L OR STATE	OFFICE U	SE					
Approved By_OMAR_			TitlePETROLEUM ENGINEER Date 07/25			Date 07/25/2017					
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.				Office Hobbs							
		U.S.C. Section 1212, make it a statements or representations as			willfully to ma	ake to any department of	r agency o	of the United			
(Instructions on page 2)		ISED ** BLM REVISED) ** BI M D				א ם: ** ם:				
				ecord Only	DI7		0				

Additional data for EC transaction #381437 that would not fit on the form

Wells/Facilities, continued

Agreement NMNM135592	Lease NMLC063798	Well/Fac Name, Number ROY BATTY FEDERAL COM 3H	API Number 30-025-41333-00-S1	Location Sec 11 T24S R33E SWSE 190FSL 1887FEL
NMNM135592 NMNM135592	NMLC063798 NMLC063798	ROY BATTY FEDERAL COM 1H ROY BATTY FEDERAL COM 2H		32.225263 N Lat, 103.540227 W Lon Sec 11 T24S R33E SWSW 330FSL 660FWL Sec 11 T24S R33E SESW 190FSL 1887FWL
NMNM135592	NMLC063798	ROY BATTY FEDERAL COM 4H	30-025-41334-00-S1	32.225265 N Lat, 103.545082 W Lon Sec 11 T24S R33E SESE 190FSL 380FEL 32.225255 N Lat, 103.535355 W Lon

32. Additional remarks, continued

REASON: UNPLANNED MIDSTREAM CURTAILMENT

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

COG OPERATING LLC ROY BATTY FEDERAL COM MULTIPLE WELLS NMLC063798

07/25/2017

Pursuant to, 43 CFR 3179

Lessees or operators are hereby authorized to vent or flare gas on a short-term basis without incurring a royalty obligation in the following circumstances:

- A. 43 CFR 3179.105 Emergencies (a) An operator may flare or, if flaring is not feasible given the emergency, vent gas royalty-free under §3179.4 (a) (vi) of this subpart during an emergency. For purposes of this subpart, an "emergency" is a temporary, infrequent and unavoidable situation in which the loss of gas or oil is uncontrollable or necessary to avoid risk of an immediate and substantial adverse impact on safety, public health, or the environment. For purposes of royalty assessment, an "emergency" is limited to a short-term situation of 24 hours or less (unless the BLM agrees that the emergency conditions necessitating venting or flaring extend for a longer period) caused by an unanticipated event or failure that is out of the operator's control and was not due to operator negligence.
- B. 43 CFR 3179.4 Determining when the loss of oil or gas is avoidable or unavoidable.
 (2) Avoidably lost oil or gas means: Lost oil or gas that is not "unavoidably lost," as defined in paragraph (a) of this section; waste oil that became waste oil through operator negligence; and, any "excess flared gas," as defined in §3179.7.
- C. 43 CFR 3179.5 When lost production is subject to royalty.
 (a) Royalty is due on all avoidably lost oil or gas.
 (b) Royalty is not due on any unavoidably lost oil or gas.

Condition of Approval to Flare Gas

- 1. The first 24 hours of a <u>temporary emergency flare</u> is considered "unavoidably lost" and is therefore royalty free. Flared volumes that are considered unavoidably lost are not to be included in Sundry Notice (Form 3160-5). These Volumes are not royalty bearing and shall be reported on OGOR "B" as either disposition code "21" or "22".
- Flared volumes considered to be "avoidably lost": These flare events will require prior approval via Notice of Intent- Sundry Notice (Form 3160-5). Volumes flared beyond limits defined in 43 CFR 3179.7 are considered "avoidably lost" and will require payment of royalties, unless an exception is granted in accordance with 43 CFR 3179. <u>Volumes for avoidably lost gas shall be reported on OGOR "B" reports as disposition code "08"</u>.

ľ

If the operator believes that the flared volumes were "unavoidably lost" and the BLM determines them to be "avoidably lost", the operator can submit a more detailed request via Sundry Notice (Form 3160-5) for an exception in accordance with 43 CFR 3179.4, 3179.103 - 3179.105. As an alternative to producing oil and flaring gas the operator may choose to shut the well in and avoid paying royalties on otherwise avoidably lost gas.

- 3. Approval not to exceed 90 days, (from 07/29/2017 to 10/27/2017), if flaring is still required past 60 days submit new request for approval.
- 4. Submit Subsequent Report with actual volumes of gas flared for each month gas is flared on a Sundry Notice (Form 3160-5). <u>Include method for volume determination and duration</u>. <u>Report</u> <u>unavoidably lost (first 24 hrs. of unexpected event) and avoidably lost (exceeding the first 24 hrs. or flared gas that has been approved as avoidably lost by the Authorized Officer) volumes and durations on the Subsequent Report.</u>
- 5. In determining the volumes of gas to be reported, shall be in accordance with 43 CFR 3179.4, 43 CFR 3179.5, 43 CFR 3179.9 and 43 CFR 3179.10
- 6. The operator must estimate or measure all volumes of gas vented or flared gas by one of the following methods.
 - i. Measure the flare gas by a meter. The meter shall meet all requirements for a sales meter as per Federal Regulations, 43 CFR 3175. Include meter serial number on Sundry Notice (Form 3160-5).
 - ii. Calculate the volume of the flared gas based on the results of a regularly performed GOR test and measured values for the volumes of oil production and gas sales, so as to allow BLM to independently verify the volume, rate, and heating value of the gas flared.

Regulation Ref: Link to 43 CFR 3179 Waste Prevention and Resources Conservation; https://www.ecfr.gov/cgi-

bin/retrieveECFR?gp=1&SID=dbd49eda8cdc488870172ed096d47be9&ty=HTML&h=L&mc=true &n=sp43.2.3170.3179&r=SUBPART