| Submit 1 Copy To Appropriate District<br>Office       State of New Mexic         District I - (575) 393-6161       FreeD, Minerals and Natural 1         1625 N. French Dr., Hobbs, NM 88240       FreeD, Minerals and Natural 1         District II - (575) 748-1283       OIL CONSERVATION DI         811 S. First St., Artesia, NM 8840       OIL CONSERVATION DI         District III - (505) 334-6178       OIL CONSERVATION DI         1220 South St. Francis       Dioto Brazos Rd., Aztec, NM 8741 NG 2 5 201         District IV - (505) 476-3460       I220 South St. Francis         1220 S. St. Francis Dr., Santa Fe, NM       Santa Fe, NM 87500         Stop       Sundry NOTICES AND REPORTS ON WELLS         (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG B         DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUPROPOSALS.)         1. Type of Well: Oil Well S       Gas Well Other         2. Name of Operator       SOUTHWEST ROYALTIES INC         3. Address of Operator       1001 NOBLE ENERGY WAY, HOUSTON, TX 77070         4. Well Location       Unit Letter       C         Unit Letter       C       1980 feet from the       W         Section       29       Township 9S       Range  | 6. State Oil & Gas Lease No.         20708         ACK TO A         JCH         8. Well Number         003         9. OGRID Number         21355         10. Pool name or Wildcat         FLYING M SAN ANDRES  |
|---|--|
| 4355' GR  |  |
| 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data  |  |
| TEMPORARILY ABANDON       CHANGE PLANS       CO         PULL OR ALTER CASING       MULTIPLE COMPL       CA         DOWNHOLE COMMINGLE       CLOSED-LOOP SYSTEM       CO         OTHER:       OTHER       OTHER  | SUBSEQUENT REF<br>MEDIAL WORK INT TO PA R. INT |
| <ol> <li>Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date<br/>of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of<br/>proposed completion or recompletion.</li> </ol>   |  |
| 1. MIRU P&A EQUIPMENT 25<br>2. SET CIBP @ 4300' W/ 15SX ON TOP OF CIBP PRESSURE TEST CSG<br>3. PUMP 25SX @ 3720' 2500' (B.SALT)<br>4. PERF & SQZ 60 SX @ 1800' WOC'TAG<br>5. PREF @ 400' SQZ 95 SX TO SURF. VERIFY CMT. CUT OFF W.H. INSTALL<br>DRY HOLE MARKER 3' BELON GROUND LEVEL   |  |
| CLOSED LOOP SYSTEM # 10# ML.F. WILL BE USED.<br>"L.P.C." AREA - TAKE PHOTO'S OF CUT OFF & MARKER<br>RECORD G.P.S. CO-ORDINATES & SUBMIT W/SUBSEQUENT CIO3   |  |
| Spud Dute. Of 11/10/1   | Y OCD 24 HOURS PRIOR TO<br>INING PLUGGING OPERATIONS   |
| I hereby certify that the information above is true and complete to the best o  | f my knowledge and belief.   |
| SIGNATURE A SIGNATURE ANALYST II DATE 8/21/2017   |  |
| Sign Afoke       Official Control of |  |
| APPROVED BY: Mach Whith TITLE Petroleum Engr. Specialist DATE 08/29/2017  |  |
| KM.L.F. consists of 10 PPG Frim w/25 sx salfgel per 100 bbls  |  |

Company: Southwest Royalties

## WELLBORE DIAGRAM

## DATE: 8/17/17 API# 30--025-24694

